NRC FOR (5-92)	M 366				-	U.S.	NUCLE	AR I	REGULATO	RY CO	MISSION			APPROVED BY EXPI	OMB NO. RES 5/31/	3150 '95	-0104	
	LICENSEE EVENT REPORT (LER) LICENSEE EVENT REPORT (LER) ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.																	
NRCFACI	RCFACILITY NAME (1) Dresden Nuclear Power Station, Unit 3									DOCK	ET	NUMBER (2) 05000249			1 0	NGE (3) F 5		
TITLE ((ITLE (4) High Pressure Coolant Injection Low Flow Setpoint Calibration Found Outside Technical Specification Limit Due to Inattention to Detail During the Recording and Review of Previous Calibration Data																	
EVE	T DATE	(5)			L	ER NUMBER (6)	· · · · · · · · · · · · · · · · · · ·		REPOR	T DAT	TE (7)	T		OTHER FACIL	ITIES INV	OLVED) (8)	
MONTH	DAY	YE	AR	YEAR	. 9	SEQUENTIAL NUMBER	REVIS	ION ER	MONTH	DAY	YEAR	FACIL	CILITY NAME DOCKET				ET NU	1BER
02	09	9'	7	97		001	00		03	06	97	FACIL	FACILITY NAME				DOCKET NUMBER	
OPER/	TING			THIS R	EPOR	T IS SUBMITTE	D PURSL	JANT	TO THE	REQUI	REMENTS	OF 10	CFF	l§: (Check o	ne or mor	`е) (11)	
MODE (9) 1 20.2201(b)						20.2203)(i)		50.73(a)(2)(iii) 73.71(b)				b)					
PO	POWER		20.2203(a)(1)					20.2203(a)(3)(ii)			50.73(a)(2)(iv)				7	3.71(c)	
LEVEL	(10)	01	4 [20.2203(a)(2)(i)					20.2203(a)(4)			- ·	50.73(a)(2)(v) OTHE			THER		
	<u>, </u>	20		20.	2203	(a)(2)(ii)			50.36(c	•	T	50.73(a)(2)(vii) (Sp			(Spe	cify	in	
				20.	2203	(a)(2)(iii)			50.36(c)(2)				50.73(a)(2)(viii)(A)			ADST	ract I in Tex	Delow ct
			. °	20.	2203	(a)(2)(iv)	X 50.73(a)(2)(i)			50.73(a)(2)(viii)(B)			NRC	Form 3	366A) =			
				20.	2203	(a)(2)(v)		<u> </u>	50.73(a	ii)	50.73(a)(2)(x)							
				,		· · · · ·	LICENS	FF (CONTACT F	OR TH	ITS LER	(12)		•			•	
NAME													T	TELEPHONE. NUM	BER (Incl	ude	Area C	ode)
	T.La	ne	- I	MD T	cair	ning Coord	inato	br		Ext	. 2833			(81	5) 942-	-292	0	
				CO	PLET	E ONE LINE FO	REACH	CO	PONENT P	AILUR	RE DESCR	IBED I	N T	HIS REPORT (1	3)			
CAUSE	CAUSE SYSTEM COMPONENT MANUFACTURER REPOR			TABL PRDS	.E	CAUSE		SYSTEM COMPONENT		MANUFACTURER		RE	PORTABLE O NPRDS					
			,							•								
													•					
			S	UPPLEM	ENTAL	REPORT EXPE	CTED (1	4)				•	E)	PECTED	MONTH	Т	DAY	YEAR
YES (If	yes, co	omple	te E	XPECTE) SUB	MISSION DATE:).		XN	0		,	SUE DA	MISSION TE (15)			•	
BSTRACT	Limi	t to	1400	0 space	es.i	.e., approxim	ately	15 s	ingle-sp	aced	typewri	tten l	ine	s) (16)				

On February 9, 1997, during the performance of Dresden Instrument Surveillance 2300-02, High Pressure Coolant Injection Flow Calibration, the low flow switch setpoint was found outside of technical specification limits. It was determined that during the previous calibration, the low flow switch was left outside of administrative limits due to inattention to detail on the part of the technicians in the data recording and supervisors reviewing the completed data. The individuals involved in this event were disciplined in accordance with Dresden Station Policy. The safety significance of this event is minimal because the low flow switch causes the minimum flow bypass valve to open on lowering pressure to ensure adequate recirculation flow through the pump and does not effect the ability of the High Pressure Coolant Injection System from performing its safety function.

PDR

S

9703120391 970306

ADOCK 05000249

PDR

NRC FORM 366A (5-92)	U.S. NUCLEAR RE	APPROVED BY ONB NO. 3150-0104 EXPIRES 5/31/95					
	LICENSEE EVENT REPORT (LEI TEXT CONTINUATION	R)	ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BURDET WASHINGTON DC 2053.				
	FACILITY NAME (1)	DOCKET NUMBER (2)		PAGE (3)			
Dura dia Nu		05000040	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 05 5	
Dresden Nuc	iclear Power Station, Unit 3	05000249	97	001	00	5 2 OF 5	

PLANT AND SYSTEM IDENTIFICATION:

General Electric - Boiling Water Reactor - 2527 MWt rated core thermal power.

Energy Industry Identification System (EIIS) codes are identified in the text as [XX] and are obtained from IEEE Standard 805-1984, IEEE Recommendation Practice for System Identification in Nuclear Power Plants and Related Facilities.

EVENT IDENTIFICATION:

High Pressure Coolant Injection Low Flow Setpoint Calibration Found Outside Technical Specification Limit Due to Inattention to Detail During the Recording and Review of Previous Calibration Data

PLANT CONDITIONS PRIOR TO EVENT:

Unit: 3	•		Event Date:	02/09/97		Event Time:	2145
Reactor Mode:	1	, , , , , , , , , , , , , , , , , , ,	Mode Name:	Run	•	Power Level	: 074

Reactor Coolant System Pressure: 968 psig

DESCRIPTION OF EVENT:

Β.

This issue is reportable pursuant to 10CFR50.73 (a)(2)(i)(b), any operation or condition prohibited by the plant's Technical Specifications.

On February 9, 1997, during performance of Dresden Instrument Surveillance (DIS) 2300-02, High Pressure Coolant Injection [BJ] Flow Calibration, the low flow switch setpoint was found to be 2.2 inches water column (inWC), outside of technical specification (TS) limit of \geq 600 gpm (equivalent to 2.82 inWC in accordance with instrument calculation NED-I-EIC-0109). Operations and Instrument Maintenance (IM) Supervision were notified. The switch was recalibrated to within specified tolerance.

While reviewing maintenance history, it was discovered that on November 14, 1996, while performing DIS 2300-02, the low flow switch setpoint was not adjusted and the setpoint was left outside acceptable limits due to a data transposition error.

DIS 2300-02 directs the technician to obtain as-found data as follows:

Raise pressure until the low flow switch resets and record the value.
Raise pressure until the high flow switch trips and record the value
Lower pressure until the high flow switch resets and record the value.
Lower pressure until the low flow switch trips and record the value.

NRC FORM 366A (5-92)	U.S. NUCLEAR RE	APPROVED BY ONB NO. 3150-0104 EXPIRES 5/31/95					
LICENSEE EVENT RI TEXT CONTIN	EPORT (LEF NUATION	٤)	ESTIMAT THIS I FORWARD THE IN (MNBB 7 WASHING REDUCTI MANAGEM	TED BURDEN PER NFORMATION COLLE D COMMENTS REGA FORMATION AND F 7714), U.S. NUCLI STON, DC 20555-0 ION PROJECT IENT AND BUDGET,	RESPONSE ECTION REON RDING BURD RECORDS MAI EAR REGULAT 001, AND T (3150-0104) WASHINGTON	TO COMPLY WITH JEST: 50.0 HRS. EN ESTIMATE TO NAGEMENT BRANCH ORY COMMISSION, 0 THE PAPERWORK 0, OFFICE OF 1, DC 20503.	
FACILITY NAME (1)		DOCKET NUMBER (2)		LER NUMBER (6))	PAGE (3)	
Duesder Nusleen Deven Station	05000240	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 07 5		
Dresden Nuclear Power Station,	UNIC 3	05000249	97	001	00	3 OF 5	

On November 14, 1996, the technician inadvertently recorded the low flow switch reset value as the low flow trip as-found value and the low flow switch trip setpoint value as the as-found reset value. The high flow switch values were recorded correctly. This error was not discovered because the as-found reset point was within the tolerance specified for the setpoint.

Although the setpoint appeared (the reset point was within the setpoint tolerance) to be within tolerance, the recorded reset value (actually the trip setpoint) was significantly lower than setpoint which is inconsistent with the expected relationship between trip setpoint and reset point for a decreasing trip setpoint. This was not identified by the technicians during data recording or review nor by the supervisory review conducted by the Unit Supervisor and the IMD Supervisor.

During interviews, the individuals involved indicated that they were aware of their responsibilities concerning independent data review and verification.

In addition, although upgraded technical specifications had not been implemented (implementation date was January 1997) when DIS 2300-02 had been performed on November 14, 1996, the procedure identified a TS limit of ≥ 2.82 inWC. The asfound low flow trip value (recorded as the reset value) was below this limit, and although it is not reportable, a Process Improvement Form (PIF) was initiated for the out of tolerance condition.

An informal review of the performance history of this switch and instrument calculation NED-I-EIC-0109, High Pressure Coolant Injection (HPCI) Pump Discharge Flow Loop Accuracy and Minimum Flow Setpoints, indicate that the switch performance, a shift of 0.4 inWC over the three month period, is as expected.

CAUSE OF EVENT:

The root cause of this event is attributed to cognitive personnel error (NRC Cause Code A). Based on a barrier analysis, it was determined that inadequate attention to detail on the part of the IM technicians and reviewers resulted in the incorrect logging of the as-found data for the low flow switch setpoint and reset point on 11/14/96. Contributing to this is the failure to self check.

D. SAFETY ANALYSIS:

The impact of having the HPCI low flow switch setpoint set too low is the possibility of running the HPCI pump without the required minimum flow of 600 gallons per minute (GPM) when manually reducing flow following an automatic or manual initiation of HPCI. The ability of the system to perform its safety function during an accident would not have been affected. The system would have operated as designed, providing 5600 GPM to the reactor vessel, and the pump's minimum flow requirements would have been satisfied during this system initiation since the high flow switch was set as required.

NRC FORM 366A (5-92)		U.S. NUCLEAR RE	GULATORY CONNISSION	APPROVED BY ONB NO. 3150-0104 EXPIRES 5/31/95					
	LICENSEE EVENT TEXT CONT	REPORT (LEE	ESTIMAT THIS I FORWARD THE IN (MNBB 7 WASHIND REDUCTI MANAGEN	ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET. WASHINGTON. DC 20503.					
	FACILITY NAME (1)		DOCKET NUMBER (2)	LER NUMBER (6) PAGE (3)					
Ducadan Nu	-icen Douor Statio		05000240	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Dresden Nuc	clear rower Station	n, Unit 3	05000249	97 [.]	001	00	4 OF 5		

If the HPCI system were operated to control reactor vessel level or pressure in accordance with DOP 2300-03, High Pressure Coolant Injection System Manual Startup and Operation, flow to the reactor could have been reduced below the pump's minimum flow requirements. With the low flow switch setpoint set too low, the pump's minimum flow requirements would not have been satisfied during this condition and the potential would have existed for pump overheating and possible pump degradation.

During the time period that the low flow switch setpoint was set too low, the Unit 3 HPCI system was not operated in any mode that would have resulted in not meeting the pump's minimum flow requirements. The system was operated for a normal surveillance in accordance with DOS 2300-03, High Pressure Coolant System Operability Verification, during which the high flow switch was operationally checked as satisfactory as required by Tech Specs.

CORRECTIVE ACTIONS:

E.

1.

2.

6.

- Surveillance performed on 02/09/97 restored low flow switch setpoint to the appropriate setting. (Complete)
- IM personnel involved in this event were disciplined in accordance with Station Policy #60. (Complete)
- 3. Other work performed by the same crew over an approximate three month period, as well as previous performances of the same surveillance, were inspected for discrepancies and found acceptable. (Complete)
- Data recording practices for IMD personnel have been changed to require two independent data recorders and a separate subsequent review. (Complete)
- 5. This event and the previous similar event will be reviewed by the Department Head with all IM department management and technical personnel to reinforce expectations regarding surveillance performance and review. (NTS #237-225-97R12-97018)
 - IM Department will review a representative sample of Tech Spec procedures performed between 11/14/96 and 02/14/97 and determine if discrepancies exist. (NTS 249-180-97-001.01)

NRC FORM 366A (5-92)	U.S. NUCLEAR RE	APPROVED BY ONB NO. 3150-0104 EXPIRES 5/31/95					
	LICENSEE EVENT REPORT (LEF TEXT CONTINUATION	ESTIMAT THIS I FORWARD THE IN (MNBB 7 WASHING REDUCTI MANAGEN	ESTIMATED BURDEN PER RESPONSE TO COMPLY W THIS INFORMATION COLLECTION REQUEST: 50.0 HI FORWARD COMMENTS REGARDING BURDEN ESTIMATE THE INFORMATION AND RECORDS MANAGEMENT BRAI (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSI WASHINGTON, DC 20555-0001, AND TO THE PAPERW REDUCTION PROJECT (3150-0104), OFFICE MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.				
	FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)	>	PAGE (3)	
Dasadan Nu	-lear Dever Station Unit 2			SEQUENTIAL NUMBER	REVISION NUMBER	5 OF 5	
Dresden Nu	crear Power Scation, Unit 3	05000249	97	001	00	,	

PRIOR SIMILAR OCCURRENCES:

LER/Docket Number

97-002/05000237

F.

Turbine First Stage Pressure Scram Bypass Switches Adjusted Outside Technical Specification Limits Due to Personnel Error.

Corrective actions included restoring setpoints to correct settings, discipline of maintenance personnel involved, review of additional work performance, and reinforcement of expectations to department. The date of discovery of the 97-002 LER was after the date of occurrence of the HPCI event reported in this LER. This means that the corrective actions reported in 97-002 occurred after the HPCI event, and could not have been effective, at the time, in preventing its occurrence.

COMPONENT FAILURE DATA:

Not applicable.