

Tennessee Valley Authority, Post Office Box 2000, Decatur, Alabama 35609-2000

July 7, 2017

10 CFR 50.73

ATTN: Document Control Desk U.S. Nuclear Regulatory Commission Washington, D.C. 20555-0001

> Browns Ferry Nuclear Plant, Unit 2 Renewed Facility Operating License No. DPR-52 NRC Docket No. 50-260

Subject: Licensee Event Report 50-260/2017-004-00

The enclosed Licensee Event Report provides details of the inoperability of four Main Steam Relief Valves for longer than allowed by plant Technical Specifications. The Tennessee Valley Authority is submitting this report in accordance with Title 10 of the Code of Federal Regulations 50.73(a)(2)(i)(B), as any operation or condition which was prohibited by the plant's Technical Specifications.

There are no new regulatory commitments contained in this letter. Should you have any questions concerning this submittal, please contact J. L. Paul, Nuclear Site Licensing Manager, at (256) 729-2636.

Respectfully, M. Bono Site Vice President

Enclosure: Licensee Event Report 50-260/2017-004-00 – Main Steam Relief Valves Lift Settings Outside of Technical Specifications Required Setpoints

cc (w/ Enclosure):

NRC Regional Administrator - Region II NRC Senior Resident Inspector - Browns Ferry Nuclear Plant

ENCLOSURE

Browns Ferry Nuclear Plant Unit 2

Licensee Event Report 50-260/2017-004-00

Main Steam Relief Valves Lift Settings Outside of Technical Specifications Required Setpoints

See Enclosed

NRC FORM 366		U.S. NU ⁽	CLEAR REG	ULATOR	Y COMM	ISSION	APPROV	VED BY OMB: NO. 3150-0104 EXPIRES: 03/31/2020					S: 03/31/2020		
(04-2017)	na la	LICE	INSEE	EVENT F	REPOR	T (LER	٤)	Estimated Reported II Send comm Nuclear R Resource@ NEOB-1020 used to im the NRC n collection.	burden essons ments n egulator (nrc.gov, (315) npose an nay not	per response learned are ind egarding burder y Commission, and to the 0-0104), Office n information cc conduct or spor	to comply with corporated into the n estimate to the Washington, DC Desk Officer, Ot of Management an ollection does not nsor, and a person	this mandatory licensing proc Information Se 20555-0001, ffice of Inform d Budget, Was display a curre is not required	collection re ress and fed prvices Brancl or by e-ma lation and F hington, DC ntly valid OM d to respond	aquest: 80 hours. back to industry. n (T-2 F43), U.S. kegulatory Affairs, 20503. If a means IB control number, to, the information	
1. FACIL	ITY NA	ME						2. DOCKI	ET NU	MBER		3. PAGE	. PAGE		
Brown	is Fer	ry Nucle	er Pla	nt, Unit 2				05000	260				1 OF	7	
4 TITLE Main	Stean	n Relief	Valve	s Lift Sett	ings Oı	utside d	of Tec	hnical S	Speci	ifications	Required	Setpoint	5		
5. E	VENT C	ATE	6.	LER NUMBE	R	7. RE	EPORT [DATE			8. OTHER FA	CILITIES IN	VOLVED		
MONITH	DAV	VEAD	VEAD	SEQUENTIAL	REV	MONTH	DAV	VEAD	FACI	ILITY NAME			DOCKET NUMBER		
MONTH	DAT	TEAK	TEAR	NUMBER	NO.	MONTH	DAY	YEAR	N/A	4			N/A		
05	08	2017	2017	004	00	07	07	2017	FACI	ILITY NAME			DOCKET	NUMBER	
03	00	2017	2017	- 004	- 00	07		2017	N/A	۹			N/A		
9. OP	ERATING	MODE		11. THIS	REPORT	IS SUBM	TTED PU	RSUANT T	O THE	REQUIREM	ENTS OF 10 CF	R§: (Check	all that app	ly)	
			20.2201(b) 20.2203(a)(3)			(a)(3)(i)		☐ 50.73(a)(2)(ii)(A)			50.	73(a)(2)(vi	ii)(A)		
	1		20.2201(d)			20.2203(a)(3)(ii)			50.73(a)(2)(ii)(B)		50.	73(a)(2)(vi	ii)(B)		
			20.2203(a)(1)			20.2203(a)(4)			☐ 50.73(a)(2)(iii)		50.	73(a)(2)(ix)(A)		
			20.	2203(a)(2)(i)		50.36(c)			50.73(a)(2)(iv	v)(A)	50.	73(a)(2)(x))		
10. F	OWER L	EVEL	20.	2203(a)(2)(ii)		50.36(c))(1)(ii)(A)			50.73(a)(2)(v	r)(A)	73.	71(a)(4)		
			20.	2203(a)(2)(iii)	, []	50.36(c))(2)	<u></u>		50.73(a)(2)(v	/)(B)	☐ 73.71(a)(5)			
	100		20.	2203(a)(2)(iv)) []	50.46(a))(3)(ii)			50.73(a)(2)(v	/)(C)	73.77(a)(1)			
			20.	2203(a)(2)(v)		50.73(a))(2)(i)(A)			□ 50.73(a)(2)(v)(D) □ 73.77(a			77(a)(2)(i)		
			20.	2203(a)(2)(vi)) 🛛	50.73(a))(2)(i)(B)	+		50.73(a)(2)(v	rii)	73.	77(a)(2)(ii)		
						50.73(a))(2)(i)(C)			OTHER s	pecify in Abstract be	low or in NRC F	orm 366A		
					12	LICENS	SEE COI	NTACT FC	R TH	IS LER					
	ONTACT		.								TELEPHO		nclude Area C	ode)	
Ryan C	oons, I	Licensing	<u>g Engin</u>	ieer							256-72	29-2070			
			13	3. COMPLETE	.ONE LINE MANU-	FOR EAC	COMP TABLE	ONENT FA	ULURE	DESCRIBED	D IN THIS REPO	RT MANU-	R	FPORTABLE	
CAU	SE	SYSTEM		PONENT FA	CTURER	TO E	EPIX	CAUS	E	SYSTEM	COMPONENT	FACTURE	R	TO EPIX	
В	,	SB	F	ר אא	Т020	<u> </u>	(N/A	۸	N/A	N/A	N/A		N/A	
14. SUPP	LEMEN	ITAL REPO	ORT EXF	PECTED						15. EX	PECTED	MONTH	DAY	YEAR	
	ES (If ye	s, complet	e 15. EXF	PECTED SUE	3MISSION	DATE)		NO 🛛		SUBIN D	ATE	N/A	N/A	N/A	
ABSTRAC	г (Limit to у 8, 20	1400 space)17, the	s, i.e., appi Tenne	roximately 15 sil ssee Valle	ngle-spaced ey Auth	d typewritter ority wa	n lines) as pre:	sented v	vith a	as-found f	testing resu	Its indica	ting that	t four of the	

On May 8, 2017, the Tennessee Valley Authority was presented with as-found testing results indicating that four of the thirteen Main Steam Relief Valves (MSRVs) from Browns Ferry Nuclear Plant, Unit 2, were outside the +/- 3 percent setpoint band required for their operability. Troubleshooting determined that three MSRVs exceeded their setpoints when their valve discs failed by corrosion bonding to their valve seats. The valve discs were previously platinum coated to prevent this, but the valve seat's rough Stellite surface caused the coating to delaminate. This was the first Unit 2 MSRV service interval to implement the improved surface treatment since a resolution to the delamination issue was identified in 2015. The valve which failed below its setpoint band was determined to have a faulty pilot spring.

These four MSRVs were found to have been inoperable for an indeterminate period of time between April 9, 2015, and February 25, 2017, and longer than permitted by Technical Specifications. The affected valves remained capable of maintaining reactor pressure within American Society of Mechanical Engineers code limits. Additionally, the valves' ability to open under remote-manual operation, activation through the Automatic Depressurization System, or MSRV Automatic Actuation Logics were not affected. The valves remained capable of performing their required safety function.

Corrective Actions were to replace all thirteen Unit 2 MSRV pilot valves with pilot valves which had the platinum coating applied in accordance with the revised procedure, and to analyze the pilot valves of the inoperable MSRVs. The pilot spring was replaced inside the valve which failed below its specification.

NRC FORM 366A	U.S. NUCLEAR REGULA	APPROVED BY OMB: NO. 3150-0104 EXPIRES: 3/31/2020					
LICENSEE EVENT REPORT (LER) CONTINUATION SHEET		Estimated burden per response to comply with this mandatory collection requises on hom- lessons learned are incorporated into the licensing process and fed back to indi- comments regarding burden estimate to the Information Services Branch (T-2 F43), U. Regulatory Commission, Washington, DC 20555-0001, or by e Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regula NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. used to impose an information collection does not display a currently valid OMB control to NRC may not conduct or sponsor, and a person is not required to respond to, the collection.					
1. FACILITY NAN	16	2. DOCKET N	UMBER		3. LER NUMBER		
				YEAR	SEQUENTIAL NUMBER	REV NO.	
Browns Ferry Nuclear Plant, Unit 2 05000-260				2017	- 004	- 00	

Ι. Plant Operating Conditions Before the Event

At the time of discovery, Browns Ferry Nuclear Plant (BFN), Unit 2, was in Mode 1 at 100 percent power.

П. **Description of Event**

A. Event Summarv

On May 8, 2017, National Technical Systems (NTS) Laboratories provided Tennessee Valley Authority (TVA) with the as-found testing results of the thirteen Main Steam [SB] Relief Valves (MSRVs) [RV] which were removed during the Spring 2017 Unit 2 Refueling Outage 19 (U2R19). Four of the Main Steam Line B, C, and D Relief Valves (BFN-2-PCV-001-0022, BFN-2-PCV-001-0023, BFN-2-PCV-001-0030, and BFN-2-PCV-001-0041) had as-found lift settings which were outside of the +/- 3 percent band of their setpoints required for their operability.

Technical Specification (TS) 3.4.3 requires twelve of the thirteen Safety/Relief Valves (S/RVs) to be operable for S/RV system operability. These four MSRVs were found to have been inoperable for an indeterminate period of time between April 9, 2015, and February 25, 2017, and longer than permitted by TS 3.4.3.

MSRV operability was restored on April 1, 2017, upon completion of post-maintenance testing (PMT) following the biennial scheduled replacement of the MSRV pilot valves with refurbished valves which were certified to lift within +/- 1 percent of their setpoints.

Throughout this event, the two-stage MSRV pilot valves remained capable of maintaining the reactor pressure below 1375 psig, which is the American Society of Mechanical Engineers (ASME) code limit of 110 percent of the vessel design pressure. The valves remained capable of performing their required safety function.

B. Status of structures, components, or systems that were inoperable at the start of the event and that contributed to the event

There were no structures, systems, or components (SSCs) whose inoperability contributed to this event.

NRC FORM 366A U.S. NUCLEAR REGULA	1366A U.S. NUCLEAR REGULATORY COMMISSION			APPROVED BY OMB: NO. 3150-0104 EXPIRES: 3/31/2020				
	Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.							
1. FACILITY NAME	2. DOCKET N	UMBER		3. LER NUMBER				
			YEAR	SEQUENTIAL NUMBER	REV NO.			
Browns Ferry Nuclear Plant, Unit 2	05000-260		2017	- 004	- 00			
C. Dates and approximate tir	nes of occurren	ICes						
<u>Dates & Approximate Tin</u> April 9, 2015 February 25, 2017 April 1, 2017	<u>rence</u> entered Mode 2, beginning the cycle. Unit 2, entered Mode 4, beginning the U2R19. cement of MSRV pilot valves and their iated PMT is completed, as part of the U2R19.							
May 8, 2017	S Laboratories provided TVA with the as-found ting results of the thirteen Unit 2 MSRV pilot ves removed during the U2R19.							
D. Manufacturer and model r	component that failed d	luring the	event					
The failed components were model number 7567F.	e all Target Rock	Corporation two-stage pr	ressure co	ontrol valves,				

E. Other systems or secondary functions affected

No other systems or secondary functions were affected by this event.

F. Method of discovery of each component or system failure or procedural error

Failure was discovered at NTS Laboratories, during their as-found testing of the thirteen MSRV two-stage pilot valves which were removed during the U2R19.

G. The failure mode, mechanism, and effect of each failed component

Three of the four two-stage pilot valves failed due to the corrosion bonding of the valve disc to the valve seat. The remaining pilot valve failed to meet its setpoint band requirements due to a weak spring.

H. Operator actions

There were no operator actions associated with this event.

I. Automatically and manually initiated safety system responses

There were no automatic or manual safety system responses associated with this event.

U.S. NUCLEAR REGULATORY COMMISSION U.S. NUCLEAR REGULATORY COMMISSION U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT (LER) CONTINUATION SHEET			APPROVED BY OMB: NO. 3150-0104 EXPIRES: 3/31/2020 Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.					
1. FACILITY NAME 2. DOCKET N		UMBER	3. LER NUMBER					
				YEAR	SEQUENTIAL NUMBER	REV NO.		
Browns Ferry Nuclear Plant, Unit 2 05000-260				2017	- 004	- 00		
III. Cause A. Ca Th	e of the event use of each component	t or system failu	ire or personnel error	their valve	a discs corrosi	ion		

Three two-stage pilot valves failed above their setpoint bands due to their valve discs corrosion bonding to the valve seat, which is apparently caused by a valve disc surface finish that does not make allowance for corrosion bonding.

One two-stage pilot valve failed below its setpoint band due to a faulty valve spring.

B. Cause(s) and circumstances for each human performance related root cause

No human performance related root causes were identified.

IV. Analysis of the event

The TVA is submitting this report in accordance with Title 10 of the Code of Federal Regulations 50.73(a)(2)(i)(B), as any operation or condition which was prohibited by the plant's TS. It was determined that the MSRV pilot valve inoperability resulted from their setpoints gradually drifting during the course of their operating cycle, which began when Unit 2 entered Mode 2 on April 9, 2015, and lasted until February 25, 2017, when Unit 2 entered Mode 3.

BFN, Unit 2, TS Limiting Condition for Operation (LCO) 3.4.3 requires twelve Operable S/RVs during Modes 1, 2, and 3. If one or more required S/RVs becomes inoperable, Required Action A.1 requires BFN, Unit 2, to enter Mode 3 within 12 hours, and Required Action A.2 requires entering Mode 4 within 36 hours. S/RV Operability is defined as being within a +/- 3 percent band of their setpoint values, in accordance with Surveillance Requirement 3.4.3.1. BFN, Unit 2, has thirteen MSRVs to satisfy this requirement with margin.

After the installation of the S/RVs, the as-left lift setpoint for S/RVs BFN-2-PCV-001-0022 and BFN-2-PCV-001-0030 was 1145 psig, S/RV BFN-2-PCV-001-0023 was 1135 psig, and SR/V BFN-2-PCV-001-0041 was 1155 psig. However, during as-found testing at NTS Laboratories, the Main Steam Line B Relief Valve, BFN-2-PCV-001-0022, lifted at 1179.5 psig (+3.01 percent); the Main Steam Line C Relief Valves, BFN-2-PCV-001-0023 and BFN-2-PCV-001-0030, lifted at 1183 psig (+4.22 percent) and 1105 psig (-5.76 percent), respectively; and the Main Steam Line D Relief Valve, BFN-2-PCV-001-0041, lifted at 1198 psig (+3.72 percent). During the fuel cycle, these valve lift setpoints gradually drifted outside of the +/- 3 percent margin which is required for their operability. The valves which exceeded their setpoint bands failed due to corrosion bonding between the valve discs and their seats. The valve which failed below its setpoint band was determined to have a faulty pilot spring. These valve failures occurred after their installation but before Unit 2 entered Mode 4 on February 25, 2017. Therefore, BFN, Unit 2, operated with inoperable S/RVs for longer than allowed by TS.

NRC FORM 366A U.S. NUCLEA	R REGULA	TORY COMMISSION	APPROVED BY OMB: NO. 3150-010	4	EXPIRES:	3/31/2020				
	LICENSEE EVENT REPORT (LER) CONTINUATION SHEET				APPROVED BY OMB: NO. 3150-0104 EXPIRES: 3/31/2020 Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@ncc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information					
1. FACILITY NAME		2. DOCKET N	UMBER		3. LER NUMBER					
Browns Forny Nuclear Blant J	Init 2	05000 260		YEAR	SEQUENTIAL NUMBER	REV NO.				
Browns Ferry Nuclear Flam, C	JIII Z	05000-200		2017	- 004	- 00				
 Operating Experience (uniform, linear process. gradually lost its tension estimating the setpoint percent limit cannot be fuel cycle on April 9, 20 inoperability was conse time between April 9, 20 V. Assessment of Safety 	OE) has The con over it drift dev reliably 15, and rvatively 015, and	s shown that Targ rrosion bonding i s lifetime. Withou velopment, the po determined. Sind February 25, 20 y declared to hav d February 25, 20 quences	get Rock two-stage MSR\ ncreases at a random rat at an accurate and reliable bint in time where the setp ce this drift occurred betwo 17, when Unit 2 entered N re been inoperable for an 017, and longer than perm	/ setpoint e, and the e model fo ooint exce een the b Mode 3, th indeterminitted by p	t drift is not a e faulty pilot s or predicting o eeded the +/- 3 eginning of th ne MSRV inate period of plant TS 3.4.3	pring ir 3 e f				
System availability was System (ADS) valves, E setpoint identified in TS ADS or MSRV Automat electrical signal to ener TS Bases 3.4.3 states t pressurization transient 1375 psig, which is the remained capable of pe The bounding maximum the requirements of the performed specifically t the vessel pressure doo Without Scram (ATWS) psig peak vessel press	not imp 3FN-2-F 3.4.3 d tic Actua gize the that the ASME of ASME o show es not en pressu ure limit	pacted by this even PCV-001-0022 ar loes not impact it ation Logics since MSRV control a overpressure pro SRVs remained code limit (110 per g their required s pressurization analyses that the dome pro xceed the limit of rization analyses is not exceeded.	ent. The failure of the Auto ad BFN-2-PCV-001-0030, s remote-manual operation e these operating modes a ir solenoid which electrican otection system must accor capable of maintaining the ercent of the vessel desig afety function. alyses are performed eac overpressure protection ar essure TS limit of 1325 per 1375 psig. In addition, the are also performed to de	omatic De to meet f on, or acti and funct ally opens ommodate e reactor n pressur h fuel cyc re met. Th sig is not sig is not ne Anticipa monstrat	epressurization the mechanica vation through ions rely upon the pilot valve the most sev pressure belo re). The valves the analyses and exceeded and ated Transien e that the 150	n al n the i an e. vere ww s at re d that t 0				
NUREG-0800 defines to Service Level C limits, v (BWRs). For the ATWS found MSRV opening s the valve groupings. Th pressure regulator faile exposure, was re-analy	bases th which ar analysi etpoints herefore d open a zed by	e acceptance cri re approximately is, the setpoint gr ; however, the th , the limiting ATV at 100% rated po AREVA. The rest	teria for reactor coolant p 10.3 MPa (1500 psig) for oupings conservatively b tree highest valve setpoin VS overpressurization even wer and 81% rated flow a ults from this analysis indi	ressure o Boiling V ound the ts fall out ent, identi at the beg cates tha	n the ASME Vater Reactors ten lowest as- side the boun fied as the AT jinning of cycle it despite that	s - ds of WS e four				

MSRV pilot valves were outside their as-found setpoint band, the maximum vessel pressure and maximum dome pressure reaches a maximum of 1398 psig, and therefore does not exceed the ATWS vessel pressure limit of 1500 psig. Therefore, there was no impact on the MSRVs to perform their specified safety function.

NRC FORM 36	6A U.S. NUCLEAR REGULA	TORY COMMISSION	APPROVED BY OMB: NO. 3150-010)4	EXPIRES:	3/31/2020
	LICENSEE EVENT RI	Estimated burden per response to comply with this mandatory collection request: 80 hours. lessons learned are incorporated into the licensing process and fed back to indus comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Regulatory Commission, Washington, DC 20555-0001, or by e-r Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulato NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If used to impose an information collection does not display a currently valid OMB control nu NRC may not conduct or sponsor, and a person is not required to respond to, the in collection.				
1. FACILITY N	IAME	2. DOCKET N	UMBER		3. LER NUMBER	1
	m. Nuclear Direct Linit 2	05000.000		YEAR	SEQUENTIAL NUMBER	REV NO.
Browns Fe	erry Nuclear Plant, Unit 2	05000-260		2017	- 004	- 00
requ A. 4 B. 1 C. 1	aired safety functions neede Availability of systems or the components and syst Each BFN operating unit ha Logic) installed, which provi- opening MSRV groups base during a reactor pressure tr 1145 psig group MSRVs, ar open signal, providing a def function. For events that occurred components needed to sh remove residual heat, cor consequences of an accid This event did not occur wh For failure that rendered a time from discovery of the TS 3.4.3 requires twelve of	ed to protect the l components th ems that failed as a non-safety re- ides defense-in- ed upon setpoints ansient event, th nd finally the five fense-in-depth fu when the reactor nutdown the reactor nutdown the reactor furble the release dent en the reactor was a train of a safet e failure until th	nealth and safety of the pro- at could have performed during the event elated, electrical logic syst lepth against MSRV setpo s at 1135 psig, 1145 psig, e four 1135 psig group MSRVs nction to allow the valves or was shut down, availand ctor and maintain safe so of radioactive material, as shutdown. y system inoperable, ess e train was returned to so /s to be operable for S/RV	ublic. d the sam tem (MSR bint drift by and 1155 SRVs, follow would rec to perform bility of s shutdown or mitiga	v Actuation y electrically psig. Therefore owed by the f eive an electron their safety systems or a conditions, ate the the elapsed	s ore, our ical
1	fuel cycle, from April 9, 201	5, to February 25	5, 2017.			
VI. Cor	rective Actions					
Corr (CR	rective Actions are being ma s) 962223 and 1294336.	anaged by TVA's	corrective action program	n under Co	ondition Repo	orts
A. I	mmediate Corrective Act	ions				
	All thirteen of the Unit 2 MS U2R19. These valves had p As-left testing verified that t plate setpoints.	RV pilot valves v blatinum coatings hese refurbished	vere replaced with refurbis applied in accordance wi pilot valves were within +	shed valve ith the rev -/- 1 perce	es during the ised procedu ent of their nai	re. me

NRC FORM 366A U.S. NUCLEAR REGULA	TORY COMMISSION	APPROVED BY OMB: NO. 3150-010	4	EXPIRES:	3/31/2020		
	EXPIRES: 375 1/2020 Estimated burden per response to comply with this mandatory collection request. 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection						
1. FACILITY NAME	2. DOCKET N	UMBER		3. LER NUMBER			
			YEAR	SEQUENTIAL	REV		
Browns Ferry Nuclear Plant, Unit 2	05000-260		2017	- 004	- 00		
 B. Corrective Actions to Preoccurring in the future Steps were added to the Mainspection, Rework and Remean Square (RMS) optical better, optimally 16 RMS, p The pilot spring was replace VII. Previous Similar Events at the A search of BFN LERs for Unitanine years. A search of the Corrective Action failure events since 1999. These 81376, 102298, 124944, 14618 1157981, 1237184, and 12943 addressed by CR 112190. CR 55557 identified that corross strong enough to cause signific corrective action, a design charsed witch logic that was endorsed CR 56793 identifies the corrosi S/RVs presented a fundamental sectors. 	vent Recurrence ain Steam Relief assembly proceed al comparator to verior to platinum of rior to platinum of ed inside the valve as 1, 2, and 3, ide on Program for B as failures were of 39, 175990, 1592 36. These individ sion bonding betwe cant drifts in their nge was implement by the BWR Ow ion-prone materia al design deficier	e or to reduce the proba Valves Target Rock Mode lure, to use a borescope, verify that the pilot disc fini- toating. we which failed below its s ntified nine LERs for this s FN, Units 1, 2, and 3, ider aptured by CRs 37328, 5 200, 226627, 294506, 372 ual failures were collective veen the valve discs and to opening pressure and resented to update/install a se ners Group to resolve set als used in the construction recy. An alternate MSRV de	bility of s el 7567 D microscop ish quality pecificatio same issu ntified eig 9786, 500 047, 5584 ely evalua cheir seat set setpoi afety relat point drift n of Targ esign/logi	similar events isassembly, pe and a Root (is 32 RMS o on. ue within the la hteen MSRV 084, 61823, 488, 962223, ated and surfaces were issues. et Rock two-s c/manufacture	s r ast tage er		
The Corrective Actions for CR	146189 required	platinum coated MSRV di	scs to be	installed in fu	iture		
VIII. Additional Information	I. Additional Information						

There is no additional information.

IX. Commitments

There are no new commitments.