NRC FOR (07-2012) 10 CFR 2.201	M 591M PA	SAFETY INSPECTION	REPORT AN		CLEAR REGULATORY	COMMISSION		
1. LICENSE	EE/LOCATIC	DN INSPECTED:	2. NRC/REGIONAL OFFICE					
Lansing	orth Walr , MI 489		Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352					
3. DOCKET NUMBER(S)			4. LICENSE NUMBER	R(S)	5. DATE(S) OF INSPECT	ION		
030-389	88		21-35144-03		JUNE 20	4, 2017		
Regulator	<ul> <li>the inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear egulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of occurres and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:</li> <li>1. Based on the inspection findings, no violations were identified.</li> <li>2. Previous violation(s) closed.</li> </ul>							
						£		
4.	cited in a with 10 C	s inspection, certain of your activities, coordance with NRC Enforcement Poli FR 19.11. s and Corrective Actions)						
corrective	actions is r	Sta ithin 30 days, the actions described by nade in accordance with the requirem ance will be achieved). I understand t	ents of 10 CFR 2.201	will be taken to correct the viola I (corrective steps already taken	, corrective steps which	n will be taken,		
	TLE	PRINTED NAME		SIGNATURE	· · · · · · · · · · · · · · · · · · ·	DATE		
LICENSEE REPRESE				· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · ·			
NRC INSP		Ryan Craffey		Ry Captre	7	420/17		
BRANCH	CHIEF	Aaron McCraw		ATMI	2	07/06/2017		
NRC FORM	591M PART	1 (07-2012)		0				

U.S. NUCLEAR REGULATORY COMMISSION										
Docket File Information Docket File Information SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION										
1. LICENSEE/LOCATION INSPECTE	ED:		2. NRC/REGIONAL OFFICE							
Niowave, Inc. 1012 North Walnut Street Lansing, MI 48906			Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352							
REPORT NUMBER(S) 201700	01									
3. DOCKET NUMBER(S)		4. LICENSE NUMBER(S)		5. DATE(S) OF INSPECTION						
030-38988		21-35144-03	5144-03 June 20, 2017							
6. INSPECTION PROCEDURES USE 87121	ED	7. INSPECTION FOCUS AREAS All								
SUPPLEMENTAL INSPECTION INFORMATION										
1. PROGRAM CODE(S)	2. PRIORITY	3. LICENSEE CONTAC		4. TELEPHONE NUMBER						
03320	1	William Reeve -	RSO	(517) 599-1715						
✓ Main Office Inspection       Next Inspection Date: 06/20/2018         ✓ Field Office Inspection       2050 Port Lansing Road, Lansing, MI         Temporary Job Site Inspection										
This was an announced initial inspection of the newly-formed NDT division at a superconducting linear accelerator manufacturer, authorized by an NRC materials license issued on February 10, 2017 to use radioactive material for industrial radiography at a field station in Lansing, Michigan, and at temporary job sites in NRC jurisdiction. At the time of the inspection, the licensee's NDT staff (the RSO and five carded radiographers) were based at the main office on North Walnut Street in Lansing, although plans were in place to move the staff to an office at the field station on Port Lansing Road in the near future. The licensee had conducted radiographic operations on two occasions to date. PERFORMANCE OBSERVATIONS The inspector visited the Walnut Street facility to evaluate the licensee's initial implementation of its radiation safety program for industrial radiography. The inspector reviewed initial training materials, semiannual performance audits and										
dosimetry reports for all five radiographers, as well as complete records of equipment maintenance and instrument calibrations. The inspector discussed with the licensee its plans for performing and tracking the completion of refresher training, program audits, and other periodic requirements. Through these reviews and discussions, the inspector found the licensee's staff to be knowledgeable of regulatory requirements for industrial radiography.										
The inspector toured the field station on Port Lansing Road to evaluate the licensee's measures for hazard communication, exposure control, and transportation of radioactive materials. The licensee demonstrated the conduct of radiography in the on-site accelerator vault (which the crew treated as a temporary job site), including equipment checks, barrier setup and control, and survey meter use. The inspector performed independent and confirmatory surveys during this demonstration and found no evidence of exposure to members of the public outside of the licensee's established boundary. The inspector reviewed utilization logs and shipping papers completed to date, and discussed aspects of the licensee's operating and emergency procedures with the crew. Through these observations and discussions, the inspector found the licensee's staff to be knowledgeable of radiation protection requirements.										
The frequencies of three requirements were fuctuation us a result of this inspection.										