

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS MANDATORY INFORMATION COLLECTION REQUEST: 50.0 HRS. REPORTED LESSONS LEARNED ARE INCORPORATED INTO THE LICENSING PROCESS AND FED BACK TO INDUSTRY. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (T-8 F33), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)
Dresden Nuclear Power Station, Unit 3

DOCKET NUMBER (2)
05000249

PAGE (3)
1 of 5

Unit 3 Manual Scram Due to Decreasing Condenser Vacuum Caused By A Stuck Open Turbine Crossaround Relief Valve

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
05	16	98	98	004	00	06	15	98	N/A	N/A
									N/A	N/A

OPERATING MODE (9)	POWER LEVEL (10)	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more) (11)								
1	035	20.2201(b)	20.2203(a)(2)(v)	50.73(a)(2)(i)	50.73(a)(2)(viii)					
		20.2203(a)(2)(i)	20.2203(a)(3)(i)	50.73(a)(2)(ii)	50.73(a)(2)(x)					
		20.405(a)(1)(ii)	20.2203(a)(3)(ii)	50.73(a)(2)(iii)	73.71					
		20.2203(a)(2)(ii)	20.2203(a)(4)	X	50.73(a)(2)(iv)					OTHER
		20.2203(a)(2)(iii)	50.36(c)(1)		50.73(a)(2)(v)					Specify in Abstract below or in NRC Form 368A
		20.2203(a)(2)(iv)	50.36(c)(2)		50.73(a)(2)(vii)					

LICENSEE CONTACT FOR THIS LER (12)

NAME: **R. Jackson, Electrical Maintenance** TELEPHONE NUMBER (Include Area Code): **(815) 942-2920 ext 2483**

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
X	SB	RV	C710	Y					

SUPPLEMENTAL REPORT EXPECTED (14)

SUPPLEMENTAL REPORT EXPECTED (14)		EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
X	YES (If yes, complete EXPECTED SUBMISSION DATE)	NO	08	31	98

ABSTRACT (Limit to 1400 spaces, i. e., approximately 15 single-spaced typewritten lines) (16)

On 5/16/98 at 2252 hours, Unit 3 was manually scrambled in response to a decrease in Main Condenser vacuum and increase in condensate demineralizer temperature, caused by the stuck open Main Turbine Crossaround Relief Valve Number 3 (CAR3). Prior to the manual scram, Operations experienced a decrease in Condenser vacuum during the initial main turbine reset and requested Engineering assistance in identifying possible air in-leakage. During investigation of the suspected air in-leakage, Plant Engineering personnel found that the CAR3 valve tailpipe was warmer than other CAR valve tailpipes. The Engineer and Operations personnel believed the valve was in satisfactory condition. The decrease in vacuum on the initial turbine reset was a result of air in the turbine supply piping due to the plant having been shutdown. The cause of this event was the CAR3 valve not being in the full closed position. A contributing cause was failure to thoroughly investigate the leakage through the CAR3 valve. The valve was disassembled and visually inspected and found to be slightly cocked. This is believed to be an apparent cause of CAR3 valve failure. There was no major damage to any internal parts identified. The safety significance was considered minimal since no emergency systems were needed to stabilize the plant following the scram. Subsequent to the scram, Group 2 and 3 isolation signals occurred as a result of the typical shrink in vessel level. All plant systems responded as designed. The cause of the CAR3 valve failure and previous occurrences information will be included in a supplemental report upon further analysis of the CAR3 valve's internal parts.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Dresden Nuclear Power Station, Unit 3	05000249	98	004	00	2 OF 5

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

PLANT AND SYSTEM IDENTIFICATION:

General Electric - Boiling Water Reactor - 2527 MWt rated core thermal power

Energy Industry Identification System (EIS) Codes are identified in the text as [XX] and are obtained from IEEE Standard 805-1984, IEEE Recommended Practice for System Identification in Nuclear Power Plants and Related Facilities.

EVENT IDENTIFICATION:

Unit 3 Manual Scram Due to Decreasing Condenser Vacuum Caused By A Stuck Open Turbine Crossaround Relief Valve.

A. PLANT CONDITIONS PRIOR TO EVENT:

Unit: 3	Event Date: 5/16/98	Event Time: 2252 CDT
Reactor Mode: 1	Mode Name: Run	Power Level: 35 Percent
Reactor Coolant System Pressure: 1000 psig		

Following a planned outage on Unit 3, plant personnel were in the process of performing startup activities. During startup, Operations personnel reset the main turbine [TA]. Upon resetting the turbine, Operations personnel perceived that a decrease in condenser vacuum indicated a possible air in-leakage pathway into the main condenser. Due to the observed vacuum decrease experienced during the main turbine reset on 5/15/98 at 1428 hours, Operations Department tripped the turbine and requested engineering assistance to identify potential air in-leakage paths to the main condenser.

During subsequent reset of the turbine on 5/15/98 at 1659 hours, condenser vacuum response was satisfactory. Discussions revealed the initial decrease in vacuum to be the result of air in the turbine steam supply piping due to the plant having been shutdown. It is typical to observe a decrease in condenser vacuum when initially resetting the turbine due to initial air influx into the condenser from the system steam piping. During the walkdown, the engineer observed that the tailpipe of the Main Turbine Crossaround Relief Valve Number 3 (CAR3) was warmer than other CAR tailpipes. This indicated that the CAR3 was passing steam to the 'A' section of the Main Condenser. This issue was discussed with Operations, where it was decided by the Engineer and Operation Shift Management that some minor valve leakage was acceptable and the CAR3 valve was in satisfactory condition for continuing the power ascension sequence. It was also noted that the CAR3 valve had been scheduled to perform its routine pressure testing during the next refuel outage.

Also during the startup, 'B' Steam Jet Air Ejector (SJAE)[SH] flow was oscillating severely and average capacity was below normal. Operations and the System Engineer confirmed that the oscillations and low capacity were not an instrument problem. They evaluated system performance as able to support continued plant operations because the SJAE drew and maintained a full vacuum. In addition, they forecast that the oscillations could be further investigated later in the startup because the other train was scheduled to be put in service in parallel for post maintenance tests. After plant shutdown, the SJAE flow oscillations were determined to be undamped system oscillations initiated by water passing through the SJAE in initial startup. The water was due to an abbreviated (but within procedural limits) warmup of the SJAE steam supply. This determination was confirmed by the following

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)		PAGE (3)
Dresden Nuclear Power Station, Unit 3	05000249	YEAR 98	SEQUENTIAL NUMBER 004	REVISION NUMBER 00
				3 OF 5

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

plant startup when SJAE startup was normal.

Unit 3 was synchronized to the grid at approximately 0552 hours on 5/16/98. The Unit's electrical output was increased to 288 MWe and preparations were in progress to place the feedwater heaters [SJ] in service.

B. DESCRIPTION OF EVENT:

This LER is being submitted pursuant to 10 CFR 50.73(a)(2)(iv), which requires the reporting of any event or condition that results in manual or automatic actuation of any Engineered Safety Feature (ESF), including the Reactor Protection System (RPS)[JC].

At approximately 1900 hours on May 16, 1998, flow oscillations which had been observed in SJAE 'B' increased from 0-120 SCFM to 0-300 SCFM. At this time, Operations discussed a contingency to manually scram the Unit if condenser vacuum decreased to 23 inches Hg or Condensate Demineralizer [SF] inlet temperature increased to 150 degrees.

At approximately 2145 hours, the NSO received an alarm for the Condensate To 'B' Gland Seal Condenser Temp Hi. A concern of Operations was that the "A" condenser hood vacuum was decreasing and that condensate demineralizer temperatures were increasing. Actions were taken to ensure that vacuum and condensate data were being closely monitored. Efforts to place the Feedwater Heaters [SJ] in service were delayed as a result of the abnormal conditions.

At approximately 2212 hours, the "RWCU Non-Regenerative Relief to Main Condenser Leak" annunciator was received. Operations secured the Reactor Water Cleanup system [CE] suspecting this relief may be open providing a source of heat input to the main condenser. The 'A' hood vacuum still continued to decrease and condensate temperature continued to trend upward. Operations reduced Reactor Recirculation [AD] flow to minimum and inserted control rods [AA] to decrease reactor power, in accordance with plant procedures. Additionally, Operations personnel were dispatched to fill the 'B' SJAE loop seals. Decreasing reactor power did not mitigate the observed decreasing condenser vacuum or increasing condensate temperatures. However, filling the loop seals did decrease oscillations in 'B' SJAE flow. Operations had planned to swap to the 'A' SJAE train once the Unit reached the Xenon soak, but discussed performing the swap during the loss of vacuum transient. Due to insufficient time, the 'A' SJAE train was not placed in service prior to the scram contingency setpoints being met.

Condensate demineralizer inlet temperature reached 149 degrees F and was continuing to increase, at which time the order to scram was made. On 5/16/98 at 2252 hours, Unit 3 was manually scrammed in response to the decrease in main condenser vacuum and increase in condensate demineralizer inlet temperature.

The manual scram of Unit 3 was inserted at a condenser vacuum of 23.9 inches Hg and decreasing. Subsequent to the scram, Group 2 and 3 isolation signals occurred as a result of the typical shrink in vessel level. All plant systems responded as design.

C. CAUSE OF EVENT:

The increase in condensate temperature and low condenser vacuum, which resulted in a manual scram, was caused by leakage through the CAR3 valve. During disassembly of the valve, maintenance personnel heard the

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Dresden Nuclear Power Station, Unit 3	05000249	98	004	00	4 OF 5

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

valve reseal which indicated that the valve had been stuck open.

This abnormal condition is supported by the following facts: 1) The CAR3 valve tailpipe was found to be warmer than other CAR valve tailpipes during startup indicating that there was some amount of leak through. 2) The CAR3 discharges to the "A" section of the condenser, which is the hood that initially began to lose vacuum and degraded the most. 3) The discharge is below the main condenser tubes, which supports the rapid temperature change data.

The cause of the CAR3 valve stuck open is unknown at this time and a root cause analysis of the valve's internal parts will be performed. A supplement report will be issued with the cause of failure and corrective actions.

A contributing cause of this event was found to be failure to investigate the CAR3 valve tailpipe temperature increase. The cause of the failure to investigate the increase in tailpipe temperature is unknown at this time but will be determined following completion of a root cause analysis. The cause will be included in the LER supplement report.

The CAR 3 valve was disassembled and found slightly cocked to the side with no major damage to internal parts. All parts were replaced and CAR 3 valve was successfully tested at its pressure setpoint. The number 1 and 2 CAR valves were tested since their preventive maintenance activity was scheduled for the upcoming refuel outage. The Number 1 CAR valve was successfully tested at its pressure relief setpoint. The number 2 CAR valve failed to lift at its set pressure and exhibited minor seat leakage during testing. The valve was disassembled, cleaned and successfully retested. The most recent PM history of the remaining four CAR valves was reviewed and all valves exhibited no sticking and successfully passed their lift test. In addition, during Unit 3 startup from the manual scram, all six CAR valves that relieves from the CIVs had their tailpipe temperature monitored with no abnormalities observed. Consequently, the station is confident that all the CAR valves on Unit 3 are in satisfactory condition to perform their design function.

D. SAFETY ANALYSIS

The safety significance of this event was limited to the fact that it was a challenge to Operations, as is every situation involving a need for prompt diagnosis and decision to manually trip the reactor. The Operations decision to manually scram was proper per procedure and pre-briefed in accordance with conservative decision making philosophy. With exception of the abnormalities causing and contributing to the need for a manual scram, plant equipment response was per design and required no operator action. No safety systems were needed in response to this event with exception of the expected automatic isolations designed to occur following a scram.

E. CORRECTIVE ACTIONS:

The following corrective actions were or will be taken:

The CAR3 valve was disassembled and the valve reseated when the mechanics loosened the bolts. Upon inspection of the valve, the stem was found slightly cocked to the side. The spindle was frozen inside the spindle guide and some minor scratching was found on the guide and bushing. All other internal parts had no damage or

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
Dresden Nuclear Power Station, Unit 3	05000249	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	5 OF 5
		98	004	00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

very little damage. (Complete)

After replacement of all internal parts, the CAR3 valve was successfully tested at its pressure setpoint. (Complete)

The Numbers 1 and 2 CAR valves were tested since their preventive maintenance activity was scheduled for the upcoming refuel outage. The Number 1 CAR valve was successfully tested at its pressure relief setpoint. The Number 2 CAR valve failed to lift at its specified lift set pressure and exhibited minor seat leakage during testing. The valve was disassembled, cleaned and successfully retested. (Complete)

Dresden General Procedure (DGP) 2-3, Reactor Scram, and DGP 2-1, Unit Shutdown, were revised to check the CAR valve positions using their handle after a turbine trip. (Complete)

DGP 1-1, Unit Startup was revised to check the CAR valve tailpipe temperatures during startup activities. (Complete)

Perform a root cause analysis on the failure to investigate increased crossaround relief valve tailpipe temperature. NTS 249-180-98-00401.

Perform an equipment root cause analysis on the internals of the Crossaround Relief Valve Number 3. Include an evaluation of thermal loading on the valve and discharge piping. NTS 249-180-98-00402

The root cause analysis for the CAR3 valve will also include the following: 1) evaluation of the CAR valve's PM frequency, 2) evaluation of the adequacy of PM actions for the CAR valves and 3) determine root cause of CAR2 valve as-found pop test results and seat leakage. NTS 249-180-98-00403.

A supplement report to this LER will be submitted following completion of the root cause analysis of the increase tailpipe temperature and internal parts of the CAR3. NTS 249-180-98-00404

The procedure limits (DOP 5400-02) on warmup of SJAE system have been revised (Complete)

F. PREVIOUS OCCURRENCES:

Previous occurrence information will be included in the supplemental LER.

G. COMPONENT FAILURE DATA:

Manufacturer	Nomenclature	Model Number
Crosby	Crossaround Relief Valve	JB 26