

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



June 29, 1998

JMHLTR: #98-0187

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Enclosed is Licensee Event Report 98-005, Docket 50-249, which describes Reactor Pressure Boundary Leakage In Excess of Technical Specifications Limit Due To Transverse In-Core Probe Dry Tube Leakage. This condition is being reported as a final report pursuant to 10 CFR 50.73(a)(2)(i) which requires the reporting of any operation or condition prohibited by the plant's Technical Specifications.

The initial review of this condition which occurred on May 6, 1998, did not conclude that this condition was reportable pursuant to 10 CFR 50.73. However upon further review, it was determined that the condition would be reportable as stated above. The missed reportability determination is being reviewed in accordance with our corrective action program.


The leaking dry tube was capped to prevent any further leakage. (Complete)

This correspondence contains the following commitment(s):

Replace Local Power Range Monitor Assembly 16-09 during the next refueling outage (D3R15). (249-180-98-00501)

If you have any questions, please contact Frank Spangenberg, Dresden Regulatory Assurance Manager at (815) 942-2920 extension, 3800.

Sincerely,


J.M. Henley
Site Vice President
Dresden Station

Enclosure

cc: Regional Administrator, Region III
NRC Resident Inspector's Office

9807070317 980629
PDR ADOCK 05000249
S PDR

1/1
IE 22