

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



July 6, 1998

JMHLTR: #98-0189

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555


Enclosed is the Supplement to Licensee Event Report 97-018, Docket 50-237, which describes an unexpected High Pressure Coolant Injection System Steam Supply isolation during surveillance testing. This condition is being reported as a final report pursuant to 10 CFR 50.73(a)(2)(iv) which requires the reporting of any event or condition that results in a manual or automatic actuation of any Engineered Safety Feature.

The following actions were taken:

1. The immediate corrective action was to declare the Unit 2 HPCI system inoperable and enter an LCO actions in accordance with the Plant's Technical Specifications. (Completed)
2. The suspect relays were replaced and successfully tested in accordance with the Instrument Department surveillance prior to declaring the system operable. (Completed)
3. A failure analysis has been performed on the relays that were removed (2-2301-02C and D). (Completed)
4. The multimeter used in performance of the surveillance has been tested and calibrated. (Completed)

If you have any questions, please contact Frank Spangenberg, Dresden Regulatory Assurance Manager at (815) 942-2920 extension, 3800.

Sincerely,


J. M. Henley
Site Vice President
Dresden Station

Enclosure

cc: Regional Administrator, Region III
NRC Resident Inspector's Office

9807080089 980706
PDR ADOCK 05000237
S PDR

Y/
IE22