

ATTACHMENT TO LICENSEE EVENT REPORT 80-015/01T-0

COMMONWEALTH EDISON COMPANY (CWE)

DRESDEN UNIT 3 (ILDRS 3)

DOCKET #050-249

During Unit 3 refueling outage while replacing hydraulic snubbers in the containment, it was noted that snubber #23 was fully retracted. The snubber, a Pacific Scientific 10 KIP Unit, is located on the reactor water clean-up line 3-1201-8"-A. After further investigation, it was noted that the 3" snubber stanchion attachment to this line was bent and the weld cracked. In addition, the process pipe was "dimpled" when the 3" pipe was bent over. The "dimple" was measured to be about 6" along the axis of pipe with a depth about 1/2". The attachment for snubber #27 was also checked and found bent slightly. Both attachments were removed from the process pipe and the areas around and under them were ultrasonic inspected. An indication was found at the center of the "dimple" (snubber #23 attachment point). However, subsequent radiographic tests did not confirm this indication. The attachment for snubber #27 was inspected and no indications were found. In addition to the pipe damage, the pipe was also displaced slightly causing one variable support spring to become unloaded and one to become fully loaded. The safety significance of this event was minimal because even in the event of a complete break of this line, the system isolation valve would have closed, preventing radiation dose limits from being exceeded, and fuel damage from occurring.

The failure of the snubber attachments and consequent pipe damage is suspected to have been caused as a result of a water hammer in the system. This initiation method is quite likely based on system operating problems on start-up after system trip and isolation. The damaged piece of pipe will be removed and replaced before startup from this refueling outage. Attached to the pipe will be an improved snubber attachment, consisting of a 12" saddle to which a piece of 4" pipe will be welded. Off the 4" pipe will be welded the snubber attachment. The proper loading of the variable pipe support springs will be made thru use of shims adjustment or relocation of the supports. All of the remaining welds of the reactor water clean-up line located inside the containment have been penetrant tested with no indication of cracking found. To eliminate the initiation of a water hammer on start-up after system trip and isolation, the seal-in feature of the reactor water clean-up system inboard isolation valve will be removed before startup to enable the valve to be throttled and the system pressurized gradually after trip and isolation. In addition, the damaged snubber will be replaced with like.



DEVIATION REPORT

Commonwealth Edison

DVR NO.	STA.	UNIT	YEAR	NO.
	D-12	-3	-80	-26

PART 1 TITLE OF DEVIATION	OCCURRED
Pipe Crack In Reactor Water Cleanup Line	4-2-80 2100 hrs
	DATE TIME

SYSTEM AFFECTED 1200	PLANT CONDITIONS	TESTING
Reactor Water Cleanup	MODE Refuel PWR (MWT) 0 LOAD (MWE) 0	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

DESCRIPTION OF EVENT
 UT of Reactor water cleanup line 1201 in the area of snubber no. 23 stanchion indicates a pipe crack.

DESCRIPTION OF CAUSE
 Probable cause is a water hammer in the line, causing the snubber stanchion to bend resulting in an indentation and crack in the pipe.

OTHER APPLICABLE INFORMATION
 Radiograph to be taken of the suspect area of pipe to confirm UT indication; action initiated to replace affected section of pipe; all remaining welds of the line inside the drywell (OVER

EQUIPMENT FAILURE	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	DR NO.	WR NO.	Thomas A. Ciesla	4-3-80
				RESPONSIBLE SUPERVISOR	DATE

PART 2 OPERATING ENGINEERS COMMENTS
 The unit is currently in its refueling outage which began 2-3-80.

TYPE OF DEVIATION REPORTABLE OCCURRENCE	EVENT OF POTENTIAL PUBLIC INTEREST	TECH SPEC VIOLATION	NON-REPORTABLE OCCURRENCE	ANNUAL REPORTING	SAFETY-RELATED WR ISSUED
<input checked="" type="checkbox"/> 14 DAY <input type="checkbox"/> 10CFR21	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
<input type="checkbox"/> 30 DAY NOTIFICATION 6.6.B.1.c					

REPORTABLE OCCURRENCE NUMBER	ACTION ITEM NO.	PROMPT ON-SITE NOTIFICATION
80-15/01T-0		R. M. Ragan 4-3-80 0800 TITLE DATE TIME
		TITLE DATE TIME

24-HOUR NRC NOTIFICATION	PROMPT OFF-SITE NOTIFICATION
<input checked="" type="checkbox"/> TPH J. Barker 4-2-80 2130 REGION III DATE TIME	F. Palmer 4-3-80 10:08 TITLE DATE TIME
<input type="checkbox"/> TGM REGION III & DOL DATE TIME	J. Gilliom 4-3-80 10:08 TITLE DATE TIME

RESPONSIBLE COMPANY OFFICER INFORMED OF 10CFR21 CONDITIONS AND THEIR REPORT TO NRC	TITLE DATE TIME
	Michael Wright 2-3-80 OPERATING ENGINEER DATE

ACCEPTANCE BY STATION REVIEW AS REQUIRED

DATE

RESOLUTION APPROVED AND AUTHORIZED FOR DISTRIBUTION

Dennis James Michael Wright
 4-10-80 4-15-80
[Signature]
 STATION SUPERINTENDENT DATE

OTHER APPLICABLE INFORMATION

have been penetrant tested with no indication of cracking.



Commonwealth Edison

DEVIATION REPORT

DVR NO.	STA	UNIT	YEAR	NO.
	D-12	- 3	- 80	- 23

PART 1 TITLE OF DEVIATION	FOUND MECHANICAL SNUBBER FULLY RETRACTED.	OCCURRED DATE	3/27/80	TIME	1200
----------------------------------	---	---------------	---------	------	------

SYSTEM AFFECTED	PLANT CONDITIONS	TESTING
Rx Clean-up	MODE: Refuel PWR (MWT) 0 LOAD (MWE) 0	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>

DESCRIPTION OF EVENT
 During an inspection of all 35 mechanical snubbers in Dresden-3 drywell, location #23 on C.U. Line 1201-8 was found to have a snubber (10Kip) with piston fully retracted.

DESCRIPTION OF CAUSE
 Unknown at this time.

OTHER APPLICABLE INFORMATION
 Mechanical snubber was initially installed with piston setting of 1 3/4".

EQUIPMENT FAILURE	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	DR NO.	WR NO.	5650	S. W. Harris	3/27/80
					RESPONSIBLE SUPERVISOR	DATE

PART 2 OPERATING ENGINEERS COMMENTS
 This snubber was discovered to be bottomed out during a routine refueling outage snubber inspection.

TYPE OF DEVIATION REPORTABLE OCCURRENCE	EVENT OF POTENTIAL PUBLIC INTEREST	TECH SPEC VIOLATION	NON-REPORTABLE OCCURRENCE	ANNUAL REPORTING	SAFETY-RELATED WR ISSUED
<input checked="" type="checkbox"/> 14 DAY <input type="checkbox"/> 10CFR21 <input type="checkbox"/> 30 DAY NOTIFICATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>

REPORTABLE OCCURRENCE NUMBER	ACTION ITEM NO.	PROMPT ON-SITE NOTIFICATION
XXX 80-15 / OIT-0		R. M. Ragan 3/31/80
		TITLE DATE TIME
		TITLE DATE TIME

24-HOUR NRC NOTIFICATION	PROMPT OFF-SITE NOTIFICATION
<input type="checkbox"/> TPH REGION III DATE TIME	F. A. Palmer 3/31/80 2:27
<input type="checkbox"/> TGM REGION III & DOL DATE TIME	J. Gilliom 3/31/80 2:27
	TITLE DATE TIME

RESPONSIBLE COMPANY OFFICER INFORMED OF 10CFR21 CONDITIONS AND THEIR REPORT TO NRC

REVIEW AND COMPLETED	Michael Wright	3-31-80
	OPERATING ENGINEER	DATE

ACCEPTANCE BY STATION REVIEW AS REQUIRED

DATE

RESOLUTION APPROVED AND AUTHORIZED FOR DISTRIBUTION

Dennis Davis
 4-10-80
B. J. Matanzo
 STATION SUPERINTENDENT
 4/15/80
 DATE