

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | I | L | D | R | S | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
8 9 14 15 25 26 30 57 CAT 58

0 1 | R | P | O | S | 0 | 5 | 0 | 0 | 0 | 2 | 3 | 7 | 0 | 5 | 1 | 2 | 8 | 0 | 8 | 0 | 6 | 0 | 3 | 8 | 0 | 9
8 9 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During reactor startup, HPCI inboard steam isolation valve failed to close
0 3 | (T.S.3.7.D.1). Reactor startup was terminated and the valve was manually closed.
0 4 | The health and safety of the public was not endangered due to redundant systems
0 5 | being operable, and line was isolatable. This is the first occurrence of this type.
0 6 |
0 7 |
0 8 |

0 9 | S | F | B | C | V | A | L | V | E | X | E | D |
9 10 11 12 13 18 19 20
17 | LER/RO REPORT NUMBER | 8 | 0 | - | 0 | 1 | 8 | / | 0 | 3 | L | - | 0
21 22 23 24 26 27 28 29 30 31 32
ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS | ATTACHMENT SUBMITTED | NPRD-4 FORM SUB. | PRIME COMP. SUPPLIER | COMPONENT MANUFACTURER
E | Z | C | A | 0 | 0 | 0 | 0 | N | Y | N | C | 6 | 6 | 5
33 34 35 36 37 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | During the preceding Unit shutdown, the valve packing had been replaced. Due to
1 1 | reactor heatup, the steam caused the valve packing to swell, preventing the valve
1 2 | from closing. The packing was adjusted. The valve was cycled three times
1 3 | satisfactorily and timed properly closed. No further action deemed necessary.
1 4 |

1 5 | C | 0 | 0 | 1 | N/A | A | Operator Observation
8 9 10 12 13 44 45 46 80

1 6 | Z | Z | N/A | N/A
8 9 10 11 44 45 80

1 7 | 0 | 0 | 0 | 2 | N/A
8 9 11 12 13 80

1 8 | 0 | 0 | 0 | N/A
8 9 11 12 80

1 9 | Z | N/A
8 9 10 80

2 0 | N | N/A | 8006/60/02
8 9 10 68 69 80

NRC USE ONLY