

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 I L D R S 3 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

CON'T 0 1 L 6 0 5 0 0 0 2 4 9 7 0 5 1 9 8 0 8 0 6 1 2 8 0 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
During normal operation with reactor level instrument surveillance in progress, level switch LIS 3-263-58A tripped at less than the Tech. Spec. limit (Table 3.2.1) of 144 inches. The safety significance of this event was minimal since channel "B" and the redundant channel "A" instruments were operable. There was no effect on public health or safety. Previous occurrences: R.O. 76-57/03L-0, Docket 50-237 and 77-51/03L-0, Docket 50-249.

0 9 SYSTEM CODE I A 11 CAUSE CODE E 12 CAUSE SUBCODE E 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE S 15 VALVE SUBCODE Z 16
17 LER/RO REPORT NUMBER 8 0 2 3 0 3 L 0
ACTION TAKEN E 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER Y 0 1 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
The cause of this event was a misaligned Yarway switch assembly, model number 4418C, serial number 44180. The switch was adjusted and satisfactorily tested. DIS 500-2 will continue to be performed monthly.

1 5 FACILITY STATUS E 28 % POWER 0 8 5 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Instrument Mechanic Observation 32
1 6 ACTIVITY CONTENT Z 33 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36
1 7 PERSONNEL EXPOSURES 0 0 0 37 Z 38 N/A 39
1 8 PERSONNEL INJURIES 0 0 0 40 N/A 41
1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43
2 0 PUBLICITY ISSUED N 44 DESCRIPTION N/A 45