

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 I L D R S 2 0 0 - 0 0 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5

0 1 REPORT SOURCE L 0 5 0 0 0 2 3 7 7 0 5 2 8 8 0 8 0 6 2 4 8 0 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

U-2 was at steady state power operation when "C" Main Steam Line Rad Monitor tripped, resulting in a half scram and a Group I isolation. The safety significance of this event was minimal because all reactor protection systems functioned as designed. This is not a repetitive event.

0 9 SYSTEM CODE M C 11 CAUSE CODE E 12 CAUSE SUBCODE G 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE X 15 VALVE SUBCODE Z 16

17 LER/RO REPORT NUMBER 8 0 EVENT YEAR 8 0 SEQUENTIAL REPORT NO. 0 1 9 OCCURRENCE CODE 0 3 REPORT TYPE L REVISION NO. 0

ACTION TAKEN C 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 ATTACHMENT SUBMITTED N 23 NPRO-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER G 0 8 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

Electronic components failure was the cause of the trip, transistors and capacitors were detected to be defective. As a corrective action, the whole assembly was replaced. No further trips were received. No future corrective action is deemed necessary.

1 5 FACILITY STATUS E 28 % POWER 0 8 6 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator's Observation 32

1 6 ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

2 0 PUBLICITY ISSUED N 44 DESCRIPTION NA 45

8007070551

Shafiq Badran

548