

ATTACHMENT TO LICENSEE EVENT REPORT 80-27/01T-0
COMMONWEALTH EDISON COMPANY (CWE)
DRESDEN UNIT 3 (ILDRS3)
DOCKET #050-249

On July 7, 1980, at 0800, an engineering evaluation of the CRD scram discharge piping revealed that it does not meet seismic requirements as described in the FSAR. The reactor was in the run mode operating at 92 percent power. This resulted in operation in a manner less conservative than assumed in the accident analyses (Tech. Spec. 6.6.B.1.i). It was determined that operability requirements were met per I.E. Bulletins 79-02 and 79-14, thus this event has minimal safety significance. Public health and safety were not affected. Previous occurrence: R.O. 80-22/01T-0, Docket #050-237.

The cause of the event was due to a design deficiency in that the correct seismic supports were not installed. Analyses were performed to verify the operability requirements of the CRD scram discharge piping per I.E. Bulletins 79-02 and 79-14. EDS Inc. is designing the new seismic supports which will be installed upon completion of fabrication.