

LICENSEE EVENT REPORT

CONTROL BLOCK:

Control block grid with circled '1' in the 8th column.

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE: I L D R S 2; LICENSE NUMBER: 200-000000-000; LICENSE TYPE: 341111; CAT 58: 45

REPORT SOURCE: L; DOCKET NUMBER: 605000237; EVENT DATE: 7072580; REPORT DATE: 8082080

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

The unit was in normal operation, dropping load in preparation for I.E.B. 80-17 scram tests. The equipment operator noticed a low level of Diesel Generator coolant present in the water tank. A lube oil sample was taken, and water was found in the oil. Minimal effect on public health and safety due to the operability of Unit 2/3 Diesel Generator. There has been a similar occurrence, R. O. 80-08/03L-0

SYSTEM CODE: EE; CAUSE CODE: E; CAUSE SUBCODE: D; COMPONENT CODE: H T E X C H; COMP. SUBCODE: C; VALVE SUBCODE: Z

LER/RO REPORT NUMBER: 17; EVENT YEAR: 80; SEQUENTIAL REPORT NO.: 027; OCCURRENCE CODE: 03; REPORT TYPE: L; REVISION NO.: 0

ACTION TAKEN: BZ; EFFECT ON PLANT: Z; SHUTDOWN METHOD: Z; HOURS: 0000; ATTACHMENT SUBMITTED: N; NPRD-4 FORM SUB.: N; PRIME COMP. SUPPLIER: N; COMPONENT MANUFACTURER: Y021

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

Coolant loss caused by leaking tubes in one cooling water/service water heat exchangers. Water in lube oil determined to be condensation. Leaking tubes were plugged and oil changed. Diesel Generator Surveillance Test performed. These heat exchangers are included in a company program to review causes of tube degradation.

FACILITY STATUS: E; % POWER: 039; OTHER STATUS: N/A; METHOD OF DISCOVERY: A; DISCOVERY DESCRIPTION: Equipment Operator Observation

ACTIVITY CONTENT: Z; AMOUNT OF ACTIVITY: N/A; LOCATION OF RELEASE: N/A

PERSONNEL EXPOSURES: 000; TYPE: Z; DESCRIPTION: N/A

PERSONNEL INJURIES: 000; DESCRIPTION: N/A

LOSS OF OR DAMAGE TO FACILITY: Z; DESCRIPTION: N/A

PUBLICITY ISSUED: N; DESCRIPTION: N/A

8'008260592