

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 I L D R S 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

REPORT SOURCE L 6 0 5 0 0 0 2 3 7 7 0 7 2 1 8 0 8 0 8 1 5 8 0 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
During normal operations, drywell oxygen concentration indication failed downscale in violation of Dresden Tech. Spec. 3.7.A.6.d. Safety consequences were minimal because drywell oxygen concentration was well below 4% before indication failed and oxygen concentration readings taken on a portable analyzer were available upon request.
Similar events: 80-7/03L-0, 80-1/03L-0

SYSTEM CODE I D 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE E 15 VALVE SUBCODE Z 16
LER/RO REPORT NUMBER 17 EVENT YEAR 8 0 21 22 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER F 0 8 1 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
The reason for the downscale reading was excessive high temperature of the oxygen analyzer cell caused by failure of a temperature sensing switch. The temperature switch, Fenwal Inc., No. 1800-0, was replaced. Correct temperature control and accurate oxygen indication resulted.

FACILITY STATUS E 28 % POWER 0 6 7 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32
ACTIVITY CONTENT Z 33 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE 36
PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39
PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41
LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43
PUBLICITY ISSUED N 44 DESCRIPTION N/A 45

8008260 616

NRC USE ONLY