

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 I L D R S 3 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

CON'T 0 1 REPORT SOURCE L 6 0 5 0 0 0 2 4 9 7 0 8 3 1 8 0 8 0 9 2 2 8 0 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 While holding at about 515 MW after control rod pulls, the 3B recirc pump ran back.
0 3 from 42% to 22% speed. The 3B recirc M.G. Set scoop tube was locked out and the pump
0 4 manually brought back to 42%. This event was of minimal safety significance since
0 5 original pump speed was quickly restored, and 3A recirc. pump speed could have been
0 6 lowered if required. This is the first event of this nature.
0 7
0 8

0 9 SYSTEM CODE C B 11 CAUSE CODE E 12 CAUSE SUBCODE G 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE C 15 VALVE SUBCODE Z 16
17 LER/RO REPORT NUMBER 8 0 0 3 4 0 3 L 0
18 C 19 Z 20 B 21 Z 22 0 0 0 0 23 24 25 26 27 28 29 30 31 32
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 This event was caused by the failure of the MG Set speed controller, GE Model #50-5430
1 1 41D-AA Z1PBE. The exact cause of failure has not been determined. The controller was
1 2 replaced like for like.
1 3
1 4

1 5 FACILITY STATUS E 28 % POWER 0 6 2 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32

1 6 ACTIVITY CONTENT Z 33 Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36

1 7 PERSONNEL EXPOSURES 0 0 0 37 Z 38 DESCRIPTION N/A 39

1 8 PERSONNEL INJURIES 0 0 0 40 DESCRIPTION N/A 41

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43

2 0 ISSUED DESCRIPTION N 44 N/A 45

8010070612

NRC USE ONLY