

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 I L D R S 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 2 3 7 7 0 3 2 7 7 9 8 0 9 0 3 8 0 9
8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2 Measured leakage of volume bounded by containment isolation valves A0-2-1601-23, 24, 60
0 3 61, 62 & 63 was 1660 SCFH. This exceeds the T.S. limits for single containment isola-
0 4 tion valve allowable leakage, total for testable penetrations and isolation valves and
0 5 maximum allowable containment leak rate. The leakage was into the secondary contain-
0 6 ment and the Standby Gas System which resulted in no danger to public health and safety.
0 7 Similar events were reported by 50-237/76-10, 50-249/76-16 and 50-249/80-07.

0 9 SYSTEM CODE S D 11 CAUSE CODE E 12 CAUSE SUBCODE X 13 COMPONENT CODE V A L V E X 14 COMP. SUBCODE B 15 VALVE SUBCODE D 16
8 9 10 11 12 13 18 19 20

17 LER/RO REPORT NUMBER 7 9 21 22 EVENT YEAR
0 1 7 SEQUENTIAL REPORT NO. 24 26
0 1 OCCURRENCE CODE 28 29
0 1 REPORT TYPE 30 31
1 REVISION NO. 32 32
ACTION TAKEN X 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED Y 23 NPRD-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER P 3 4 0 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
1 0 Leakage was initially identified to be from the shaft seals on A0-2-1601-60. Subse-
1 1 quent testing indicated leakage on the 1601-23 and 1601-24 valve shaft seals and seat
1 2 leakage on valve 1601-24. The 1601-24 valve was replaced and shaft seals on valves
1 3 1601-23 and 1601-60 were repaired. No further action deemed necessary.

1 5 FACILITY STATUS H 28 % POWER 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Local Leak rate testing 32
8 9 10 12 13 44 45 46 80

1 6 ACTIVITY CONTENT Z 33 Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36
8 9 10 11 44 45 80

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE 38 DESCRIPTION N/A 39
8 9 10 11 12 13 80

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41
8 9 10 11 12 13 80

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43
8 9 10 80

2 0 PUBLICITY ISSUED N 44 DESCRIPTION N/A 45
8 9 10 80

8010270381

SUPPLEMENT TO DVR

DVR NO.				
STA	UNIT,	YEAR	NO.	
D - 12	- 2	- 79	- 25	

PART 1	TITLE OF EVENT	OCCURRED	
	Containment Vent Line Excessive Leakage	03/27/79	0530
		<u>DATE</u>	<u>TIME</u>
	REASON FOR SUPPLEMENTAL REPORT		
	Incorporates leakage on the 1601-23 & 24 valves		
PART 2			
ACCEPTANCE BY STATION REVIEW	<u>J Brunner</u>	<u>John W. Wiggins</u>	_____
DATE	<u>9/30/80</u>	<u>10/15/80</u>	_____
SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION	<u>Douglas King</u>		<u>10/16/80</u>
	STATION SUPERINTENDENT		DATE