

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 I L D R S 3 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

CON'T REPORT SOURCE: L 6 0 5 0 0 0 2 4 9 7 1 1 0 5 8 0 8 1 1 1 7 8 0 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During normal operation, with DIS 700-3 in progress, SRM channel 23 was found to trip at greater than the Technical Specification limit on Table 3.2.3. The safety significance was minimal since all other channels were operable and would have provided a rod block if required. There were no health or safety effects on the public. Previous occurrences, Docket 050-249; 79-23, 79-19, and 79-15.

0 9 SYSTEM CODE I E 11 CAUSE CODE E 12 CAUSE SUBCODE G 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE E 15 VALVE SUBCODE Z 16

17 LER/RO REPORT NUMBER 8 0 21 22 EVENT YEAR 8 0 23 24 SEQUENTIAL REPORT NO. 0 4 2 25 26 OCCURRENCE CODE 0 3 27 28 REPORT TYPE L 29 30 REVISION NO. 0 31 32 ACTION TAKEN E 18 Z 19 33 34 FUTURE ACTION Z 20 35 EFFECT ON PLANT Z 21 36 SHUTDOWN METHOD 0 0 0 0 22 37 40 HOURS ATTACHMENT SUBMITTED N 23 41 42 NPRD-4 FORM SUB. N 24 43 PRIME COMP. SUPPLIER N 25 44 47 COMPONENT MANUFACTURER G 0 8 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27 The cause is attributed to electronic drift of high alarm setpoint potentiometer on module Z-16B. The setpoint was immediately adjusted and tested satisfactorily. DIS 700-3 will continue to be done weekly.

1 5 FACILITY STATUS E 28 29 % POWER 0 9 9 30 OTHER STATUS N/A 31 METHOD OF DISCOVERY B 32 DISCOVERY DESCRIPTION Surveillance Testing

1 6 ACTIVITY CONTENT Z 33 34 RELEASED OF RELEASE Z 35 AMOUNT OF ACTIVITY N/A 36 LOCATION OF RELEASE

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 38 TYPE Z 39 DESCRIPTION N/A

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 41 DESCRIPTION N/A

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 43 DESCRIPTION N/A

2 0 PUBLICITY ISSUED N 44 45 DESCRIPTION N/A 8011250368 P. Holland 815-942-2920 ext 482

20 917-926