

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 I L D R S 2 000-0000000-000 411111

CON'T 01 REPORT SOURCE L 05000249 122580 011981

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

02 During normal unit operation, air was discovered blowing from air start regulator valve for the Unit 3 diesel generator. Diesel generator was declared inoperable, and all required surveillances performed. Event of minimal safety significance since the 2/3 diesel generator was capable of providing emergency power. First event of this type at Dresden Station.

07 08

09 SYSTEM CODE EE CAUSE CODE E CAUSE SUBCODE B COMPONENT CODE VALVE EX COMP. SUBCODE D VALVE SUBCODE H LER/RO REPORT NUMBER 80 SEQUENTIAL REPORT NO. 049 OCCURRENCE CODE 03 REPORT TYPE L REVISION NO. 0 ACTION TAKEN C FUTURE ACTION Z EFFECT ON PLANT Z SHUTDOWN METHOD Z HOURS 0000 ATTACHMENT SUBMITTED N NPRD-4 FORM SUB. Y PRIME COMP. SUPPLIER N COMPONENT MANUFACTURER P08C

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

10 The cause was a bad seal in the air start regulator valve. The regulator valve was replaced, and the Unit 3 diesel generator was demonstrated to be operable. No further action deemed necessary.

14

15 FACILITY STATUS F % POWER 059 OTHER STATUS N/A METHOD OF DISCOVERY B DISCOVERY DESCRIPTION Operator's Round

16 ACTIVITY CONTENT Z RELEASED OF RELEASE Z AMOUNT OF ACTIVITY N/A LOCATION OF RELEASE N/A

17 PERSONNEL EXPOSURES NUMBER 000 TYPE Z DESCRIPTION N/A

18 PERSONNEL INJURIES NUMBER 000 DESCRIPTION N/A

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z DESCRIPTION N/A

20 ISSUED N DESCRIPTION N/A

810-1270613

Sam Bader

815-942-2920 Ext. 422

90 917-026