

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
0 1 I L D R S 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
0 1 REPORT SOURCE L 0 5 0 0 0 2 3 7 1 2 3 1 8 0 0 1 2 6 8 1 9
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation while performing drywell Hi Pressure Containment Spray
0 3 Interlock Surveillance, the 150I-62D pressure switch actuated at 44.2 inches of
0 4 water increasing. Tech. Spec. limit is less than or equal to 41.6 inches of water
0 5 increasing. The health and safety of the general public was not affected, since
0 6 redundant instrumentation was available. This is the first occurrence of this type.
0 7
0 8

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
0 9 SYSTEM CODE S F 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE S 15 VALVE SUBCODE Z 16

17 LER/RO REPORT NUMBER 8 10 EVENT YEAR 8 0 0 SEQUENTIAL REPORT NO. 0 9 8 OCCURRENCE CODE 0 3 REPORT TYPE L REVISION NO. 0
ACTION TAKEN E 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER 3 8 2 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause was misalignment of the actuating arm and microswitch adjusting screw
1 1 being set too high. The actuating bar was realigned and the microswitch adjusted.
1 2 The pressure switch will continue to be checked per the surveillance schedule.
1 3
1 4

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
1 5 FACILITY STATUS E 28 % POWER 0 4 3 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Routine Surveillance 32

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
1 6 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 TYPE 37 Z 38 DESCRIPTION N/A 39

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
1 8 PERSONNEL INJURIES NUMBER 0 0 0 DESCRIPTION N/A 41

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
2 0 PUBLICITY ISSUED N 44 DESCRIPTION N/A 45

NRC USE ONLY

NAME OF PREPARER K. Zirwas

PHONE: 942-2920 Ext. 422

8102020 396