

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1	<u>I</u>	<u>L</u>	<u>D</u>	<u>R</u>	<u>S</u>	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0
	LICENSEE CODE														LICENSE NUMBER										LICENSE TYPE					CAT 58														

CONT	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0
	REPORT SOURCE					DOCKET NUMBER										EVENT DATE					REPORT DATE																			

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES: (10)

0.1 Unit 2 was at steady power operation and DTS 1600-2 "Secondary Containment Leak Rate Test" had been performed. At the completion of the test, the Reactor Building

0.2 Ventilation isolation valve 2A-5742 would not open. There was no hazard to public

0.3 because Standby Gas Treatment System was running and the other three isolation

0.4 valves were operable. There has been no previous report of an event of this type.

0.5

0.6

0.7

0.8

1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	
	SYSTEM CODE					CAUSE CODE					COMPONENT CODE					COMP. SUBCODE					VALVE SUBCODE																			
	<u>S</u> <u>D</u>					<u>E</u> <u>E</u>					<u>V</u> <u>A</u> <u>L</u> <u>V</u> <u>O</u> <u>P</u>					<u>D</u>					<u>Z</u>																			
	EVENT YEAR					SEQUENTIAL REPORT NO.					OCCURRENCE CODE					REPORT TYPE					REVISION NO.																			
	<u>8</u> <u>0</u>					<u>0</u> <u>4</u> <u>9</u>					<u>0</u> <u>3</u>					<u>L</u>					<u>0</u>																			
	ACTION TAKEN					EFFECT ON PLANT					SHUTDOWN METHOD					HOURS					ATTACHMENT SUBMITTED					NPRD-4 FORM SUB.					PRIME COMP. SUPPLIER					COMPONENT MANUFACTURER				
	<u>Z</u>					<u>Z</u>					<u>0</u> <u>0</u> <u>0</u> <u>0</u>					<u>N</u>					<u>Y</u>					<u>N</u>					<u>V</u> <u>0</u> <u>9</u> <u>3</u>									

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS: (27)

1.0 The four way directional control solenoid valve in valve A0-2A-5742 operator stuck

1.1 in the "closed" position due to accumulation of dirt in the valve internals. The

1.2 solenoid valve and coil were replaced and A0-2A-5742 was tested for proper operation

1.3 prior to returning to service. No further corrective action required.

1.4

1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0
	FACILITY STATUS					% POWER					OTHER STATUS					METHOD OF DISCOVERY					DISCOVERY DESCRIPTION																		
	<u>E</u>					<u>0</u> <u>3</u> <u>8</u>					<u>N/A</u>					<u>B</u>					<u>N/A</u>																		
	ACTIVITY RELEASED					AMOUNT OF ACTIVITY					LOCATION OF RELEASE																												
	<u>Z</u>					<u>Z</u>					<u>N/A</u>					<u>N/A</u>																							
	PERSONNEL EXPOSURES NUMBER					TYPE					DESCRIPTION																												
	<u>0</u> <u>0</u> <u>0</u>					<u>Z</u>					<u>N/A</u>																												
	PERSONNEL INJURIES NUMBER					DESCRIPTION																																	
	<u>0</u> <u>0</u> <u>0</u>					<u>N/A</u>																																	
	LOSS OF OR DAMAGE TO FACILITY TYPE					DESCRIPTION																																	
	<u>Z</u>					<u>N/A</u>																																	
	PUBLICITY ISSUED					DESCRIPTION																																	
	<u>N</u>					<u>N/A</u>																																	

810202 S22