

(1-13)	ENSEE EVENT REPORT
44.	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	I L D R S 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 ELICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
0 1 7 8	REPORT L 6 0 5 0 0 0 2 3 7 7 1 2 1 1 7 7 8 1 2 2 9 7 7 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) During Drywell inerting the nitrogen storage tank level fell below 60 inches contrary
0 3	to T.S.3.7.A.6./b. This is of minimum consequences because the level was raised to
0 4	198" within 3 hrs. This is within the 7 days allowed by Tech Specs. This has hap-
0 5	pened twice before Reportable Occurrence #50-237/76-35 and 73, Docket #050-237.
0 6	
0 7	
0 8	9 7 80
0 9	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBCODE S E 11 X 12 Z 13 Z Z Z Z Z 14 Z 15 Z 16
7 8	9 10 11 12 13 18 19 20 SEQUENTIAL OCCURRENCE REPORT REVISION REPORT NO. CODE TYPE NO.
	17) REPORT 7 7 9 0 7 6 0 3 1 1 0 32 ACTION FUTURE EFFECT SHUTDOWN COMPONENT
	ACTION FUTURE COMP. COMPONENT NORTHON HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER X 18 Z 19 Z 20 Z 21 0 0 0 N 23 N 24 Z 25 Z 9 9 9 9 26 X 33 34 35 36 37 40 41 31 42 43 43 44 47 47 47 47 48 48 48
10	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The nitrogen level was allowed to drop below 60" in order to complete drywell inert-
	ing. Level was restored when nitrogen truck arrived. No further corrective action
1 2	is necessary.
1 3	
1 4	<u></u>
	9 ACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 C 28 0 2 3 29 NA A 31 Operator Observation
A	9 10 12 13 44 45 46 CTIVITY CONTENT LOCATION OF RELEASE 36 LOCATION OF RELEASE 36
1 6 7 8	Z (33) Z (34) NA NA NA NA NA NA NA N
17	NUMBER TYPE DESCRIPTION (39) 0 0 0 37 Z 38 NA
7 8	9 PERSONNEL INJURIES 80 NUMBER DESCRIPTION 41
7 8	0 0 0 0 40 NA 9 11 12 LOSS OF OR DARMET TO FACILITY (43)
1 9	TYPE DESCRIPTION Z 42 NA 9 10 NA
2 0	PUBLICITY SSUED DESCRIPTION 45 NA
7 8	9 10 8/03090639 Pietryga 68 69 265 80 5



REGULATORY DOCKET FILE COPY

December 29, 1977

BBS LTR #1221-77





Reportable Occurrence Report #77-076/03L-0, Docket #050-237 is hereby submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(b), conditions leading to operation in a degraded mode permitted by a limiting condition for operation.

&~B.B. Stephenson Station Superintendent

Dresden Nuclear Power Station

athin M Roberts

BBS:dlz

Enclosure

cc: Director of Inspection & Enforcement

Director of Management Information & Program Control

File/NR6

JAN 4 1978