

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | 1 | 4 | D | R | S | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 1 | 4 | 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

0 1 | L | 0 | 5 | 0 | 0 | 0 | 2 | 3 | 7 | 1 | 1 | 2 | 4 | 7 | 7 | 1 | 2 | 2 | 2 | 7 | 7 | 9  
7 8 REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While performing the Group-2 Isolation Operability Test, A02-1601-63 (Drywell Vent)  
0 3 | twice failed to close when fuses 595-704A & B were pulled. It did close when 595-704  
0 4 | C&D fuses were pulled. This is reportable because the valve is a primary isolation  
0 5 | valve. This is of minimum consequences because the redundant system was available and  
0 6 | operated properly when initiated. The reactor was also in cold shutdown at the time.  
0 7 | This is a non-repetitive event.

0 8 | \_\_\_\_\_ 80

0 9 | S | D | X | Z | V | A | L | V | E | X | B | D  
9 10 11 12 13 18 19 20

17 | 7 | 7 | - | 0 | 6 | 7 | / | 0 | 3 | L | - | 0  
21 22 23 24 26 27 28 29 30 31 32  
18 | Z | Z | Z | Z | 0 | 0 | 0 | 0 | N | Y | N | P | 3 | 4 | 0  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Cause could not be determined. Upon investigation nothing could be found wrong with  
1 1 | the valve or associated electrical equipment. A02-1601-63 functioned correctly on  
1 2 | two successive attempts when fuses 595-704 A&B were pulled. The valve is a 6 inch  
1 3 | Pratt Butterfly vlv. 2 F 11 with 3 1/4" x 10" air cyl. Air tank and controls model #  
1 4 | #MC-103. Min. oper. press. 80 p.s.i. and max. oper. press. 100 p.s.i.

1 5 | H | 0 | 0 | 0 | NA | B | Group 2 Isolation Test  
9 10 12 13 30 44 45 46 47

1 6 | Z | Z | NA | NA  
9 10 11 13 44 45 47

1 7 | 0 | 0 | 0 | Z | NA  
9 11 12 13 44 47

1 8 | 0 | 0 | 0 | NA  
9 11 12 13 44 47

1 9 | Z | NA  
9 10 12 44 47

2 0 | N | NA | \_\_\_\_\_  
9 10 45 68 69 80

8103090654

W. Pietryga




**Commonwealth Edison**  
Dresden Nuclear Power Station  
R.R. #1  
Morris, Illinois 60450  
Telephone 815/942-2920

*O. Lanham*

REGULATORY DOCKET FILE COPY

December 23, 1977

BBS LTR #1211-77



James G. Keppler, Regional Director  
Directorate of Regulatory Operations - Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Reportable Occurrence Report #77-067/03L-0, Docket #050-237 is hereby submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(b), conditions leading to operation in a degraded mode permitted by a limiting condition for operation.

*Arthur M. Roberts*  
for B.B. Stephenson  
Station Superintendent  
Dresden Nuclear Power Station

BBS:diz

Enclosure

cc: Director of Inspection & Enforcement  
Director of Management Information & Program Control  
File/NRC

DEC 28 1977

