

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

PLEASE PRINT ALL REQUIRED INFORMATION

01	LICENSEE NAME ILDRS	LICENSE NUMBER 00-000000-00	LICENSE TYPE 41111	EVENT TYPE 03					
7	8	9	14	15	25	26	30	31	32

01	CATEGORY CONT	REPORT TYPE L	REPORT SOURCE I	DOCKET NUMBER 050-0237	EVENT DATE 053176	REPORT DATE 061676					
7	8	57	58	59	60	61	68	69	74	75	80

EVENT DESCRIPTION

02 LPCI AND CORE SPRAY MONTHLY OPERABILITY CHECKS WERE NOT PERFORMED AS REQUIRED BY
7 8 9 80

03 TECH SPEC SECTIONS 4.5.A.C AND 4.5.A.D DURING THE MONTH FOLLOWING APRIL 23, 1976
7 8 9 80

04 THE SURVEILLANCES WERE COMPLETED ON JUNE 3, 1976; HOWEVER, THIS DATE WAS NOT
7 8 9 80

05 WITHIN THE PERMISSIBLE TECH SPEC TIME LIMIT. THIS EVENT REPRESENTS THE FIRST REPORT-
7 8 9 80

06 AGLE OCCURRENCE RESULTING FROM THE SURVEILLANCE PROGRAM AT DRESDEN. (50-237/1976-39)
7 8 9 80

07	SYSTEM CODE S	CAUSE CODE A	COMPONENT CODE ZZZZZ	PRIME COMPONENT SUPPLIER Z	COMPONENT MANUFACTURER Z999	VIOLATION Y				
7	8	9	10	11	12	17	43	44	47	48

CAUSE DESCRIPTION

08 THE CAUSE OF THE EVENT WAS PERSONNEL ERROR. SUPERVISING PERSONNEL FAILED TO SCHEDULE
7 8 9 80

09 THE SURVEILLANCES DURING THE ALLOTTED TIME PERIOD. THE LPCI SUBSYSTEM WAS OPERATED
7 8 9 80

10 ON SEVERAL OCCASIONS DURING THIS PERIOD, MOST NOTABLY DURING THE AUTOMATIC BLOWDOWN
7 8 9 80

11	FACILITY STATUS E	% POWER 075	OTHER STATUS NA	METHOD OF DISCOVERY D	DISCOVERY DESCRIPTION NA				
7	8	9	10	12	13	44	45	46	80

12	FORM OF ACTIVITY RELEASED Z	CONTENT OF RELEASE Z	AMOUNT OF ACTIVITY NA	LOCATION OF RELEASE NA			
7	8	9	10	11	44	45	80

PERSONNEL EXPOSURES

13	NUMBER 000	TYPE Z	DESCRIPTION NA			
7	8	9	11	12	13	80

PERSONNEL INJURIES

14	NUMBER 000	DESCRIPTION NA			
7	8	9	11	12	80

OFFSITE CONSEQUENCES

15 NA
7 8 9 80

LOSS OR DAMAGE TO FACILITY

16	TYPE Z	DESCRIPTION NA		
7	8	9	10	80

PUBLICITY

17 NA
7 8 9 80

ADDITIONAL FACTORS

18 NA
7 8 9 80

19
7 8 9 80

NAME: R.W. COEN PHONE: EXT. 421

8103100123

CAUSE DESCRIPTION (Continued)



system problem on May 25 (R.O. 50-237/1976-34). At that time, full-flow torus cooling was initiated using 3 LPCI pumps. Although the pumps were indeed operated, the failure to perform formal surveillance testing for the month constitutes a Tech Spec violation.



Commonwealth Edison

Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

Regulatory, Section 1118



BBS Ltr. #464-76

Mr. James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Enclosed please find Reportable Occurrence number 50-237/1976-39,
This report is being submitted to your office in accordance with the
Dresden Nuclear Power Station Technical Specifications, Section 6.6.B.

B. B. Stephenson
Station Superintendent
Dresden Nuclear Power Station

BBS:jo

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
File/NRC

6317