

ATTACHMENT TO LICENSEE EVENT REPORT #79-017-01X3
COMMONWEALTH EDISON COMPANY (CWE)
DRESDEN UNIT 2
DOCKET # 050-237

Measured leakage of volume bounded by containment isolation valves AO-2-1601-23, 24, 60, 61, 62 & 63 was 1660 SCFH. This exceeds the T.S. limits for single containment isolation valve allowable leakage, total for testable penetrations and isolations valves and maximum allowable containment leak rate. The leakage was into the secondary containment and the Standby Gas System which resulted in no danger to public health and safety. Similar events were reported by 50-237/76-10, 50-249/76-16 and 50-249/80-07.

Leakage was initially identified to be from the shaft seals on AO-2-1601-60. Subsequent testing indicated leakage on the 1601-23 and 1601-24 valve shaft seals and seat leakage on valve 1601-24. The 1601-24 valve was replaced and shaft seals on valves 1601-23 and 1601-60 were repaired. No further action deemed necessary.

SUPPLEMENT TO DVR

DVR NO.
STA UNIT, YEAR NO.
D - 12 - 2 - 79 - 25

PART 1	TITLE OF EVENT	OCCURRED	
	Containment Vent Line Excessive Leakage	<u>03/27/79</u>	<u>0530</u>
		DATE	TIME
REASON FOR SUPPLEMENTAL REPORT			
Correct error in type of reportable occurrence indicated in transmittal			
letter dated October 23, 1978.			
PART 2			
ACCEPTANCE BY STATION REVIEW	<u>J. Brunner</u>	<u>John W. Wojcik</u>	_____
DATE	<u>3/2/81</u>	<u>3/7/81</u>	_____
SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION	<u>Douglas Scott</u>		<u>3/9/81</u>
	STATION SUPERINTENDENT		DATE