**OELD** R. Bevan ACRS(10) P. O'Connor

D. Eisenhut D. Verrelli J. Hegner B. Siegel Gray

DEC 2 2 1981 ►

US NUCLEAR REGULATORY COMMISSI DOCUMENT MANAGEMENT BR

TIDE

Docket Nos. 50-237/249 50-254/265

DEC 15 1981

Mr. L. DelGeorge Director of Nuclear Licensing Commonwealth Edison Company P. 0. Box 767 Chicago, Illinois 60690

Dear Mr. DelGeorge:

Subject: NUREG-0737, Item II.K.3.44 - Evaluation of Anticipated

Transients Combined with Single Failure

Re: Dresden Station Units 2 and 3, and Quad Cities Units 1 and 2

You endorsed the BWR Owners Group position regarding NUREG-0737, Item II.K.3.44 - Evaluation of Anticipated Transients Combined with Single Failure, in your letter dated December 15, 1980. As identified in Generic Letter No. 81-32, dated August 7, 1981, the staff has completed its review of the BWR Owners Group Report dated December 29, 1980 pertaining to this item. Enclosed is a copy of the staff's evaluation of the BWR Owners Group response to this item which was found to be acceptable on a generic basis.

Generic Letter No. 81-32 also requested that you provide verification that the assumptions and initial conditions used in the generic analyses are representative for your plants. Since your response dated October 22, 1981 provided this assurance, we consider Item II.K.3.44 complete for Dresden Station Units 2 and 3, and Quad Cities Units 1 and 2.

> Original Signed by L. J. A. Ippolito Thomas A. Ippolito, Chief Operating Reactors Branch #2 Division of Licensing

Enclosure: As stated

cc w/enclosures

8201210057

See next page

·I&E('3) ~

Distribution: \*\* Docket File J. Heltemes, AEOD T NRC PDR NSTC OFFICE SNorris SURNAME /81 DATE

Isham, Lincoln & Beale Counselors at Law One First National Plaza, 42nd Floor Chicago, Illinois 60603

Mr. B. B. Stephenson
Plant Superintendent
Dresden Nuclear Power Station
Rural Route #1
Morris, Illinois 60450

Dr. Richard F. Foster P.O. Box 4263 Sunriver, Oregon 97701

U. S. Nuclear Regulatory Commission Resident Inspectors Office Dresden Station RR #1 Morris, Illinois 60450

Mary Jo Murray Assistant Attorney General Environmental Control Division 188 W. Randolph Street Suite 2315 Chicago, Illinois 60601

Morris Public Library 604 Liberty Street Morris, Illinois 60451

Chairman
Board of Supervisors of
Grundy County
Grundy County Courthouse
Morris, Illinois 60450

John F. Wolf, Esquire 3409 Shepherd Street Chevy Chase, Maryland 20015

Dr. Linda W. Little 500 Hermitage Drive Raleigh, North Carolina 27612 Illinois Department of Nuclear Safety 1035 Outer Park Drive, 5th Floor Springfield, Illinois 62704

U. S. Environmental Protection Agency Federal Activities Branch Region V Office ATTN: Regional Radiation Representative 230 South Dearborn Street Chicago, Illinois 60604

Dr. Forrest J. Remick 305 East Hamilton Avenue State College, Pennsylvania 16801

The Honorable Tom Corcoran
United States House of Representatives
Washington, D. C. 20515

Mr. Philip Steptoe Isham, Lincoln & Beale Counselors at Law One First National Plaza, 42nd Floor Chicago, Illinois 60603

Mr. Douglas Scott-Plant Superintendent Dresden Nuclear Power Station Rural Route #1 Morris, Illinois 60450

Mr. D. R. Stichnoth President Iowa-Illinois Gas and Electric Company 206 East Second Avenue Davenport, Iowa 52801

Mr. Nick Kalivianakas Plant Superintendent Quad Cities Nuclear Power Station 22710 - 206th Avenue North Cordova, Illinois 61242

Moline Public Library 504 - 17th Street Moline, Illinois 61265 cc:

Susan N. Sekuler Assistant Attorney General Environmental Control Division 188 W. Randolph Street Suite 2315 Chicago, Illinois 60601

Resident Inspector
U.S. Nuclear Regulatory Commission
22712 206th Avenue N.
Cordova, Illinois 61242

James L. Kelley, Chairman Atomic Safety & Licensing Board Panel U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Dr. Peter A. Morris Atomic Safety & Licensing Board Panel U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Enclosure

Evaluation of BWR Owners Group Generic

Response to Item II.K.3.44 of NUREG-0737,

Evaluation of Anticipated Transients With

Single Failure to Verify no Fuel Failure"

## Position

For anticipated transients combined with the worst single failure and assuming proper operator actions, licensees should demonstrate that the core remains covered or provide analysis to show that no significant fuel damage results from core uncovery. Transients which result in a stuck-open relief valve should be included in this category.

## Summary and Staff Evaluation

The intent of this requirement was to demonstrate that for a transient which could result in a stuck open relief valve (e.g., an isolation event which heads to a relief valve cycling and then sticking open), in combination with the worst single failure, the core either remains covered with water or experiences only moderate fuel damage as a result of the uncovery of fuel. There was no intent to determine how many rods might experience boiling transition as a result of the event. The area of boiling transition following transients combined with a single failure is considered in Chapter 15.0 of the Standard Review Plan as part of the normal licensing review.

The BWR Owners Group generic response to this item is given in a letter to Darrell G. Eisenhut (NRC) from D. B. Waters (BWR Owners Group), BWROG-80-12, "BWR Owners Group Evaluation of NUREG-0737 Requirements", December 29,1980. The Owners Group found that the most severe transient from the core cooling viewpoint is the loss of feedwater event; this is due to the rapid depletion of reactor coolant inventory. The worst single active component failure for the loss of feedwater transient is

failure of the high pressure coolant injection system because the high pressure coolant injection system is the largest capacity make-up (other than feedwater) available at high pressure.

For the case of loss of feedwater, failure of the high pressure injection system and one stuck open relief valve, analyses presented in Figures 3.2.1.1.5-9.4, and 3.2.1.1.5-10.4 of NEDO-24708A shown that for the plants analyzed, the reactor core isolation cooling (RCIC) system can automatically provide sufficient inventory to keep the core covered. The analyses were performed for a typical BWR/4 and a typical BWR/5 plant. This capability is not a design basis for the RCIC system, and not all plants have been analyzed to demonstrate this capability. If a plant should not have the capability, manual depressurization using the automatic depressurization system (ADS) would be used to avoid core uncovery. Manual depressurization is the proper operation action for all plants during loss of inventory conditions when the high pressure systems are unable to maintain and restore reactor vessel water level.

No analyses were presented for the specific case of loss of feedwater, loss of high pressure coolant injection and a stuck open relief valve with ADS actuation at the normal ADS level (level 1). Figures 3.2.1.1.5-25.4 and 3.2.1.1.5.-26.4 of NEDO-24708A shown that manual actuation of the ADS when the water level is 5 feet above the top of th active fuel (270 seconds for the BWR/4 and 300 seconds for the BWR/5) prevents fuel uncovery for the extreme case of loss of feedwater, loss of high pressure injection, loss of RCIC and a stuck open relief valve. Figure 3.1.1.1-51.2 of NEDO-24708A shows only a brief uncovery of the top 1 foot of fuel for an ADS blowdown (ADS initiated at level 1, approximately 2 feet above top of active fuel) with no high pressure systems lavailable for a BWR/4-218 plant.

Test results from the two loop test apparatus (TLTA) show that fluid mixture levels in the core region are underpredicted for an ADS blowdown. In a monthly progess report, letter to Edward Halman (NRC) and P. Kalra (EPRI) from G. W. Burnetle (GE),

"BWR Blowdown/ECC Program, Contract no. NRC-04-76-215, Informal Monthly Progess
Report for April 1980", May 12,1980, General Electric states," The results indicate
The bundle was covered with two-phases mixture for the entire transient, while a
two-phases mixture level was seen in the lower plenum and bypass after the ADS
initiation at 286 seconds. The fast system depressurization due to the activation
of ADS resulted in flashing and high vapor generation which led to the occurrence
of the counter current flow limiting (CCFL) at the side entry orifice (SEO). This
CCFL phenomenon at SEO prevents the bundle mass inventory from draining into the
lower plenum and hence maintains a low void fraction mixture with nucleate boiling
throughout the fuel bundle during the entire transient". Because the SAFE code, which
GE uses to predict the level transient, does not include the effect of CCFL at the
side entry orifice, the model underpredicts the mixture level in/above the core.

Since the calculations show that the core does not uncover for the worst transient combined with the worst single failure and a stuck open relief valve; and since test data from TLTA show the calculations to be conservative for an ADS blowdown, we find the generic responses of the BWR Owners Group to be acceptable. Individual licensees/applicants who reference the generic response to item II.K.3.44 must verify that the assumption's and initial conditions used in the analyses are applicable or are bounding for their specific plants.