



Commonwealth Edison
 One First National Plaza, Chicago, Illinois
 Address Reply to: Post Office Box 767
 Chicago, Illinois 60690

November 16, 1981

Mr. James G. Keppler, Director
 Directorate of Inspection and
 Enforcement - Region III
 U.S. Nuclear Regulatory Commission
 799 Roosevelt Road
 Glen Ellyn, IL 60137

TE HQ FILE COPY

Subject: Dresden Station Units 1, 2 and 3
 Response to Inspection Report
 Nos. 50-10/81-12, 50-237/81-24
 and 50-249/81-18
NRC Docket Nos: 50-10/237/249

Reference (a): R. C. Spessard letter to Cordell
 Reed dated October 15, 1981.

Dear Mr. Keppler:

The following is provided in response to the Subject inspection conducted on August 1 through September 4, 1981 by Messrs. T. M. Tongue and M. J. Jordan of activities at Dresden Nuclear Power Station Units 1, 2 and 3. Reference (a) identified one item of noncompliance. The attachment to this letter contains the Commonwealth Edison Company response to this item.

To the best of my knowledge and belief the statements contained herein and in the attachment are true and correct. In some respects these statements are not based upon my personal knowledge but upon information furnished by other Commonwealth Edison employees. Such information has been reviewed in accordance with Company practice and I believe it to be reliable.

Please address any questions you may have concerning this matter to this office.

Very truly yours,

Thomas J. Rausch
 Thomas J. Rausch
 Nuclear Licensing Administrator
 Boiling Water Reactors

SUBSCRIBED AND SWORN to
 before me this 16th day
 of November, 1981.

Rosalie A. Pienta
 Notary Public

Region III Inspector - Dresden

8201260361 820119
 PDR ADOCK 05000237
 PDR

2881N

NOV 19 1981

ATTACHMENT

COMMONWEALTH EDISON COMPANY

Response to Notice of Violation

Technical Specification 6.2.A required in part, detailed written procedures including applicable checkoff lists. . . shall be prepared, approved and adhered to for prevention and corrective maintenance operations which could have an effect on the safety of the facility.

Contrary to the above, during the Unit 2 refueling outage in January 1981, the 2-2301-3 valve (HPCI Turbine Steam Supply) was disassembled and rebuilt by maintenance personnel without an appropriate procedure or reference information. This resulted in the valve disc being reinstalled improperly, which prevented condensate drainage from the steamline resulting in the HPCI system being inoperable. This condition existed for several weeks of reactor operation until it was discovered, reported and corrected by the licensee on May 26, 1981.

Corrective Actions Taken and Results Achieved

When the condition was discovered, a Work Request was immediately written, and the 2-2301-3 valve disassembled so that the valve disc could be installed in the proper orientation. This corrective action was completed on May 29, 1981.

Corrective Actions Taken to Avoid Further Non-Compliance

To avoid further non-compliance when performing maintenance activities on the 2301-3 valve (HPCI turbine steam supply), a work manual has been written to carefully describe the proper method of installing the valve disc.

Date For Full Compliance

The work manual has been written and is available for further maintenance activities. Therefore, we believe full compliance has been achieved.