



**Commonwealth Edison**  
 One First National Plaza, Chicago, Illinois  
 Address Reply to: Post Office Box 767  
 Chicago, Illinois 60690

**Regulatory Docket File**

BBS Ltr. #626-75

Dresden Nuclear Power Station  
 R. R. #1  
 Morris, Illinois 60450  
 September 22, 1975

Mr. James G. Keppler, Regional Director  
 Directorate of Regulatory Operations-Region III  
 U. S. Nuclear Regulatory Commission  
 799 Roosevelt Road  
 Glen Ellyn, Illinois 60137



**SUBJECT: SUPPLEMENT TO REPORT OF ABNORMAL OCCURRENCE PER SECTION 6.6.A OF THE TECHNICAL SPECIFICATIONS EXCESSIVE LEAKAGE PAST REACTOR BUILDING TO TORUS VACUUM BREAKER 2-1601-31A**

Report Number 50-237/1974-31


In a letter to Mr. J. F. O'Leary, dated August 2, 1974, concerning the subject occurrence, the corrective action described was to modify the valve to minimize binding in the valve disc to disc arm joint.

After further examination, evaluation and surveillance testing, it has been determined that the modification is unnecessary. The reactor building to torus vacuum breaker valves are not identical to the torus to drywell vacuum breakers and no significant corrosion was detected when the valve was disassembled and examined. On the basis of this examination and other modifications to increase the closing force, the modification of the disc to disc arm connection has been reevaluated. Continued surveillance testing of these particular valves has shown no recurrence of improper seating of the valve. For the above reasons the modification to the disc to disc arm joint on valves 2-1601-31A & B is not necessary and will be canceled.

*B. B. Stephenson*  
 B. B. Stephenson  
 Superintendent

BBS:JSA:smp

File/NRC



SEP 26 1975

10305