

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Dresden Nuclear Power Station, Unit 3	DOCKET NUMBER (2) 0 5 0 0 0 2 4 9	PAGE (3) 1 OF 04
--	--------------------------------------	---------------------

TITLE (4)
Manual Reactor Scram Due to High Condensate Temperature and Main Condenser Low Vacuum Caused by Broken Turbine Bearing Water and Oil Drain

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		
04	09	87	87	010	00	05	01	87	N/A		
									DOCKET NUMBER(S) 0 5 0 0 0		

OPERATING MODE (9) N	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)									
POWER LEVEL (10) 0 4 3	20.402(b)	<input checked="" type="checkbox"/>	88.736(c)(2)(iv)	<input type="checkbox"/>	73.71(b)	<input type="checkbox"/>				
	20.408(a)(1)(i)	<input type="checkbox"/>	88.736(c)(2)(v)	<input type="checkbox"/>	73.71(a)	<input type="checkbox"/>				
	20.408(a)(1)(ii)	<input type="checkbox"/>	88.736(c)(2)(vi)	<input type="checkbox"/>	OTHER (Specify in Abstract below and in Text, NRC Form 388A)					
	20.408(a)(1)(iii)	<input type="checkbox"/>	88.736(c)(2)(vii)(A)	<input type="checkbox"/>						
	20.408(a)(1)(iv)	<input type="checkbox"/>	88.736(c)(2)(vii)(B)	<input type="checkbox"/>						
	20.408(a)(1)(v)	<input type="checkbox"/>	88.736(c)(2)(viii)	<input type="checkbox"/>						

LICENSEE CONTACT FOR THIS LER (12)		TELEPHONE NUMBER	
NAME Michael E. Moy Technical Staff Engineer (X-489)	AREA CODE 8 1 5	9 4 2 -	2 9 2 0

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)											
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	
X	S D	D R N	X X X X	N		X	S G	X X X X	X X X X	Y	
X	S H	D R N	X X X X	N							

SUPPLEMENTAL REPORT EXPECTED (14) <input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
--	-------------------------------	-------	-----	------

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On April 9, 1987 at 2335 hours with Unit 3 in the run mode at approximately 43% rated thermal power, the reactor was manually scrambled due to high condensate demineralizer inlet temperature of 130°F and main condenser low vacuum decreasing to the scram setpoint of 23 inches of mercury.

The root cause of the event was component failure. The "C" low pressure turbine bearing cone waste water and oil drain to the Turbine Building equipment sump was determined to have broken inside the condenser.

The safety significance of the event was minimal since the Reactor Operators and Shift Supervisors controlled the plant in a conservative condition in accordance with approved procedures for loss of condenser vacuum.

Corrective actions were to cut the turbine bearing cone drains and install plugs at the inlet and outlet for each low pressure turbine bearing cone. Repairs were completed under Work Request D64292.

A similar previous event was reported by Licensee Event Report #87-16 on Docket #050237.

8705120268 870501
PDR ADDOCK 05000249
S PDR

IE 2 2
11

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Dresden Nuclear Power Station, Unit 3	DOCKET NUMBER (2) 05000249	LER NUMBER (6)			PAGE (3)		
		YEAR 87	SEQUENTIAL NUMBER -010	REVISION NUMBER -00			

TEXT (If more space is required, use additional NRC Form 388A's) (17)

The root cause of this event was component failure. The "C" low pressure turbine bearing cone waste water and oil drain piping [TF] to the Turbine Building equipment sump [WK], which is routed through the main condenser [SG], was determined to have broken. This drain piping [TF], which normally is at Turbine Building [NM] ambient pressure, was discovered to be under vacuum. This indicated that it had broken inside the main condenser [SG], resulting in air inleakage at the bearing collection and sump [WK] ends of the drain piping [TF].

D. SAFETY ANALYSIS OF THE EVENT:

An increased off-gas flow had been observed since startup of Unit 3 from a scram which occurred on March 21, 1987. Visual inspections and checks performed by Technical Staff personnel using inleakage detection equipment were unsuccessful in pinpointing the inleakage source. On April 9, 1987, the inleakage increased sharply. The Reactor Operators and Shift Supervisors promptly responded to this event in accordance with Dresden Operating Abnormal Procedure (DOA) 3300-2, "Loss of Condenser Vacuum". Due to the rapid vacuum loss, the Shift Supervisor ordered that a manual scram be performed. A comprehensive leakage detection effort was then initiated to find any sources of inleakage and repairs were performed prior to startup. For these reasons, the safety significance of this event was minimal.

E. CORRECTIVE ACTIONS:

Repairs to the "C" low pressure turbine bearing cone drain were completed under Work Request #D64292 on April 23, 1987 at approximately 1000 hours. In addition to the "C" drain, the drains for each low pressure turbine bearing cone (3 total) were cut and plugged at the inlet and outlet with expandable plugs. Allowing the drains to remain plugged during power operation does not degrade system operation since the drains were associated with the turbine bearing fire deluge system which was removed from both Units 2 and 3 under modification 12-2(3)-82-1. These repairs, while performed under the work request, were considered a temporary system alteration and authorized in accordance with Dresden Administrative Procedure (DAP) 7-4, "Control of Temporary System Alterations". Work Request Numbers D64483 and D64535 (Unit 2 and Unit 3 respectively) were written requesting initiation of permanent corrective actions to prevent recurrence of this event.

F. PREVIOUS EVENTS:

<u>LER Number/Docket</u>	<u>Title</u>
86-16/50-237	Reactor Scram on Low Condenser Vacuum Due to Disconnected Drain Pipe Union.

Corrective actions were to reconnect the disconnected drain pipe union.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Dresden Nuclear Power Station, Unit 3	DOCKET NUMBER (2) 305000249	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		87	010	00	04	OF 04

TEXT (If more space is required, use additional NRC Form 388A's) (17)

G. COMPONENT FAILURE DATA:

Manufacturer: N/A

Nomenclature: Turbine bearing waste water and oil drain

Model Number: N/A

Mfg. Part Number: N/A

This component failure in itself is not reportable according to industry NPRDS guidelines, however, the loss of main condenser vacuum is being reported on the NPRDS system data base. No similar events were listed in the NPRDS data base.



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

May 1, 1987

EDE LTR #87-288

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Licensee Event Report #87-010-0, Docket #050249 is being submitted as required by Technical Specification 6.6, NUREG 1022 and 10 CFR 50.73 (a)(2)(iv).

E.D. Eenigenburg
Station Manager
Dresden Nuclear Power Station

EDE/kjl

Enclosure

cc: A. Bert Davis, Regional Administrator, Region III
File/NRC
File/Numerical

IE 22
1/1