

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8712310052 DOC. DATE: 87/12/21 NOTARIZED: NO DOCKET #
 FACIL: 50-389 St. Lucie Plant, Unit 2, Florida Power & Light Co. 05000389
 AUTH. NAME AUTHOR AFFILIATION
 JOHNSON, A.B. Florida Power & Light Co.
 WOODY, C.O. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 87-007-00: on 871125, reactor trip on loss of load caused by main generator exciter bearing failure.

W/8 ltr.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 5
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	
	PD2-2 IA	1 1	PD2-2 PD	1 1	
	TOURIGNY, E	1 1			
INTERNAL:	ACRS MICHELSON	1 1	ACRS MOELLER	2 2	
	AEOD/DOA	1 1	AEOD/DSP/NAS	1 1	
	AEOD/DSP/ROAB	2 2	AEOD/DSP/TPAB	1 1	
	ARM/DCTS/DAB	1 1	DEDRO	1 1	
	NRR/DEST/ADS	1 0	NRR/DEST/CEB	1 1	
	NRR/DEST/ELB	1 1	NRR/DEST/ICSB	1 1	
	NRR/DEST/MEB	1 1	NRR/DEST/MTB	1 1	
	NRR/DEST/PSB	1 1	NRR/DEST/RSB	1 1	
	NRR/DEST/SGB	1 1	NRR/DLPQ/HFB	1 1	
	NRR/DLPQ/QAB	1 1	NRR/DOEA/EAB	1 1	
	NRR/DREP/RAB	1 1	NRR/DREP/RPB	2 2	
	NRR/DRIS/SIB	1 1	NRR/PMAS/ILRB	1 1	
	REG-FILE 02	1 1	RES DEPY GI	1 1	
	RES TELFORD, J	1 1	RES/DE/EIB	1 1	
	RGN2 FILE 01	1 1			
EXTERNAL:	EG&G GROH, M	5 5	FORD BLDG HOY, A	1 1	
	H ST LOBBY WARD	1 1	LPDR	1 1	
	NRC PDR	1 1	NSIC HARRIS, J	1 1	
	NSIC MAYS, G	1 1			

TOTAL NUMBER OF COPIES REQUIRED: LTR 46 ENCL 45

R
I
D
S
/
A
D
S
/
A
D
D
S

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) St. Lucie, Unit 2						DOCKET NUMBER (2) 0 5 0 0 0 3 8 9			PAGE (3) 1 OF 0 4		
--	--	--	--	--	--	--------------------------------------	--	--	----------------------	--	--

TITLE (4) REACTOR TRIP ON LOSS OF LOAD CAUSED BY MAIN GENERATOR EXCITER BEARING FAILURE DUE TO PERSONNEL ERROR

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
1	1	2 5 8 7	8 7	0 0 7	0 0	1	2 2 1	8 7	N/A		0 5 0 0 0

OPERATING MODE (9) 1	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																							
POWER LEVEL (10) 0 5 0	20.402(b)	20.405(a)(1)(i)	20.405(a)(1)(ii)	20.405(a)(1)(iii)	20.405(a)(1)(iv)	20.405(a)(1)(v)	20.406(c)	50.38(c)(1)	50.38(c)(2)	50.73(a)(2)(i)	50.73(a)(2)(ii)	50.73(a)(2)(iii)	50.73(a)(2)(iv)	50.73(a)(2)(v)	50.73(a)(2)(vi)	50.73(a)(2)(vii)	50.73(a)(2)(viii)(A)	50.73(a)(2)(viii)(B)	50.73(a)(2)(ix)	73.71(b)	73.71(c)	OTHER (Specify in Abstract below and in Text, NRC Form 365A)		

LICENSEE CONTACT FOR THIS LER (12)

NAME A. B. Johnson, Shift Tech. Advisor		TELEPHONE NUMBER AREA CODE 3 0 5 4 6 5 1 - 3 1 5 1 0	
--	--	--	--

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
A	T B	E X C	W 1 2 0	N					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)	<input checked="" type="checkbox"/> NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
---	--	-------------------------------	-------	-----	------

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 25 November 1987, St. Lucie Unit Two was operating at 50 percent power steady state in Mode 1. At 2331 hours, the reactor tripped on loss of load due to a turbine trip. The turbine tripped on a main generator lockout. The failure of the main generator exciter bearing caused the armature of the Permanent Magnet Generator (PMG) to grind into its stator. When this occurred, the PMG discontinued supplying voltage to the exciter of the main generator. The trip was uncomplicated and the unit was quickly stabilized in Mode 3, Hot Standby.

The root cause of the event was a personnel error during the performance of the weekly generator exciter ground check on which a prolonged ground resulted in the failure of the generator exciter bearing.

The following corrective actions have been implemented: replaced the PMG and the exciter bearing, removed the exciter bearing thermocouple to prevent future grounding occurrence of this type, procedures have been revised to ensure any future grounds are recognized, and training was given to all Electrical Maintenance personnel for better understanding of the exciter ground check.

8712310052 871221
PDR ADOCK 05000389
S DCD

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) St. Lucie, Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 3 8 9 8 7	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
			0 0 7	0 0	0 2	OF

TEXT (If more space is required, use additional NRC Form 366A's) (17)

DESCRIPTION OF EVENT:

On 25 November, 1987, St. Lucie Unit Two was operating at 50 percent power steady state in Mode 1. The unit was returned to service on 23 November following a refueling outage and was holding at 50 percent power while repairs were in progress on the 2A Steam Generator Feed Pump (SGFP) (EIIS:SJ) due to a small water leak that developed on the vent line at the pump casing. The reactor was being maintained in a steady state condition with all automatic controllers placed in automatic with the exception of the Control Rod Drive System (EIIS:JD) which was in OFF.

At 2331 hours, the Reactor Protective System (EIIS:JC) initiated a reactor trip on loss of load due to a turbine trip. The turbine tripped on a main generator (EIIS:TB) lockout. The control room was alerted with information that smoke was seen coming out of the Main Generator Exciter (EIIS:TL). The Assistant Nuclear Plant Supervisor (ANPS) instructed the Turbine Operator (TO) to check for rubs on the rotating components of the turbine-generator. The TO reported evidence of turbine-generator rubs to the control room and the ANPS instructed the Reactor Control Room Operators (RCOs) to open the vacuum breakers on the main condenser (EIIS:SG) to aid in slowing down the turbine. A fire team was assembled and stationed with fire fighting equipment at the vicinity of the main generator exciter. There were no reports of an actual fire.

The trip was an uncomplicated trip and all systems functioned normally. The Steam Bypass Control System (SBCS) (EIIS:JI) operated to reduce primary average temperature (T-avg) to the zero percent power setpoint of 532 degrees F. Auxiliary feedwater (EIIS:BA) was initiated manually to control the steam generator (S/G) level for Reactor Coolant System (RCS) (EIIS:AB) heat removal. The standard post trip actions were completed and the unit was immediately stabilized in Hot Standby, Mode 3.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) St. Lucie, Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 3 8 9 8 7	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8 7	0 0 7	0 0	0 3	OF 0 4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

CAUSE OF THE EVENT:

The immediate cause of the main generator lockout was loss of the generator field. The loss of field was caused by destruction of the exciter Permanent Magnet Generator (PMG) that occurred when the exciter bearing failed allowing the PMG armature to rub on the PMG stator.

Further investigation into the failure of the exciter bearing indicated that a ground was caused by a completed electrical circuit between the exciter bearing and the exciter base. This completed electrical circuit bypassed the insulation between the bearing pedestal and the exciter base. The ground was caused by an improper installation of an instrument cable (EIIS:IT). The instrument cable provides the terminal connection from the thermocouple of the #9 exciter bearing housing to its terminal box, which provides remote temperature indication in the control room. The as-found condition of the instrument cable indicated that the braided wire cable shield was not properly positioned in the clamp; therefore, a ground developed at the exciter bearing. Examination of the exciter bearing revealed pitting marks on the bearing surface, characteristic of current flowing across the bearing journal to the bearing pad, which resulted in the bearing failure.

The improper arrangement of the instrument cable cannot be conclusively identified as a wiring error during the installation of the new main generator exciter. The PMG and the instrument cable were meggered to detect for possible grounds and the results were acceptable. It has been postulated that one of two circumstances may have occurred: 1) the instrument cable was installed correctly with the braided wire shield in the clamp when it was meggered; then at some later date, the instrument cable was accidentally stepped on causing the cable shield to become separated from the clamp; or 2) the instrument cable, being clamped incorrectly to the pedestal, had not yet been connected to the terminal box when the megger test was performed.

After placing the main generator back in service, the ground should have been detected during the performance of the weekly generator exciter ground check. The preventative maintenance Plant Work Order (PWO) requires voltages to be read across the #9 bearing shaft to ground and across the #9 bearing pedestal to ground. The data is to be evaluated to ensure no grounds have developed in the main generator exciter. Early recognition of the ground would have prompted immediate action to remove the main generator from service for the necessary repairs.

The root cause of the event was a cognitive personnel error by a utility maintenance supervisor in misinterpretation of the main generator exciter ground voltage readings. The appropriate procedure was properly followed. However, lack of understanding of the significance of the generator exciter ground check and inadequate acceptance criteria in the PWO were contributing factors in the personnel error. There were no unusual characteristics of the work location that directly contributed to the personnel error.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) St. Lucie, Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 3 8 9	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 7	- 0 0 7	- 0 0	0 4	OF	0 4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

ANALYSIS OF THE EVENT:

The event is reportable under 10 CFR 50.73 (a)(2)(iv), "any event or condition that resulted in manual or automatic actuation of any Engineered Safety Feature, including the Reactor Protection System."

This event was observed to be a routine reactor trip on loss of load. The resulting transient was well enveloped by the St. Lucie Unit #2 Final Updated Safety Analysis Report section 15.2.1.2 "Limiting Reactor Coolant System Pressure Event-Isolation of Turbine (100% power)." All Plant Safety Functions were met and there were no additional complications. Consequently, the health and safety of the public were not affected by this event.

CORRECTIVE ACTIONS:

1. The Permanent Magnet Generator was replaced.
2. The Exciter Bearing was replaced.
3. An evaluation was made and the Exciter Bearing thermocouple was determined to be unnecessary and it was removed to prevent future incidents of this type.
4. The preventative maintenance plant work order was revised to adequately define the acceptance criteria and the proper actions when the acceptance criteria are not met.
5. Training was given to all Electrical Maintenance personnel to elaborate on the importance of properly evaluating the data during performance of the weekly generator exciter ground check.
6. The plant training group will evaluate this item to determine appropriate training requirements and methods.

AFL

DECEMBER 21 1987

L-87-528
10 CFR 50.73

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555

Gentlemen:

Re: St. Lucie Unit 2
Docket No. 50-389
Reportable Event: 87-07
Date of Event: November 25, 1987
Reactor Trip on Loss of Load Caused by Main
Generator Exciter Bearing Failure due to Personnel Error

The attached Licensee Event Report (LER) is being submitted pursuant to the requirements of 10 CFR 50.73a to provide notification on the subject event.

Very truly yours,

C. O. Woody
For C. O. Woody
Executive Vice President

COW/GRM/cn:M/011
Attachment

cc: Dr. J. Nelson Grace, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, St. Lucie Plant

IB22
11