

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9012170237      DOC. DATE: 90/12/10      NOTARIZED: NO      DOCKET #  
 FACIL: 50-389 St. Lucie Plant, Unit 2, Florida Power & Light Co.      05000389  
 AUTH. NAME      AUTHOR AFFILIATION  
 WOLAVER, M.W.      Florida Power & Light Co.  
 SAGER, D.A.      Florida Power & Light Co.  
 RECIPIENT NAME      RECIPIENT AFFILIATION

SUBJECT: LER 90-004-00: on 901109, inadvertent actuation of assorted engineered safeguards equipment, including emergency diesel generator 2A, occurred. Caused by personnel error. Personnel counseled. W/901210 ltr.

DISTRIBUTION CODE: IE22T      COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 4  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 1	PD2-2 PD	1 1
	NORRIS, J	1 1		
INTERNAL:	ACNW	2 2	ACRS	2 2
	AEOD/DOA	1 1	AEOD/DSP/TPAB	1 1
	AEOD/ROAB/DSP	2 2	NRR/DET/ECMB 9H	1 1
	NRR/DET/EMEB 7E	1 1	NRR/DLPQ/LHFB11	1 1
	NRR/DLPQ/LPEB10	1 1	NRR/DOEA/OEAB	1 1
	NRR/DREP/PRPB11	2 2	NRR/DST/SELB 8D	1 1
	NRR/DST/SICB 7E	1 1	NRR/DST/SPLB8D1	1 1
	NRR/DST/SRXB 8E	1 1	<u>REG FILE</u> 02	1 1
	RES/DSIR/EIB	1 1	RGN2 FILE 01	1 1
EXTERNAL:	EG&G BRYCE, J.H	3 3	L ST LOBBY WARD	1 1
	NRC PDR	1 1	NSIC MAYS, G	1 1
	NSIC MURPHY, G.A	1 1	NUDOCS FULL TXT	1 1


NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED  
 TOTAL NUMBER OF COPIES REQUIRED: LTR 33 ENCL 33

*Alo-y  
 cur*

R  
I  
D  
S  
/  
A  
D  
D  
S  
/  
A  
D  
D  
S





P.O. Box 14000, Juno Beach, FL 33408-0420

December 10, 1990

L-90-428  
10 CFR 50.73


U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D. C. 20555

Gentlemen:

Re: St. Lucie Unit 2  
Docket No. 50-389  
Reportable Event: 90-04  
Date of Event: November 9, 1990  
Inadvertent Actuation of Engineered Safeguards Equipment  
During Time Response Testing Due to Personnel Error

The attached Licensee Event Report is being submitted pursuant to the requirements of 10 CFR 50.73 to provide notification of the subject event.

Very truly yours,

  
D. A. Sager  
Vice President  
St. Lucie Plant

DAS:GRM:kw

Attachment

cc: Stewart D. Ebnetter, Regional Administrator, USNRC Region II  
Senior Resident Inspector, USNRC, St. Lucie Plant

DAS/PSL #297

9012170237 901210  
PDR ADCK 05000389  
S PDR

an FPL Group company

1/1  
IE 20

# LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) <p style="text-align: center;">St. Lucie Unit 2</p>	DOCKET NUMBER (2) <p style="text-align: center;">0   5   0   0   0   3   8   9</p>	PAGE (3) <p style="text-align: center;">1   OF   0   3</p>
--	---	---

TITLE (4) **INADVERTENT ACTUATION OF ENGINEERED SAFEGUARDS EQUIPMENT DURING TIME RESPONSE TESTING DUE TO PERSONNEL ERROR**

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
1	1	09	9	0	0	1	2	10	N/A		0   5   0   0   0   3   8   9

OPERATING MODE (9)	5	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR : (Check one or more of the following) (11)									
POWER LEVEL (10)	0   0   0	20.402(b)		20.405(c)	X	50.73(a)(2)(iv)		73.71(b)	OTHER (Specify in Abstract below and in Text NRC Form 366A)		
		20.405(a)(1)(i)		50.36(c)(1)		50.73(a)(2)(v)		73.71(c)			
		20.405(a)(1)(ii)		50.36(c)(2)		50.73(a)(2)(vii)					
		20.405(a)(1)(iii)		50.73(a)(2)(i)		50.73(a)(2)(viii)(A)					
		20.405(a)(1)(iv)		50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)					
		20.405(a)(1)(v)		50.73(a)(2)(iii)		50.73(a)(2)(x)					

**LICENSEE CONTACT FOR THIS LER (12)**

NAME <p style="text-align: center;">M. W. Wolaver, Shift Technical Advisor</p>	TELEPHONE NUMBER
	AREA CODE
	4   0   7   4   6   5   -   3   5   5   0

**COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)**

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

**SUPPLEMENTAL REPORT EXPECTED (14)**

<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)	<input checked="" type="checkbox"/> NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

**ABSTRACT (Limit to 1400 spaces. i.e. approximately fifteen single-space typewritten lines)(16)**

On November 9, with Unit 2 in Mode 5 during a refueling outage, an inadvertent actuation of assorted Engineered Safeguards equipment, including the 2A Emergency Diesel Generator, occurred during Engineered Safeguards Features testing. This equipment belongs specifically to the 'A' side Safety Injection Actuation System/Containment Isolation Actuation System (SIAS/CIAS), Group 5.

The root cause of the event was personnel error. Instrumentation and Control personnel misread information in the testing procedure, and inadvertently actuated the wrong equipment.

Corrective actions: The test procedure was reviewed for errors. The testing was completed satisfactorily following this procedure. A Control Room Engineering Design Integration team reviewed color coding, placement and design of equipment labeling; workspace location and the procedure involved. No deficiencies were noted with respect to the criteria of NUREG 0700. An independent INPO Human Performance Enhancement System review was also performed on this event. The Instrument and Control personnel involved were counseled.



LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  St. Lucie Unit 2	DOCKET NUMBER (2)  0500038990	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		90	004	00	02	OF	03

TEXT (If more space is required, use additional NRC Form 366A's)(17)

**DESCRIPTION OF THE EVENT**

On November 9, Unit 2 was in Mode 5 during a refueling outage. The Reactor Coolant System (RCS) (EIS:AB) loops were full and on solid pressure control, with venting in progress. Instrument and Control (I&C) personnel were performing Engineered Safeguards (EIS:JE) time response testing as per I&C procedure 2-140053. According to the procedure, the Operations crew were briefed and given a list of equipment that were expected to actuate during that portion of the testing. The equipment listed belonged to the 'A' side Safety Injection Actuation Signal/Containment Isolation Signal (SIAS/CIAS) (EIS:JM), Group 3. However, at 1959 hours, I&C personnel depressed the wrong pushbutton and unexpectedly actuated a different group of Engineered Safeguards equipment, the Group 5 equipment. The Operations crew immediately realized that the actuations were incorrect and notified the I&C personnel, then proceeded immediately to review Plant conditions and realign equipment. The major equipment that actuated included: 2A Emergency Diesel Generator (EIS:EK), 2A Intake Cooling Water Pump, 2A Component Cooling Water Pump (EIS:CC), 2A and 2B Boric Acid Makeup Pumps (EIS:CA), and the Emergency Borate Valve. Testing was terminated, the Engineered Safeguards actuations were reset, and Mode 5 operations were resumed.

**CAUSE OF THE EVENT**

A Control Room Engineering Design Integration Team reviewed color coding, placement, labeling, workspace location, and the procedure involved. No deficiencies were noted with respect to the criteria of NUREG 0700. An independent INPO Human Performance Enhancement System (HPES) review was also performed on this event.

The root cause of this event was cognitive personnel error. Utility I&C personnel misread a correct and approved I&C testing procedure. The wrong pushbutton was depressed on an Engineered Safeguards cabinet actuation module. This caused the actuation of a different group of Engineered Safeguards equipment than anticipated. There were no adverse conditions at the work location that affected the job, and the pushbuttons were clearly and logically labeled.

**ANALYSIS OF THE EVENT**

This event is reportable under the requirements of 10CFR50.73.a.2.iv as an event that resulted in manual or automatic actuation of any Engineered Safeguards Feature.

The portion of the testing being performed at this time concerned the actuation of 'A' side SIAS/CIAS, Group 3 equipment. As a result of the error, Group 5 equipment was actuated. The Unit was configured in Mode 5 such that these actuations had no affect on Plant operation. All Group 5 equipment actuated correctly and properly as called upon. Therefore, there were no equipment operability concerns.

There is no possibility that this scenario could effect power operations due to the fact that this test is performed only in modes 3, 4, 5, or 6.

Thus, the health and safety of the public were not at risk at any time during this event.



LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  St. Lucie Unit 2	DOCKET NUMBER (2)  0   5   0   0   0   3   8   9   9   0	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
			0   0   4	0   0	0   3	OF	0   3

TEXT (If more space is required, use additional NRC Form 366A's)(17)

**CORRECTIVE ACTIONS**

1. An HPES review was performed on this event.
2. A Control Room Engineering Design Integration Team review was performed on equipment, procedures, and work environment. No deficiencies with respect to NUREG 0700 were noted.
3. The Engineered Safeguards time delay testing was completed satisfactorily.
4. I&C personnel were counseled as to the need to follow test procedures closely.

**ADDITIONAL INFORMATION**

Failed Component Identification:

NONE

Previous Similar Events:

LER 389-89-003 describes an inadvertent Containment Isolation actuation due to a Licensed Operator mistakenly resetting one channel while a second channel was in the tripped condition.