

FORD 2

REGULARY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9208240324 DOC. DATE: 90/06/18 NOTARIZED: NO DOCKET # 05000335
 FACIL: 50-335 St. Lucie Plant, Unit 1, Florida Power & Light Co.
 AUTH. NAME SAGER, D. A. AUTHOR AFFILIATION Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION Document Control Branch (Document Control Desk)

SUBJECT: Responds to NRC bulletin 89-002, "Stress Corrosion Cracking of High Hardness Type 410 Stainless Steel Internal Preload Bolting in Anchor Darling Model S350W Swing Check Valves or...." Valve found to have broken hinge pin block studs.

DISTRIBUTION CODE: DF01D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Direct Flow Distribution: 50 Docket (PDR Avail)

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID	CODE/NAME	LTR	ENCL		ID	CODE/NAME	LTR	ENCL
INTERNAL:	NUDDCS-	ABSTRACT	1	1	REG FILE	01	1	1	
EXTERNAL:	NRC	PDR	1	1	NSIC		1	1	

*John MEANNING 1
14-B-2*

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK. ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 5 ENCL 9

A01

R
I
D
S
/
F
O
R
D
D
O
C
U
M
E
N
T



Faint, illegible text or markings, possibly bleed-through from the reverse side of the page.

Another set of faint, illegible text or markings, also appearing to be bleed-through.

A single, small, faint character or mark located in the middle of the page.



FPL

JUN 18 1990

L-90-208

10 CFR 50.54(f)

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

Gentlemen:

Re: St. Lucie Unit 1
Docket 50-335
NRC Bulletin 89-02
TAC No. 74316

On July 19, 1989, the NRC issued NRC Bulletin No. 89-02, "Stress Corrosion Cracking of High Hardness Type 410 Stainless Steel Internal Preloaded Bolting in Anchor Darling Model S350W Swing Check Valves or Valves of Similar Design." Licensees were requested to identify, disassemble and inspect certain types of swing check valves which may contain Type 410 stainless steel bolting material. The NRC requested that it be informed of the completion of these inspections as well as the number of valves found to have service-induced cracking of bolting.

Seven valves subject to Bulletin 89-02 were inspected during the Spring 1990 St. Lucie Unit 1 refueling outage and their bolting material replaced with bolting meeting the requirements of the bulletin. Of the seven valves inspected, one valve was found to have two broken hinge pin block studs.

Since all bolting was replaced with bolting meeting the material and hardness requirements of NRC Bulletin 89-02, this completes the required actions of this bulletin for St. Lucie Unit 1.

Should there be any further questions, please contact us.

Very truly yours,

D. A. Sager

D. A. Sager
Vice President
St. Lucie Plant

DAS:JMP:kw

7208240324 900618
PDR ADDOCK 05000335
G PDR

cc: Stewart D. Ebnetter, Regional Administrator; Region II, USNRC
Senior Resident Inspector, USNRC, St. Lucie Plant

DAS/PSL #182

Add: John Menning
14B-2

JFol
1/0



21
22
23

24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100