

ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9306290152 DOC. DATE: 93/06/21 NOTARIZED: NO DOCKET #
FACIL: 50-389 St. Lucie Plant, Unit 2, Florida Power & Light Co. 05000389
AUTH. NAME AUTHOR AFFILIATION
SMITH, G.D. Florida Power & Light Co.
SAGER, D.A. Florida Power & Light Co.
RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 93-007-00: on 930521, observed indication of multiple
dropped CEA on core mimic display resulting to manual
reactor trip. Caused by equipment failure. LLRT conducted to
verify containment vessel integrity. W/930621 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 6
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 1	PD2-2 PD	1 1
	NORRIS, J	1 1		
INTERNAL:	ACNW	2 2	ACRS	2 2
	AEOD/DOA	1 1	AEOD/DSP/TPAB	1 1
	AEOD/ROAB/DSP	2 2	NRR/DE/EELB	1 1
	NRR/DE/EMEB	1 1	NRR/DORS/OEAB	1 1
	NRR/DRCH/HHFB	1 1	NRR/DRCH/HICB	1 1
	NRR/DRCH/HOLB	1 1	NRR/DRIL/RPEB	1 1
	NRR/DRSS/PRPB	2 2	NRR/DSSA/SPLB	1 1
	NRR/DSSA/SRXB	1 1	<u>REG FILE</u> 02	1 1
	RES/DSIR/EIB	1 1	RGN2 FILE 01	1 1
EXTERNAL:	EG&G BRYCE, J.H	2 2	L ST LOBBY WARD	1 1
	NRC PDR	1 1	NSIC MURPHY, G.A	1 1
	NSIC POORE, W.	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 32 ENCL 32

AD4



P.O. Box 128, Ft. Pierce, FL 34954-0128

June 21, 1993

L-93-160
10 CFR 50.73

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Re: St. Lucie Unit 2
Docket No. 50-389
Reportable Event: 93-07
Date of Event: May 21, 1993
Manual Reactor Trip After the Simultaneous Dropping
of Control Element Assemblies due to Equipment Failure

The attached Licensee Event Report is being submitted pursuant to the requirements of 10 CFR 50.73 to provide notification of the subject event.

Very truly yours,

DASager
D. A. Sager
Vice President
St. Lucie Plant

DAS/JJB/kw

Attachment

cc: Stewart D. Ebnetter, Regional Administrator, USNRC Region II
Senior Resident Inspector, USNRC, St. Lucie Plant

DAS/PSL #938-93

9306290152 930621
PDR ADOCK 05000389
S PDR

an FPL Group company

IK22
11

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.8 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20546, AND TO THE PAPERWORK REDUCTION PROJECT (D-150 8194), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) St. Lucie Unit 2						DOCKET NUMBER (2) 0 5 0 0 0 3 8 9			PAGE (3) 1 OF 0 5		
---------------------------------------	--	--	--	--	--	----------------------------------------------------	--	--	----------------------------	--	--

TITLE (4) Manual Reactor Trip After the Simultaneous Dropping of Control Element Assemblies due to Equipment Failure

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)											
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)									
0	5	2	1	9	3	9	3	0	0	7	0	0	0	6	2	1	9	3	N/A	0 5 0 0 0 3 8 9

OPERATING MODE (9) 1	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR : (Check one or more of the following) (11)					
	20.402(b)	20.405(c)	X	50.73(a)(2)(iv)	73.71(b)	
POWER LEVEL (10) 0 7 2	20.405(a)(1)(i)	50.36(c)(1)		50.73(a)(2)(v)	73.71(c)	
	20.405(a)(1)(ii)	50.36(c)(2)		50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text NRC Form 366A)	
20.405(a)(1)(iii)	50.73(a)(2)(i)		50.73(a)(2)(viii)(A)			
20.405(a)(1)(iv)	50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)			
20.405(a)(1)(v)	50.73(a)(2)(iii)		50.73(a)(2)(x)			

LICENSEE CONTACT FOR THIS LER (12)

NAME Galen D. Smith, Shift Technical Advisor	TELEPHONE NUMBER		
	AREA CODE 4 0 7	4 6 5 - 3 5 5 0	

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
B	A A	C O N	C 5 1 5	Y					

SUPPLEMENTAL REPORT EXPECTED (14)

<input checked="" type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)	<input type="checkbox"/> NO	EXPECTED SUBMISSION DATE (15)	MONTH 0 5	DAY 3 0	YEAR 9 4
-------------------------------------------------------------------------------------	-----------------------------	-------------------------------	----------------	--------------	---------------

ABSTRACT (Limit to 1400 spaces. i.e. approximately fifteen single-space typewritten lines) (16)

On May 21, 1993, St. Lucie Unit 2 was manually tripped from 72% power by utility-licensed operators approximately ten seconds after seven Control Element Assemblies (CEA's) fully inserted into the core. The dropped CEAs were confirmed by the presence of rod bottom lights, CEA reed switch position transmitter indication, and decreasing reactor coolant system average coolant temperature. Standard Post Trip Actions were carried out and the unit was placed in a stable condition in Mode 3.

Initial investigation revealed that several CEA power supply breakers were open and/or fuses blown which was indicative of an electrical fault. Subsequently, two grounded CEA cables associated with CEA's 54 and 61 were discovered in electrical penetration D-1 to the containment shield building. The root cause of the electrical grounds will be investigated during the next Unit 2 refueling outage.

Corrective Actions for this event: 1) Isolated grounded conductors in electrical penetration D-1 and relanded affected CEA cables to available spare penetration modules in penetration D-1, 2) Replaced the subgroup breaker associated with subgroup sixteen and individual disconnect breakers for CEA's 8, 54, 60, and 61, 3) Performed an Engineering Evaluation on multiple CEA drops and effects on Departure from Nucleate Boiling Ratio and Local Power Density which concluded that no Specified Acceptable Fuel Design Limits (SAFDL) were exceeded, 4) During the next Unit 2 refueling outage, penetration D-1 will be inspected, 5) A local leak rate test on penetration D-1 was performed with satisfactory results, and 6) The addition of a ground detection circuit to the Control Element Drive Mechanism Control System as a system enhancement is being evaluated.

**LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION**

ESTIMATE BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION
NEEDS: 50 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS
AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION,
WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE
OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) St. Lucie Unit 2	DOCKET NUMBER (2) 05000389	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		93	007	00	02	OF 05

TEXT (If more space is required, use additional NRC Form 366A's) (17)

DESCRIPTION OF EVENT

On May 21, 1993, while Unit 2 was at 72% power steady state operation, control room operators observed the indication of multiple dropped Control Element Assemblies (CEA's) (EIS : AA) on the Core Mimic Display and the CEA Display Panel accompanied by the simultaneous annunciation of alarm K-23 "CEDMCS (Control Element Drive Mechanism Control System) (EIS : AA) Trouble". Subsequently, a decrease in Tave was observed. The Digital Data Processing System indicated that the seven dropped CEAs were numbers 8, 54, 60, 61, 53, 65 and 67. Approximately 10 seconds after the CEA's dropped, operators manually tripped the reactor and the turbine in accordance with the immediate operator actions of the CEA Off-Normal procedure, ONOP 2-0110030. Emergency Operating Procedure (EOP) One, "Standard Post Trip Actions", was implemented immediately post-trip. The Steam Bypass Control System (EIS: JI) operated properly to reduce Tave to 532 degrees Fahrenheit. The Steam Generators (SG's) (EIS: AB) were supplied post trip via the Steam Generator Feed Pumps (SGFP) (EIS: SJ) and the 15% feedwater bypass valve. After the successful implementation of standard post trip actions by two Reactor Control Operators, an uncomplicated reactor trip was diagnosed and the Senior Reactor Operator directed the crew to exit EOP-1 and enter EOP-2, "Reactor Trip Recovery". After the completion of EOP-2, the unit was maintained in Mode 3 for the post trip review and event investigation. Subsequent examination of the CEDMCS revealed the following conditions for the seven dropped CEA's: (See Figure One for an abbreviated schematic of the CEA power system)

- CEA 8, Regulating Group 5 - disconnect breaker was not tripped, no Subgroup fuses blown.
- CEA 54, Shutdown Group A - disconnect breaker was tripped.
- CEA 60, Regulating Group 3 (Subgroup 15) - disconnect breaker not tripped, no Subgroup fuses blown.
- CEA 61, Regulating Group 3 (Subgroup 16) - A&B phases of disconnect breaker tripped, 2 Subgroup fuses blown.
- CEA 63, Regulating Group 3 (Subgroup 16) - disconnect breaker closed, 2 Subgroup fuses blown.
- CEA 65, Regulating Group 3 (Subgroup 16) - disconnect breaker closed, 2 Subgroup fuses blown.
- CEA 67, Regulating Group 3 (Subgroup 16) - disconnect breaker closed, 2 Subgroup fuses blown.

CAUSE OF EVENT

The CEA power distribution system utilizes a 240 VAC three phase system with an ungrounded neutral line. This three phase AC is then rectified and conditioned by the CEDMCS to a nominal 50 VDC which is then supplied to each Control Element Drive Mechanism (CEDM) (EIS: AA) coil stack inside of containment. During steady state conditions, the control room CEDMCS operating panel is switched to "Off", as it was during this event. This results in only the Upper Gripper Coil of each CEA being energized. If the Automatic CEDM Timer Module (ACTM) for a CEA reads an abnormal current condition for the Upper Gripper coil, the CEA will be maintained withdrawn by the ACTM energizing the Lower Gripper Coil. Under normal conditions, this DC power arrangement with an ungrounded neutral line is tolerant of at least one conductor short to ground. Furthermore, as long as the conductor grounds are of the same polarity, multiple conductor grounds on different coil stacks may not affect the system's operability and may go undetected. When a second conductor ground develops on a conductor of different polarity a short circuit develops which may cause CEDM coils to deenergize.

**LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION
REQUEST: 50 8 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS
AND REPORTS MANAGEMENT BRANCH (P-330), U.S. NUCLEAR REGULATORY COMMISSION,
WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE
OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) St. Lucie Unit 2	DOCKET NUMBER (2) 05000389	LER NUMBER (6)		PAGE (3)	
		YEAR 93	SEQUENTIAL NUMBER 007	REVISION NUMBER 00	03 OF 05

TEXT (If more space is required, use additional NRC Form 366A's) (17)

CAUSE OF THE EVENT (cont.)

The most probable cause of the drop of seven CEAs is attributable to grounds in the 50 VDC CEDM power system located in an electrical penetration. Testing by the I&C Department revealed that five grounds were present in the Shield Building side of electrical penetration D-1. These conductor to ground shorts resulted in an overcurrent condition that opened the disconnect breaker for CEA 54, several contacts in the disconnect breaker for CEA 61, and the 2 fuses blown on subgroup 16. The two CEAs which did not observe a condition that would permanently interrupt power to the Upper Gripper and Lower Gripper Coils were CEAs 8 and 60. (CEDM 60 was found to have a ground on the neutral phase of its load transfer coil; this condition alone would not cause the CEA to drop. CEDM 8 had no faults identified). The most likely cause for CEA's 8 and 60 to drop during this event was due to a transient induced on the CEDMCS 240 VAC power system when the conductor to ground faults developed. Output monitoring of the 2A Motor Generator (MG) set with a temporary power line monitor during testing of CEA 61 prior to the repairs showed that the grounds were reflected back throughout the CEDMC power system. This disturbance probably resulted in the dropping of CEA's 8 and 60.

The root cause of the conductor grounds in electrical penetration D-1 could not be determined immediately after the event since inspection of the penetration would require electrical penetration disassembly. Comprehensive testing of the CEDMCS, CEDM conductors, and the containment penetration provided a high degree of confidence in the operability of the systems required to support unit restart. A detailed analysis of the conductor grounding will be performed at the next refueling outage.

ANALYSIS OF EVENT

This event is reportable pursuant to 10CFR50.73(a)(2)(iv) as a manual actuation of the Reactor Protection System (RPS) (EHS : JE). Having seven CEA's fully insert into the core during power operation is not specifically analyzed in the St. Lucie Unit 2 Final Updated Safety Analysis Report (FUSAR). Section 15.4.2.3.8 of the FUSAR analyzes a single dropped CEA as well as a dropped CEA subgroup. For a CEA subgroup insertion from 100% power, a calculated minimum Departure from Nucleate Boiling Ratio (DNBR) of 1.28 is reached in approximately 4 minutes with no operator action.

The Nuclear Engineering Department analyzed the seven dropped CEA's scenario and concluded that no DNBR or Fuel Design Limits were exceeded during this event. This evaluation was conservative in that it did not credit the immediate manual trip inserted by the operators. Additionally, no incore neutron detector alarms were received prior to the manual reactor trip; providing further assurance of remaining within core design limitations. The reactor trip was observed to be a routine manual trip. The resulting plant transient was well enveloped by the St. Lucie Unit 2 FUSAR.

Visual inspection and testing of electrical penetration D-1 did not reveal any indication of containment integrity being affected by the conductor grounds. Testing indicated that the faults were in a cable splice in the shield building penetration, several feet removed from the containment penetration. A precautionary local leak rate test was performed on penetration D-1 with satisfactory results, thus assuring that containment vessel integrity was not affected during this event.

**LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION
REQUEST: 30 2 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS
AND REPORTS MANAGEMENT BRANCH (P-330), U.S. NUCLEAR REGULATORY COMMISSION,
WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE
OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) St. Lucie Unit 2	DOCKET NUMBER (2) 05000389	LER NUMBER (6)			PAGE (3)	
		YEAR 93	SEQUENTIAL NUMBER 007	REVISION NUMBER 00	04	OF 05

TEXT (If more space is required, use additional NRC Form 366A's) (17)

CORRECTIVE ACTIONS

- 1) All CEDM cables were meggered through their respective penetrations which identified the five (three on CEA 54, one on CEA 61, and one on CEA 60) ground faults in penetration D-1 and to confirm that no other CEDM penetrations were affected.
- 2) Spare conductors in modules 20 and 24 of penetration D-1 were meggered to ensure that no faults existed prior to placing those spares in service. The grounded conductors in modules 11 and 17 of penetration D-1 were isolated and the affected CEA cables were reterminated to leads on the five available spares in modules 20 and 24.
- 3) Pin to pin meggering was performed on the conductors in modules 11 and 17 of penetration D-1. This was to confirm that there were no conductor to conductor shorts within those modules for the conductors which were kept in service.
- 4) CEA Subgroup 16 breaker and the individual CEA disconnect breakers associated with CEAs 8, 54, 60, and 61 were replaced.
- 5) Using a power line condition monitor with the trip circuit breakers closed, satisfactory CEDM motor generator bus phase to phase and phase to voltage traces were recorded and reviewed to ensure that no faults existed on that power supply.
- 6) Nuclear Engineering has performed an analysis of multiple rod drops as experienced by this event to confirm that DNBR or Local Power Density safety limits were not violated.
- 7) To confirm the integrity of the fuel, Iodine levels in the RCS were monitored by Reactor Engineering and compared with previous values. No abnormal levels were noted.
- 8) During the next Unit 2 refueling outage, electrical penetration D-1 will be inspected by Electrical Maintenance to determine the root cause of the electrical grounds.
- 9) A satisfactory Local Leak Rate test on penetration D-1 verified containment vessel integrity.
- 10) The addition of a ground detection circuit to the Control Element Drive Mechanism Control System as a system enhancement is being evaluated.

ADDITIONAL INFORMATION

Failed Component Identification

Component : Low Voltage Electrical Penetration
Manufacturer : CONAX Corporation Part Number : 7310-10004-07

Previous Similar Events:

See LER #389-89-007 and LER #335-80-050 (manual reactor trips due to multiple dropped CEAs)

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION
REQUEST: 50.9 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS
AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION,
WASHINGTON, DC 20535, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE
OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) St. Lucie Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 3 8 9	LER NUMBER (6)			PAGE (3)		
		YEAR 9 3	SEQUENTIAL NUMBER 0 0 7	REVISION NUMBER 0 0			

TEXT (If more space is required, use additional NRC Form 366A's) (17)




FIGURE ONE - CEA POWER DISTRIBUTION