


50-249

Commonwealth Edison Company

ONE FIRST NATIONAL PLAZA ★ CHICAGO, ILLINOIS

Address Reply to:

POST OFFICE BOX 767 ★ CHICAGO, ILLINOIS 60690



Dresden Nuclear Power Station
 R. R. #1
 Morris, Illinois 60450
 January 7, 1972

Regulatory File Cy.

Dr. Peter A. Morris, Director
 Division of Reactor Licensing
 U. S. Atomic Energy Commission
 Washington, D. C. 20545



SUBJECT: LICENSE DPR-25 DRESDEN NUCLEAR POWER STATION UNIT #3
SECTION 6.6.B.3 OF THE TECHNICAL SPECIFICATIONS

Dear Dr. Morris:

This is to report a condition relating to the operation of the station, when the mechanical vacuum pump suction valve (3-5402B) failed to close, thus rendering the mechanical vacuum pump incapable of being isolated as required by Section 3.8.B.1 of the Dresden Unit #3 Technical Specifications.

Problem and Investigation

On December 30, 1971, at 2310, with the reactor in the run mode at 150 MWe, condenser flow reversal tests were in progress, when valve 3-5402B failed to fully close. The manual suction valve for the mechanical vacuum pump was closed and the reactor placed in a cold shutdown condition. Subsequent investigation revealed that the failure of the valve was the result of the valve disc binding in the guides due to a slight overtravel in the valve.

Corrective Action

A three inch slug was installed in the valve operator to reduce the valve travel in the open direction. After the installation of the slug, the valve was cycled and the anomaly could not be reproduced. Slugs will be added to the remaining similar mechanical vacuum pump suction valves on Units 2 and 3 at the earliest practical time.

Sincerely,

W. P. Worden

W. P. Worden
 Superintendent

WPW:ls

157 48