

Dr. Central file

5-8-72,

50-249



*512 MAY 8 PM 4 18
dof 52100*

352P EST MAY 8 72 DEB623

SSE249 DE CCG094 (CH 129CC601094) PD WU JOL

0126P EDT 05/08/72

ZCZC 1 NL PD MORRIS ILL MAY 4 415P CDT

MR BOUCE GRIER, DIRECTOR REGION 3 COMPLIANCE

US ATOMIC ENERGY COMM 799 ROOSEVELT RD GLEN ELLYN ILL 60137

60137

BT

D P R 25 DRESDEN NUCLEAR POWER STATION UNIT 3:

THIS WILL CONFIRM CONVERSATION AT 15:00 HRS THIS DATE WITH H DANCE REGARDING FAILURE OF THE ISOLATION CONDENSOR VALVE 3-1301-3 TO OPEN ELECTRICALLY FOLLOWING A REACTOR SCRAM. IMMEDIATELY FOLLOWING THE SCRAM WHICH OCCURRED AT 0901 HRS A GROUP 1 ISOLATION OCCURED BECAUSE OF A HIGH WATER LEVEL CONDITION.

AN ATTEMPT WAS MADE TO PLACE THE ISOLATION CONDENSOR IN SERVICE BUT VALVE 3-1301-3 WOULD NOT OPEN. AN OPERATOR HAD TO GO TO THE VALVE

312-858-2668
TELEPHONE NO. *heads*
TELEPHONED TO
TIME DELIVERED *1032A*

Hme



Telegram

AND MANUALLY CRAKE THE VALVE OFF ITS SEAT. ONCE THE VALVE WAS OPENED ITS BREAKER RE-SET AND IT FUNCTIONED PROPERLY.

WHILE THE OPERATOR WAS WORKING ON PLACING THE ISLTATION CONDENSOR IN SERVICE REACTOR PRESSURE INCREASED TO APPROXIMATELY 1100 PSIG AT THIS PRESSURE 3A ELECTROMATIC VALVE OPENS AUTOMATICALLY.

WHEN THE ELECTROMATIC VALVE OPENED THE DRYWELL PRESSURE IMMEDIATELY INCREASED TO 2.5 PSIG. AFTER PEAKING AT 2.5 PSIG THE DRYWELL PRESSURE RETURNED TO NORMAL.

A COMPLETE DRYWELL INSPECTION WILL BE MADE WHEN ENTRY IS POSSIBLE TO DETERMINE THE CAUSE OF THE PRESSURIZATION AND TO DETERMINE IF ANY EQUIPMENT HAS BEEN DAMAGED AS A RESULT OF THIS PRESSURIZATION IN ADDITION A COMPLETE CHECK-OUT WILL BE MADE ON VALVE 3-1301-3.

6F-120 (R5-59) THE ISOLATION CONDENSOR TO DETERMINE WHY IT FAILED TO OPEN



Telegram

W P WORDEN PLANT SUPERINTENDENT DRESDEN NUCLEAR POWER STATION

D P R 25 3 15:00 3-1301-3 0901 3-1301-3 1100 PSIG 3A 2.5 2.5
3-1301-3

NNNN(C133P EDT)