NRG FORM 591M PART 1 U.S. NUCLEAR REGULATORY COMMISSION									
10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION									
LICENSEE/LOCATION INSPECTED: 2. NRC/REGIONAL OFFICE									
Tyme Engineering 32121 Schoolcraft Livonia, Michigan	t Road		Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352						
REPORT NUMBER(S	3) 2017001								
3. DOCKET NUMBER(S)		4. LICENSE NUMBER	(S)	5. DATE(S) OF INSPECT	,				
030-36599		21-32523-01		8/8/17-8	(1)/17				
LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspection. The inspection findings are as follows:									
1. Based on the inspection findings, no violations were identified.									
2. Previous violation(s) closed. The violations(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.									
Non-cited violation(s) were discussed involving the following requirement(s):									
					·				
# 				• •					
During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)									
-									
•									
	Statement of Corrective Actions								
I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.									
TITLE	PRINTED NAME		SIGNATURE		DATE				
LICENSEE'S REPRESENTATIVE									
NRC INSPECTOR	Bill C. Lin	7	Bef =)	8/22/17				
BRANCH CHIEF	Aaron T. McCraw		1/11		¥ 25 17				

NRC FORM 591M PART 3 U.S. NUCLEAR REGULATORY COMMISSION (07-2012) Docket File Information									
Docket File Information SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION									
1. LICENSEE/LOCATION INSPECT	EU:		2. NRC/REGIONAL OFFICE						
Tyme Engineering, Inc.			Region III						
32121 Sohoolcraft Road			U. S. Nuclear Regulatory Commission						
Livonia Michigan 48150			2443 Warrenville Road, Suite 210						
			Lisle, IL 60532-4352						
REPORT NUMBER(S) 2017-	001								
3. DOCKET NUMBER(S)		4. LICENSE NUMBER(S) 5.		5. DATE(S) OF INSPECTION					
030-36599		21-32523-01	8/8/2017-8/17/2017						
6. INSPECTION PROCEDURES USED		7. INSPECTION FOCUS AREAS							
87124		3.01-3.07							
SUPPLEMENTAL INSPECTION INFORMATION									
1. PROGRAM CODE(S)	2. PRIORITY	3. LICENSEE CONTAC	Г	4. TELEPHONE NUMBER					
3121	5	Brian Hibdon		(248) 356-8440					
✓ Main Office Inspection Next Inspection Date: 08/08/2022									
Field Office Inspec	otion								
Townson, Joh Ci									
Temporary Job Si	te inspection								
PROGRAM SCOPE									
This was a routine inspection of a portable gauge licensee located in Livonia, Michigan. The licensee currently									
possesses 18 Troxler Model gauges for use during the construction season. The licensee does not perform any services									
or maintenance activities on its gauges; these services are performed by the licensee's contractor. Currently, the licensee employs 15 authorized gauge users who have completed manufacturers training. The gauges are stored in a									
vault in the licensee's office in Livonia, Michigan.									
Performance Observation									
At the time of the inequation, the NDC inequates did not have the amount with the charge the surface of the sur									
At the time of the inspection, the NRC inspector did not have the opportunity to observe the performance of a density measurement at a temporary job site. The inspector toured the facility, performed independent surveys around									
the gauge storage area, reviewed records, and interviewed licensee personnel. The licensee demonstrated how they									
transport a portable gauge to a temporary job site in accordance with NRC regulatory requirements, and the operator									
demonstrated an adequate understanding of emergency and handling procedures during the onsite interview. At the									
time of the on site inspection, the licensee did not have all of its training records, leak tests, and inventories									
immediately available for the inspector's review. The inspector performed an in-office reviewed of those documents and performed a telephone exit with the licensee's radiation safety officer on August 17, 2017.									
The property of the state of th									
No violations of NRC requirements were identified during this inspection.									
·									