

DEFECTIVE WESTINGHOUSE TYPE W-2 CONTROL SWITCH COMPONENT

Recent inspection findings indicate a possible safety problem may exist in plants employing Westinghouse Type W-2 control switches. The information is as follows:

A. Description of Circumstances

Plant A

By notification from Westinghouse Nuclear Service Division, dated February 8, 1973, the licensee was informed of a defect in certain Westinghouse Type W-2 control switches. Repair kits were ordered to replace the defective components. Inspection of the replacement parts, prior to installation, revealed 8 of 14 pull levels (metal discs with expansion pins inserted) to be cracked. None of the replacement parts were installed.

Plant B

Following the same notification from Westinghouse as above, repair kits were ordered to replace the defective component. Replacement parts were installed in forty switches. One pull lever was found cracked during installation and discarded. Two spare repair kits were retained. At the request of the Atomic Energy Commission the pull levers in these two spare kits were inspected. One of the two was found to be cracked.

B. Action Requested

1. If these switches are used in safety systems in your plant please notify this office, within 30 days of receipt of this Bulletin, in writing, of the extent of such use and the actions you plan to take or have taken to correct the problem with the original W-2 switches and to assure that repair parts are not defective. If corrective actions have not been completed, it is requested that your scheduled date of completion be provided.
2. If this matter does not apply to your plant, a negative report is requested.

7910250728



UNITED STATES
ATOMIC ENERGY COMMISSION
 DIRECTORATE OF REGULATORY OPERATIONS
 REGION 1
 631 PARK AVENUE
 KING OF PRUSSIA, PENNSYLVANIA 19406

MAR 26 1974

Docket No. 50-244

Rochester Gas and Electric Corporation
 Attention: Mr. Keith W. Amish
 Senior Vice President
 Electric and Steam
 89 East Avenue
 Rochester, New York 14649

Gentlemen:

The enclosed DRO Bulletin No. 3 "Failure of Structural or Seismic Support Bolts on Class I Components" is sent to provide you with information reported by Connecticut Yankee as an abnormal occurrence at The Haddam Neck reactor facility.

This information may have applicability at your facility(ies). Action requested on your part is identified in Section B of the enclosed Bulletin.

Sincerely,

Robert T. Carlson
 James P. O'Reilly
Acting Director

Enclosure:
 DRO Bulletin No. 74-3

cc: Mr. C. Platt, Plant Superintendent

- bcc: RO FILES
- ✓ DR Central Files
- PDR
- Local PDR
- NSIC
- DTIE
- State of New York

OFFICE ▶	CRESS <i>[Signature]</i>	<i>[Signature]</i>	<i>[Signature]</i>	<i>[Signature]</i>	<i>[Signature]</i>	<i>[Signature]</i>
SURNAME ▶	O'Reilly/by <i>[Signature]</i>	<i>[Signature]</i>	3/26	3/26/74		<i>[Signature]</i>
DATE ▶	3/26/74					