



**Commonwealth Edison**  
 Dresden Nuclear Power Station  
 R.R. #1  
 Morris, Illinois 60450  
 Telephone 815/942-2920

BBS Ltr. #76-844

December 2, 1976



Mr. James G. Keppler, Regional Director  
 Directorate of Regulatory Operations - Region III  
 U. S. Nuclear Regulatory Commission  
 799 Roosevelt Road  
 Glen Ellyn, Illinois 60137

Enclosed please find Reportable Occurrence report number 50-249/1976-34. This report is being submitted to your office in accordance with the Dresden Nuclear Power Station Technical Specifications, Section 6.6.B.

B. B. Stephenson  
 Station Superintendent  
 Dresden Nuclear Power Station

BBS:jo

Enclosure

cc: Director of Inspection & Enforcement  
 Director of Management Information & Program Control  
 File/NRC



12503

# LICENSEE EVENT REPORT

CONTROL BLOCK: 

--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: 

01	I	L	D	R	S	3
----	---	---	---	---	---	---

 LICENSE NUMBER: 

00	-	000000	-	00
----	---	--------	---	----

 LICENSE TYPE: 

4	1	1	1	1	1
---	---	---	---	---	---

 EVENT TYPE: 

0	1
---	---

REPORT TYPE: 

T
---

 REPORT SOURCE: 

L
---

 DOCKET NUMBER: 

05	0	-	02	4	9
----	---	---	----	---	---

 EVENT DATE: 

1	1	1	9	7	6
---	---	---	---	---	---

 REPORT DATE: 

1	2	0	2	7	6
---	---	---	---	---	---

### EVENT DESCRIPTION

02 AS A RESULT OF THE 2301-8 HPCI INJECTION VALVE STEM FAILURE  
03 THAT WAS RECENTLY DISCOVERED ON UNIT-2 (R.O. REPORT NO. 50-  
04 237/1976-66), A HPCI LOGIC DESIGN WIRING PROBLEM WAS IDEN-  
05 TIFIED WHICH WAS BELIEVED TO BE COMMON TO BOTH UNIT-2 AND  
06 UNIT-3. THE WIRING ERROR, WHICH DID IN FACT EXIST ON UNIT-3,  
(SEE ATTACHED SHEET)

SYSTEM CODE: 

S	F
---	---

 CAUSE CODE: 

B
---

 COMPONENT CODE: 

V	A	L	V	E	X
---	---	---	---	---	---

 PRIME COMPONENT SUPPLIER: 

N
---

 COMPONENT MANUFACTURER: 

C	6	6	5
---	---	---	---

 VIOLATION: 

N
---

### CAUSE DESCRIPTION

08 VALVE MO 3-2301-8 WAS RACKED OUT OF SERVICE IN THE OPEN POSI-  
09 TION, AND VALVE 2301-9 WAS CLOSED TO ISOLATE THE HPCI PUMP DISCHARGE  
10 DURING THE NEXT SCHEDULED UNIT OUTAGE, THE STEM OF VALVE  
(SEE ATTACHED SHEET)

FACILITY STATUS: 

E
---

 % POWER: 

0	9	4
---	---	---

 OTHER STATUS: 

NA
----

 METHOD OF DISCOVERY: 

D
---

 DISCOVERY DESCRIPTION: 

NA
----

FORM OF ACTIVITY RELEASED: 

Z
---

 CONTENT OF RELEASE: 

Z
---

 AMOUNT OF ACTIVITY: 

NA
----

 LOCATION OF RELEASE: 

NA
----

### PERSONNEL EXPOSURES

NUMBER: 

0	0	0
---	---	---

 TYPE: 

Z
---

 DESCRIPTION: 

NA
----

### PERSONNEL INJURIES

NUMBER: 

0	0	0
---	---	---

 DESCRIPTION: 

NA
----

### OFFSITE CONSEQUENCES

15 

NA
----

### LOSS OR DAMAGE TO FACILITY

TYPE: 

Z
---

 DESCRIPTION: 

NA
----

### PUBLICITY

17 

NA
----

### ADDITIONAL FACTORS

18 

NA
----

19 

--

NAME: TERRANCE E. LANG

PHONE: EXT. 433

EVENT DESCRIPTION (Continued)

may have caused the 2301-8 valve to oscillate open/closed during refueling surveillance testing of the HPCI turbine trip circuitry. It had been determined prior to the Unit-2 failure that the motor operators for valve 2301-8 and several other safety-related valves were oversized for the valve applications. It is conceivable that the oversized operator might subject the valve stem to higher stresses under conditions such as excessive cycling. To preclude a failure of the 2301-8 valve in the closed position, the valve was opened and racked out of service. This is not a repetitive occurrence. (50-249/1976-34)

CAUSE DESCRIPTION (Continued)

3-2301-8 will be inspected and, if necessary, replaced.

A modification request has been submitted to alter the 2301-8 valve control circuitry so as to eliminate excessive cycling during routine surveillance testing. Furthermore, a modification request has been initiated to replace the motor operators on several safety-related valves with reduced-capacity units. Completion of this modification will preclude valve stem overstressing which might result from oversized motor operators. Valve MO 3-2301-8 is a Crane 14-inch gate valve, equipped with a Limitorque SMB-4 motor operator rated at 200 ft.-lb.