



**Commonwealth Edison**  
Dresden Nuclear Power Station  
R.R. #1  
Morris, Illinois 60450  
Telephone 815/942-2920

*D. Lankam*

# REGULATORY DOCKET FILE COPY

November 3, 1977



BBS LTR #1027-77

James G. Keppler, Regional Director  
Directorate of Regulatory Operations - Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Reportable Occurrence Report #77-044/03L-0, Docket #050-0249 is hereby submitted to your office in accordance with Dresden Nuclear Power Station Technical Specifications 6.6.B.2.b., conditions leading to operation in a degraded mode permitted by a limiting condition for operation.

*Arthur M. Roberts*

for B.B. Stephenson  
Station Superintendent  
Dresden Nuclear Power Station

BBS:dlz

cc: Director of Inspection & Enforcement  
Director of Management Information & Program Control  
File/NRC

NOV 7 1977

773200086

# LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | 1 | L | D | R | S | 3 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5  
7 8 9 14 15 25 26 30 57 CAT 58

CON'T  
0 1 | REPORT SOURCE | L | 0 | 5 | 0 | 0 | 0 | 2 | 4 | 9 | 7 | 1 | 0 | 0 | 4 | 7 | 7 | 8 | 1 | 1 | 0 | 3 | 7 | 7 | 9  
7 8 60 61 68 69 74 75 80

### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal operation, Unit 3 diesel oil storage tank was discovered at 8700 gal.  
0 3 | T.S.3.9.C. which requires 10,000 gal of diesel oil on site for each emergency diesel was  
0 4 | exceeded. This event has little safety significance since the Unit 3 diesel was avail-  
0 5 | able with sufficient fuel to operate until fuel delivery and the D2/3 diesel was opera-  
0 6 | ble. This event has not occurred previously at Dresden.

0 9 | SYSTEM CODE | E | E | 11 | CAUSE CODE | A | 12 | CAUSE SUBCODE | B | 13 | COMPONENT CODE | I | N | S | T | R | U | 14 | COMP. SUBCODE | S | 15 | VALVE SUBCODE | Z | 16  
7 8 9 10 11 12 13 18 19 20

17 | LER/RO REPORT NUMBER | 7 | 7 | 21 | 22 | SEQUENTIAL REPORT NO. | 0 | 4 | 4 | 24 | 26 | OCCURRENCE CODE | 0 | 3 | 28 | 29 | REPORT TYPE | L | 30 | REVISION NO. | 0 | 32

ACTION TAKEN | H | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 37 | 40 | ATTACHMENT SUBMITTED | Y | 23 | NPRD-4 FORM SUB. | N | 24 | PRIME COMP. SUPPLIER | N | 25 | COMPONENT MANUFACTURER | M | 2 | 3 | 5 | 26  
33 34 35 36 37 40 41 42 43 44 47

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The shift equipment operators failed to inform the Shift Engineer of Unit 3 fuel oil  
1 1 | low level condition. The Equipment Operators were reinstructed. The tank was filled  
1 2 | above T.S. limit within 2½ hours of discovery of the low level. The low level alarm  
1 3 | switch was inoperable and has since been replaced. No future action required.

1 5 | FACILITY STATUS | E | 28 | % POWER | 0 | 8 | 8 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | A | 31 | DISCOVERY DESCRIPTION | Routine Inspection | 32  
7 8 9 10 12 13 44 45 46 80

1 6 | ACTIVITY CONTENT | Z | 33 | RELEASED OF RELEASE | Z | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36  
7 8 9 10 11 44 45 80

1 7 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | NA | 39  
7 8 9 11 12 13 80

1 8 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41  
7 8 9 11 12 80

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43  
7 8 9 10 80

2 0 | PUBLICITY ISSUED | N | 44 | DESCRIPTION | NA | 45 | NRC USE ONLY  
7 8 9 10 68 69 80

ATTACHMENT TO LICENSEE EVENT REPORT 77-044/03L-0  
COMMONWEALTH EDISON COMPANY (CWE)  
DRESDEN UNIT 3 (ILDRS-3)  
DOCKET # 050-0249

During normal operation, the Unit 3 diesel generator fuel oil storage tank level was found at 8700 gal. This was a violation of Technical Specification T.S. 3.9.C which requires that each emergency diesel generator has 10,000 gal. of fuel available on site. D-2/3 diesel generator low pressure coolant injection and core spray surveillances were performed as required by T.S. 3.5.f. Fuel was delivered and fuel storage tank level was increased to 10,350 gal. within 2½ hours. This event has little safety significance since the Unit 3 diesel generator was available with sufficient fuel to operate until fuel delivery, and the D-2/3 diesel generator was operable.

The level in the diesel generator fuel oil storage tank is logged (on the diesel generator shift operating routine) once per shift by the equipment operator. For six shifts the level was recorded below the level which the log requires shift engineer notification and was below the T.S. limit for three shifts before the Shift Engineer was informed of the low level condition. The equipment operators have been reinstructed on the requirements and importance of the diesel generator fuel oil levels.

Unit 3 diesel generator fuel oil was being used to startup the D-2/3 heating boiler causing a high rate of fuel consumption at the time of the incident. However, there was adequate time to prevent exceeding the limit had action been taken when the first low level indication occurred.

The Unit 3 fuel oil storage tank low level alarm was inoperable at the time of the incident due to a faulty level switch. It was discovered that the low level alarm switch 3-5141-17 reset was not functioning properly during a calibration check on 8-26-77. A new switch was ordered and was not received until after the incident had occurred. The switch (Type: DAW-33-153, SN 3D598331) was replaced with a new mercoid switch (Type: PG-153-R-P2, SN 77-16303) on 10-12-77.

No future corrective action is required.