



Commonwealth Edison
 Dresden Nuclear Power Station
 R.R. #1
 Morris, Illinois 60450
 Telephone 815/942-2920

LE *D. Lankham*

August 25, 1978

BBS Ltr. #78-1185

James G. Keppler, Regional Director
 Directorate of Regulatory Operations - Region III
 U.S. Nuclear Regulatory Commission
 799 Roosevelt Road
 Glen Ellyn, IL 60137

US NRC
 REGIONAL SERVICES
 BRANCH

1978 SEP 8 AM 11 52

REC'D DISTRIBUTION
 SERVICES UNIT

Reportable Occurrence Report #78-031/03L-0, Docket #050-249 is hereby submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(b), conditions leading to operation in a degraded mode permitted by a limiting condition for operation or plant shutdown required by a limiting condition for operation.

B.B. Stephenson

B.B. Stephenson
 Station Superintendent
 Dresden Nuclear Power Station

BBS/deb

Enclosure

cc: Director of Inspection & Enforcement
 Director of Management Information & Program Control
 File/NRC

AUG 22 1978

A002/11

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 I L D R S 3 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

CON'T REPORT SOURCE L 6 0 5 0 0 0 2 4 9 7 0 7 2 6 7 8 8 0 8 2 5 7 8 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
02 While cycling the drywell equipment drain line isolation valve 3-2001-5 after a limit
03 switch adjustment, it was found that isolation valve 3-2001-6 would not close. The
04 safety significance of this event was minimal because isolation valve 3-2001-5 was
05 immediately closed and primary integrity was maintained. Similar event occurred on
06 Unit 2 as ref in I-12-2-74-7.

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
S D 11 E 12 A 13 V A L V O P 14 E 15 Z 16

17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
7 8 7 8 0 3 1 0 3 L 0

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
A 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 Y 24 N 25 A 4 9 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
10 The seals in the solenoid valve that operates isolation valve 3-2001-6 were deteriorated causing the valve to fail. The solenoid valve was replaced. Isolation valve
11 3-2001-6 was tested satisfactorily and returned to service. No further corrective
12 action necessary.

15 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
E 28 0 8 5 29 NA A 31 Operational Event

16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
Z 33 Z 34 NA NA 36

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
0 0 0 37 Z 38 NA 39

18 PERSONNEL INJURIES NUMBER DESCRIPTION
0 0 0 40 NA 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
Z 42 NA 43

20 ISSUED DESCRIPTION PUBLICITY NRC USE ONLY
N 44 NA 45