

August 25, 1978

BBS Ltr. #78-1186

James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Reportable Occurrence Report #78-045/03L-0, Docket #050-237 is hereby submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(a), reactor protection system or engineered safety feature instrument settings which are found to be less conservative than those established by the technical specifications but which do not prevent the fulfillment of the functional requirements of affected systems.

Station Superintendent

Dresden Nuclear Power Station

BBS/deb

Enclosure

CC: Director of Inspection & Enforcement
Director of Management Information & Program Control
File/NRC

## LICENSEE EVENT REPORT



:	CONTROL BLOCK:             (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
•	
, 8	I L D R S 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 5 EICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
0 1 7 8	REPORT L 6 0 5 0 0 0 2 3 7 7 0 8 0 7 7 8 8 0 8 2 5 7 8 9  DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	While performing monthly surv. DIS 1400-3, Auto Blowdown permissive sw. PS 2-1430-1466D
0 3	tripped at 120 psig. Tech Spec Table 3.2.2 requires trip between 50 and 100 psig.
0 4	Dresden setpt is 95 +/- 5 psig. Safety significance minimal since redundant
0 5	switches were operable and would have provided permissive signal at 94.0 psig. Simi-
06	lar event ref. in Docket #050-237, LER #78-031/03L-0.
0 7	
0 8	9 80
0 9 7 8	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
	LER/RO EVENT YEAR SEQUENTIAL REPORT NO.  TO REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32 32
	ACTION FUTURE COMPONENT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER SUBMITTED FORM SUB. SUPPLIER MANUFACTURER SUBMITTED FORM SUB. SUPPLIER MANUFACTURER COMPONENT MANUFACTURER SUBMITTED FORM SUB. SUPPLIER MANUFACTURER COMPONENT MANUFACTURER SUBMITTED FORM SUB. SUPPLIER MANUFACTURER COMPONENT COMPONENT MANUFACTURER COMPONENT COMPONE
10	Cause was a sticky actuator on the switch. Actuator was cleaned. Switch was reset
11	to trip at 94.8 psig increasing and repeatability verified. The Core Spray Pump
1 2	Auto Blowdown Permissive Pressure Switches will continue to be tested monthly using
1 3	DIS 1400-3. No further corrective action deemed necessary at this time.
1 4 7 8	9
1 5	FACILITY STATUS
Δ.	9 CTIVITY CONTENT 12 13 44 45 46 ELEASED OF RELEASE AMOUNT OF ACTIVITY (35)    Z   (33)   Z   (34)   NA   NA   10
1 7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) NA
1 8	9 PERSONNEL INJURIES NUMBER DESCRIPTION (41) NA 9 11 12 80
1 9	LOSS OF CR DAMAGE TO FACILITY 43  TYPE DESCRIPTION  NA  NA
2 0	PUBLICITY ISSUED DESCRIPTION 45  NAC USE ONLY  NA  NA  NA  NA
. 0	9 10 68 69 80.5