

Mr. James G. Keppler

لأواره

The 2A, 3A, and 3B reactor building vent fans and the 2C, 3A, and 3B reactor building exhaust fans were operating just prior to the occurrence.

Secondary containment was breached, refueling operations were terminated on Unit 2 and an orderly shutdown of Unit 3 was initiated. Unit 3 reactor was in the shutdown mode 17 hr. 25 minutes after the occurrence.

-2-

No incidents occurred during this time and there was no effect on the health and safety of the public.

The report on this incident is under preparation but not yet complete and this letter is to notify the commission that the report will be submitted by December 15, 1974.

Sincerely,

B. B. Stephenson Superintendent

BBS: JT: smp



Commonwe Ædison One First National Plaza, Chicago, Illinois Address Reply to: Post Office Box 767 Chicago, Illinóis 60690

Mr. James G. Keppler, Regional Director

U. S. Atomic Energy Commission

BBS Ltr. #881-74

Dresden Nuclear Power Station R. R. #1 Morris, Illinois 60450 December 9, 1974 Directorate of Regulatory Operations-Region III Mail Section

799 Roosevelt Road Glen Ellyn, Illinois 60137 SUBJECT: REPORT OF ABNORMAL OCCURRENCE PER SECTION 6.6.A OF THE TECHNICAL SPECIFICATIONS

SECONDARY CONTAINMENT BLOWOUT PANEL FAILURE

References: 1) Regulatory Guide 1.16 Rev. 1, Appendix A

- 2) Notification of Region III of AEC Regulatory Operations Telephone: Mr. D. Knopf, 1600 hours on November 30, 1974 Telegram: Mr. J. Keppler, 1600 hours on December 2, 1974
- 3) Dresden Units 2 and 3 FSAR, Vol. 1, Section 5.3-2, Rev. 3-22-68.
- 4) Dresden Unit 3 Preoperational Test Report C-12-9, Section 6.
- 5) CRC Handbook of Applied Engineering Science, Table 5-23.

Report Number: 50-249/74-35

Report Date: December 9, 1974

Occurrence Date: November 30, 1974


Facility: Dresden Nuclear Power Station, Morris, Illinois

IDENTIFICATION OF OCCURRENCE

Secondary Containment Blowout Panel Failure

CONDITIONS PRIOR TO OCCURRENCE

Unit 2 was in refuel mode, with core alterations in progress, and Unit 3 was in run mode, at a thermal power of 1614 MWt and a load of 517 MWe, just prior to the occurrence.



5- E

Ξ.

The 2A, 3A, and 3B reactor building vent fans and the 2C, 3A, and 3B reactor building exhaust fans were operating just prior to the occurrence.

Secondary containment was breached, refueling operations were terminated on Unit 2 and an orderly shutdown of Unit 3 was initiated. Unit 3 reactor was in the shutdown mode 17 hr. 25 minutes after the occurrence.

No incidents occurred during this time and there was no effect on the health and safety of the public.

The report on this incident is under preparation but not yet complete and this letter is to notify the commission that the report will be submitted by December 15, 1974.

Sincerely

B. B. Stephenson Superintendent

BBS:JT:smp