



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

REGULATORY DOCKET FILE COPY

US NRC
DISTRIBUTION SERVICES
BRANCH

1978 JUN 7 PM 12 30

RECEIVED DISTRIBUTION
SERVICES UNIT

June 2, 1978

BBS Ltr. #78-907

James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Reportable Occurrence Report #78-023/01T-0, Docket #050-249 is hereby submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.1.(b), operation of the unit or affected systems when any parameter or operation subject to a limiting condition is less conservative than the least conservative aspect of the limiting condition for operation established in the technical specifications.

Arthur M. Roberts
for B. B. Stephenson
Station Superintendent
Dresden Nuclear Power Station

BBS/deb

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
File/NRC

781600293

*A002
5/11*

ATTACHMENT TO LICENSEE EVENT REPORT 78-023/01T-0
COMMONWEALTH EDISON COMPANY (CWE)
DRESDEN UNIT-3 (ILDRS-3)
DOCKET #050-249

During startup operability surveillance testing while the Unit 3 reactor was in the refuel mode on May 20, 1978, it was found that source range monitor (SRM) 24 couldn't be driven to its proper startup position in the core. It was therefore declared inoperable. SRM 21 had previously been declared inoperable because it was reading below the Technical Specification limit of 3 counts per second. This resulted in a violation of the Technical Specification 3.2.C.2., Table 3.2.3 in which only one SRM is allowed to be inoperable in the startup condition. No previous reportable events of this type have occurred. No adverse effects on public health or safety resulted as a consequence of this event since the problems were detected before control rod drive withdrawal was initiated.

The cause of the failure of SRM 24 to insert to its proper position in the core was a faulty drive cable. The cable was replaced, and the SRM was successfully inserted. No future corrective action is necessary. The cause of the failure of SRM 21 was due to a bad signal cable. The signal cable was replaced with no future corrective actions planned.