




Commonwealth Edison
 Dresden Nuclear Power Station
 R.R. #1
 Morris, Illinois 60450
 Telephone 815/942-2920

D. Lanham



September 1, 1977

BBS Ltr. #77-783

Regulatory

File Cy

James G. Keppler, Regional Director
 Directorate of Regulatory Operations - Region III
 U.S. Nuclear Regulatory Commission
 799 Roosevelt Road
 Glen Ellyn, IL 60137

Enclosed please find Reportable Occurrence Report #50-237/1977-29. This report is being submitted to your office in accordance with the Dresden Nuclear Power Station Technical Specifications, Section 6.6.B.

for Arthur M. Pollock
 B.B. Stephenson
 Station Superintendent
 Dresden Nuclear Power Station

BBS:dlz

Enclosure

cc: Director of Inspection & Enforcement
 Director of Management Information & Program Control
 File/NRC

SEP 6 1977

772560100

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME:

01	I	L	D	R	S	2
----	---	---	---	---	---	---

 LICENSE NUMBER:

0	0	-	0	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---	---

 LICENSE TYPE:

4	1	1	1	1
---	---	---	---	---

 EVENT TYPE:

0	3
---	---

CON'T:

0	1
---	---

 CATEGORY:

--	--

 REPORT TYPE:

L

 REPORT SOURCE:

L

 DOCKET NUMBER:

0	5	0	-	0	2	3	7
---	---	---	---	---	---	---	---

 EVENT DATE:

0	8	0	2	7	7
---	---	---	---	---	---

 REPORT DATE:

0	9	0	1	7	7
---	---	---	---	---	---

EVENT DESCRIPTION

0	2
---	---

 During routine one-half core scram testing, control rod drives (CRD's) F-5 & H-7 un-

0	3
---	---

 coupled and overtravelled when withdrawn to position 48 following testing. This

0	4
---	---

 event has little safety significance since uncoupled CRD's still retain the same

0	5
---	---

 capability to scram as before uncoupling. This event occurred previously with CRD

0	6
---	---

 F-5 on December 12, 1976 (Reportable Occurrence #50-237/1976-68). CRD's F5 & H-7

(CONTINUED)

SYSTEM CODE:

R	B
---	---

 CAUSE CODE:

E

 COMPONENT CODE:

C	R	D	R	V	E
---	---	---	---	---	---

 PRIME COMPONENT SUPPLIER:

N

 COMPONENT MANUFACTURER:

G	0	8	0
---	---	---	---

 VIOLATION:

N

CAUSE DESCRIPTION

0	8
---	---

 Inspection of control rod drives (CRD's) which have previously experienced this event

0	9
---	---

 indicates that improper inner filter installation is probably responsible for the un-

1	0
---	---

 coupling. If the inner filter becomes unlatched, full withdrawal of the CRD to

(CONTINUED)

FACILITY STATUS:

E

 % POWER:

0	6	6
---	---	---

 OTHER STATUS:

--

 METHOD OF DISCOVERY:

B

 DISCOVERY DESCRIPTION: NA
FORM OF ACTIVITY RELEASED:

Z

 CONTENT OF RELEASE:

Z

 AMOUNT OF ACTIVITY: NA LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES

NUMBER:

0	0	0
---	---	---

 TYPE:

Z

 DESCRIPTION: NA

PERSONNEL INJURIES

NUMBER:

0	0	0
---	---	---

 DESCRIPTION: NA

OFFSITE CONSEQUENCES

DESCRIPTION: NA

LOSS OR DAMAGE TO FACILITY

TYPE:

Z

 DESCRIPTION: NA

PUBLICITY

DESCRIPTION: NA

ADDITIONAL FACTORS

DESCRIPTION: NA

DESCRIPTION: NA

NAME: Michael Parcell PHONE: 265

EVENT DESCRIPTION (continued)

were recoupled according to procedure and recoupling verified by observing no overtravel indication when each CRD was twice withdrawn to position 48.

CAUSE DESCRIPTION (continued)

position 48 can result in uncoupling. Symptoms of this event indicate that CRD's F-5 and H-7 have the same inner filter problem. As a result they are scheduled for an overhaul which will include a detailed disassembly inspection at the next unit 2 refueling outage.

If inner filter unlatching is determined to be the problem, C.E.Co. Quality Control will perform future inner filter installation and testing. For a more detailed discussion of the corrective action mentioned above, refer to a recent letter from M. St. Turbak on May 10, 1977 to D.K. Davis, Acting Chief Operating Reactors, Branch #2, Division of Operating Reactors.

