D, LANHAM



Commonwe Edison One First National Plaza, Chicago, Illinois Address Reply to: Post Office Box 767 Chicago, Illinois 60690

BBS Ltr. #77-176

March 7, 1977

Mr. James G. Keppler, Regional Director Directorate of Regulatory Operations - Region III U. S. Nuclear Regulatory Commitssion 799 Roosevelt Road Glen Ellyn, Illinois 60137

REFERENCES: Docket Number 50-237 Docket Number 50-249

Enclosed pleaseefind an update report to Reportable Occurrence report number 50-237/1976-63. This report is being submitted to your office in accordance with the Dresden Nuclear Power Station Technical Specifications, Section 6.6.B.

B. B. Stephenson

Station Superintendent Dresden Nuclear Power Station

BBS:jo

Enclosure

cc: Director of Inspection & Enforcement Director of Management Information & Program Control File/NRC

UPDATE REPORT-PREVIOUS REPORT DATE: 11-1-76 LEASE PRINT ALL REQUIRED INFORMATION 1 CONTROL BLOCK: LICENSEE LICENSE EVENT LICENSE NUMBER TYPE TYPE 0 0 -1 D R S 2 0 0 0 0 0 0 - 0 04 1 1 11 REPORT REPORT CATEGORY DOCKET NUMBER REPORT DATE TYPE EVENT DATE 01 CON'T 0 5 0 - 0 2 3 7 0 0 3 7 6 1 3 L 58 59 60 61 R EVENT DESCRIPTION During normal operation, radiation protection personnel reported that stack gas 02 8 ā 80 03 sample pump flow appeared to be abnormally low. An operator confirmed that 2/3 7 8 9 80 "A" pump flow was 2.6 SCFM; 2/3 "B" pump flow was 0.0 SCFM (flow greater than 04 80 8 9 05 | 2.9 SCFM is considered normal). Tech Spec section 3.8.A.1 requires continuous 8.9 80 06. chimney monitoring, but states that during plateout tests, when both pumps must 80 (Continued) PRIME SYSTEM CAUSE COMPONENT COMPONENT MANUFACTURER COMPONENT CODE SUPPLIER CODE CODE VIOLATION. Z 9 9 9 Y 07 BB Z Z 10 11 48 CAUSE, DESCRIPTION 08 Normal wear products from the carbon impeller vanes collected in the sample 80 8 9 lines, pump cavity, and filter of the 2/32"A" pump, resulting in reduced pump 09, 8 9 80 The zero flow condition on the 2/3 "B" pump was caused efficiency and flow. 10 80 (Continued) RIQ METHOD OF FACILITY DISCOVERY DESCRIPTION OTHER STATUS STATUS %. ROWER DISCOVERY 9 Е A 0 NA NA 1 1 45 80 10 12 13 44 46 q FORM OF CONTENT ACTIVITY LOCATION, OF RELEASE AMOUNT OF ACTIVITY RELEASED ŇΑ 1 2 Ζ NA 80 10 45 Q PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 13 0 0 NA .01 80 8 9 11 12 PERSONNEL. INJURIES NUMBER DESCRIPTION 14 0 0 0 NA 8.9 11 12 OFFSITE, CONSEQUENCES, NΔ 1.5 80 8'9 LOSS OR DAMAGE TO FACILITY DESCRIPTION NA 80 10 PUBLICITY NA 17 80 ADDITIONAL FACTORS 18 NA 80 8 9 19. 80 8.9 Ext. بر265 Randolph C. Weidner PHONE: NAME:. GPO · AA1 - 667

المراجع المراجع المراجع المراجع المراجع المراجع ومن مراجع من مراجع المراجع المراجع المراجع والمراجع المراجع ال المراجع المراجع المراجع المراجع المراجع المراجع ومن مراجع ومراجع المراجع المراجع المراجع والمراجع والمراجع والم

EVENT DESCRIPTION (Continued)

be out-of-service, the steam jet air ejector monitors may be used to satisfy the plant chimney monitoring requirements if the reactor is operating at a steady-state power level. Although a plateout test was not being performed when both pumps were forced out of service, the reactor had been operating in the steady-state condition for 13 hours, and both steam jet air ejector monitors were operable. During the period from 1725 to 1930 hours, while the 2/3 "A" sample pump and suction filter were being replaced to provide rapid compliance with Tech Spec requirements, the steady-state operation of the unit and the static response of the SJAE monitors ensured that no unacceptable releases occurred. Because the cause of failure could not be readily identified on the 2/3 "B" sample pump, it was decided to first restore the operability of the "A" sample pump by simply replacing the pump and suction filter. Personnel errors resulting in stack gas sample pump problems have occurred occasionally in the past. (50-237/1976-63)

CAUSE DESCRIPTION (Confinued)

by an improper valve lineup.

As stated above, the 2/3 "A" sample pump and suction filter were replaced. The 2/3 "B" sample pump was returned to service at 1125 hours on 10/4/76, after the valving error was discovered.

Reevaluation of the events related to the temporary loss of stack gas sampling capability on October 3, 1976, has resulted in the following conclusions:

- 1. The proximate cause of the event was personnel error (cause code A). This conclusion is based on the fact that, at the time of the event, the operator was unable to establish flow in the standby sample train even though no equipment malfunction existed.
- 2. The root cause of the event was the inadequacy of the system description in the applicable operating procedure -- DOP 1700-4. Had a piping and valve diagram been included in the procedure, the operator would certainly have been able to readily perform the valving required to place the standby sample train in service.

To avoid recurrence, procedure DOP 1700-4, Off-Gas Vent (Stack) Radiation Monitoring System, was revised, and a valve and piping diagram and isometric drawing were added. Additionally, a copy of the new valve and piping diagram has been posted in the sample pump area.

and)