



**Commonwealth Edison**  
 Dresden Nuclear Power Station  
 R.R. #1  
 Morris, Illinois 60450  
 Telephone 815/942-2920

FILE

*W. Zarnham*

50  
237

August 7, 1978

BBS Ltr. #78-1148

James G. Keppler, Regional Director  
 Directorate of Regulatory Operations - Region III  
 U.S. Nuclear Regulatory Commission  
 799 Roosevelt Road  
 Glen Ellyn, IL 60137

DIS. DIV. 115 NRC  
 NUCLEAR SERVICES  
 ANCH

1978 AUG 22 PM 1 21

REG. DIST. DIVISION  
 SERVICES UNIT

Reportable Occurrence Report #78-042/03L-0, Docket #050-237 is hereby submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(b), conditions leading to operation in a degraded mode permitted by a limiting condition for operation or plant shutdown required by a limiting condition for operation.

*B.B. Stephenson*

B.B. Stephenson  
 Station Superintendent  
 Dresden Nuclear Power Station

BBS/deB

Enclosure

cc: Director of Inspection & Enforcement  
 Director of Management Information & Program Control  
 File/NRC

AUG 9 1978

A002  
5/11

LICENSEE EVENT REPORT

CONTROL BLOCK: [1] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
[01] I L D R S 2 [2] 0 0 - 0 0 0 0 0 - 0 0 [3] 4 1 1 1 1 [4] [5]

CON'T [01] REPORT SOURCE [L] [6] 0 5 0 0 0 2 3 7 [7] 0 7 0 8 7 8 [8] 0 8 0 3 7 8 [9]

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES [10]
[02] On 7-8-78 at 2330 hrs during weekly turbine control vlv exercising #3 control vlv
[03] failed to fast close at the 10% vlv position. This event is contrary to Technical
[04] Specifications which require two channels be operable per trip system in case of a
[05] generator load reject. The fast acting solenoids are utilized to close the control
[06] valves. A load reduction began immediately. The reactor scram was automatically
[07] by-passed at less than 45%. This has not happened before at Dresden.

[09] SYSTEM CODE [H A] [11] CAUSE CODE [E] [12] CAUSE SUBCODE [B] [13] COMPONENT CODE [I N S T R U] [14] COMP. SUBCODE [C] [15] VALVE SUBCODE [Z] [16]

[17] LER/RO REPORT NUMBER [7 8] [18] ACTION TAKEN [A] [19] FUTURE ACTION [Z] [20] EFFECT ON PLANT [B] [21] SHUTDOWN METHOD [Z] [22] HOURS [0 0 8 0] [23] ATTACHMENT SUBMITTED [Y] [24] NPD-4 FORM SUB. [N] [25] PRIME COMP. SUPPLIER [X] [26] COMPONENT MANUFACTURER [X 9 9 9]

[10] CAUSE DESCRIPTION AND CORRECTIVE ACTIONS [27]
[11] Investigation of the #3 control vlv revealed that an electrical terminal lug on the
[12] fast acting solenoid had become deteriorated and had finally broken off. The terminal
[13] lug was replaced and the vlv tested satisfactorily. Unit returned to higher power
[14] operation. No further corrective action necessary.
[15] FACILITY STATUS [E] [28] % POWER [0 8 9] [29] OTHER STATUS [NA] [30] METHOD OF DISCOVERY [B] [31] DISCOVERY DESCRIPTION [Turbine Control Vlv Exersing]
[16] ACTIVITY CONTENT [Z] [33] RELEASED OF RELEASE [Z] [34] AMOUNT OF ACTIVITY [NA] [35] LOCATION OF RELEASE [NA]
[17] PERSONNEL EXPOSURES [0 0 0] [37] [Z] [38] DESCRIPTION [NA]
[18] PERSONNEL INJURIES [0 0 0] [40] DESCRIPTION [NA]
[19] LOSS OF OR DAMAGE TO FACILITY [Z] [42] DESCRIPTION [NA]
[20] PUBLICITY [N] [44] DESCRIPTION [NA]

ATTACHMENT TO LICENSEE EVENT REPORT 78-042/03L-0  
COMMONWEALTH EDISON COMPANY (CWE)  
DRESDEN UNIT 2 (ILDRS-2)  
DOCKET # 050-237

During weekly turbine control valve exercising per DOS 5600-2, #3 control valve failed to fast close from 10% valve position. Valve was exercised four times without fast closure operation. Tech Spec 3.1 requires two trip channels operable in case of a generator load reject. The fast acting solenoids are utilized to close the control valves following a generator load reject condition. Since the #3 control valve would not fast close at the 10% position load reduction was begun immediately with the unit at 700 MWe. The reactor scram was by-passed when the reactor was less than 45% power. This event has not occurred previously at Dresden.

Investigation of the #3 control valve revealed that an electrical terminal lug on the fast acting solenoid had become deteriorated and had finally broken off. The terminal lug was replaced and the valve tested satisfactorily. Unit returned to higher power operation. No further corrective action necessary.