

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8504090220 DOC.DATE: 85/04/04 NOTARIZED: NO DOCKET #  
 FACIL:50-244 Robert Emmet Ginna Nuclear Plant, Unit 1, Rochester G. 05000244  
 AUTH.NAME AUTHOR AFFILIATION  
 KOBER,R.W. Rochester Gas & Electric Corp.  
 RECIP.NAME RECIPIENT AFFILIATION  
 ZWOLINSKI,J.A. Operating Reactors Branch 5

SUBJECT: Informs that mods being completed for upgrading in-core thermocouples to meet emergency procedure requirements, per util 831129 commitment. Info re design of mod & number of operable thermocouples required by procedures provided.

DISTRIBUTION CODE: A002D COPIES RECEIVED: LTR L ENCL 0 SIZE: 1  
 TITLE: OR Submittal: Inadequate Core Cooling (Item II.F.2) GL 82-28

NOTES: NRR/DL/SEP 1cy.  
 OL: 09/19/69

05000244

RECIPIENT ID CODE/NAME		COPIES LTTR ENCL		RECIPIENT ID CODE/NAME		COPIES LTTR ENCL	
NRR ORB5 BC MILLER,C		1	1	NRR ORB5 LA		1	1
INTERNAL:	ACRS 17	10	10	ADM/LFMB	1	0	
	NRR SHEA,J 01	1	1	NRR/DHFS/HFEB15	1	1	
	NRR/DHFS/PSRB16	1	1	NRR/DL/ORAB 08	1	1	
	NRR/DL/ORB5	1	1	NRR/DSI DIR 09	1	1	
	NRR/DSI/CPB 10	3	3	NRR/DSI/ICSB 14	1	1	
	NRR/DSI/RSB 13	1	1	<u>REG FILES</u> 04	1	1	
	RGN1 07	1	1				
EXTERNAL:	LPDR 03	1	1	NRC PDR 02	1	1	
	NSIC 06	1	1				
NOTES:		1	1				





ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649-0001



ROGER W. KOBER  
VICE PRESIDENT  
ELECTRIC & STEAM PRODUCTION

TELEPHONE  
AREA CODE 716 546-2700

April 4, 1985

Director of Nuclear Reactor Regulation  
Attention: Mr. John A. Zwolinski, Chief  
Operating Reactors Branch No. 5  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Subject: Inadequate Core Cooling Instrumentation  
R. E. Ginna Nuclear Power Plant  
Docket No. 50-244

Dear Mr. Zwolinski:

In our letter dated November 29, 1983, we committed to upgrade to fully environmentally qualified status the 39 incore thermocouple system by the end of the 1985 refueling outage. Modifications are being completed and although sufficient incore thermocouples have been upgraded to meet all emergency procedure requirements, not all thermocouples have been upgraded. We believe, however, that this satisfies the intent of the NRC request and our commitments.

The design of the modification divided the thermocouples into two trains, with 19 in train A and 20 in train B. Included in the total of 39 thermocouples are three located in the vessel head and 36 at the fuel assembly outlet. Currently, 15 or more thermocouples in both train A and train B are operable with one operable thermocouple in train A and two operable thermocouples in train B located in the head. Of the remaining six thermocouples, three are broken at the vessel head, and three are exhibiting noise.

The number of operable thermocouples exceeds those required in the current and the upgraded emergency operating procedures. The current emergency procedures specify that the value for the five highest reading thermocouples be employed. The upgraded procedures require that the core exit thermocouples be used to determine subcooling without specifying a number of thermocouples to be used. The current set of operable thermocouples permits sufficient flexibility to meet these requirements, even with the loss of one train or should additional thermocouples become inoperable.

Very truly yours,

*Roger W. Kober*  
Roger W. Kober

B504070220	B50404
PDR	ADOCK 05000244
P	PDR

A002  
1/0

