

May 24, 1983

Docket No. 50-244
LS05-83-05-053

LICENSEE: ROCHESTER GAS AND ELECTRIC CORPORATION
FACILITY: R. E. Ginna
SUBJECT: SUMMARY OF MAY 12, 1983 MEETING WITH
ROCHESTER GAS AND ELECTRIC CORPORATION (RG&E)
ON STEAM GENERATOR SLEEVING PROGRAM

On May 12, 1983, members of the NRC staff met with representatives of Rochester Gas and Electric Corporation (RG&E) to discuss the history and status of the steam generator tube sleeving at Ginna. The licensee informed the staff of modifications made to the basic steam generator tube sleeving procedure that was approved on April 1, 1983. The major modifications include the use of sleeves which are entirely within the tube sheet and the pre-tensioning of tubes prior to brazing. The discussions were general and covered tube inspections and criteria for acceptance, sleeving procedures, and sleeving inspection techniques. A meeting to discuss the details of the sleeving inspection results is scheduled for May 20, 1983. The attendance list (Enclosure 1) and a copy of the slides used by RG&E (Enclosure 2) are enclosed.

The meeting began with a review of the eddy current inspection technique and the results of the eddy currenting sections of the "B" steam generator. Historically, damaged tubes were removed from service through plugging. However improvements, such as sleeving techniques have permitted the licensee to keep more tubes in service. Before the current outage which began March, 1983, 21 sleeves were installed in the "B" steam generator.

SEO 1
S
1/1
DSU USE (07)

Eddy current inspections during this current outage identified 78 tubes in the "B" steam generator and 4 in the "A" generator with varying degrees of defects. Of the 78 defects found in the "B" steam generator, 23 were above 40% which would have required either plugging or sleeving.

The Safety Evaluation issued by the staff on April 1, 1983 covered the use of 36 inch sleeves which were explosively welded at the bottom to the tubes within the tubesheet and brazed at the top to the tubes as they extended above the tubesheet. Some of the damaged tubes were near the periphery of the bundle. Space limitations would not permit the

8305260237 830524
PDR ADOCK 05000244
P PDR

SURNAME ▶

DATE ▶

May 24, 1983

use of the standard sleeve. Consequently, a 22 inch sleeve which was explosively welded at both top and bottom was subsequently used on 29 of the tubes. The sleeve installation and eddy current inspection procedures were reviewed with the staff.

During installation of the standard sleeves, the licensee noted that the ultrasonic inspections indicated inadequate braze joints. An investigation concluded that movement of the tubes was restricted at the lowest tube support plate. The tube "lockup" situation restricted thermal growth during brazing. Instead of axial movement the tube would bulge (about 30 mil increase in diameter) at the braze joint. The licensee modified the procedure by heating the tube below the upper joint prior to brazing thus increasing the diameter at that point. When the upper joint was brazed, no additional stresses were introduced and acceptable seals were obtained. The licensee is performing an analysis of the additional stresses introduced to determine if they were significant.

The staff considered the sleeving modifications to be adequate pending formal submittal of the modified procedures and review of the inspection results and stress analysis.

Original signed by/

George F. Dick, Jr., Project Manager
Operating Reactors Branch #5
Division of Licensing

Enclosures:
As stated

DISTRIBUTION

Docket	HConrad
NRC PDR	BDLiaw
Local PDR	CYCheng
ORB Reading	LFrank
NSIC	JRajan
DCrutchfield	SVarga
HSmith	DVassallo
GDick	RCClark
OELD	JStolz
ELJordan	
JMTaylor	
ACRS (10)	
SEPB	

OFFICE	DL ORB#5	DL ORB#5					
SURNAME	GDick	DCrutchfield					
DATE	05/25/83	05/14/83					

cc

Harry H. Voigt, Esquire
LeBoeuf, Lamb, Leiby and MacRae
1333 New Hampshire Avenue, N. W.
Suite 1100
Washington, D. C. 20036

Mr. Michael Slade
12 Trailwood Circle
Rochester, New York 14618

Ezra Bialik
Assistant Attorney General
Environmental Protection Bureau
New York State Department of Law
2 World Trade Center
New York, New York 10047

Resident Inspector
R. E. Ginna Plant
c/o U. S. NRC
1503 Lake Road
Ontario, New York 14519

Director, Bureau of Nuclear
Operations
State of New York Energy Office
Agency Building 2
Empire State Plaza
Albany, New York 12223

Dr. Emmeth A. Luebke
Atomic Safety and Licensing Board
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dr. Richard F. Cole
Atomic Safety and Licensing Board
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dr. Thomas E. Murley,
Regional Administrator
Nuclear Regulatory Commission, Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

U. S. Environmental Protection Agency
Region II Office
ATTN: Regional Radiation Representative
26 Federal Plaza
New York, New York 10007

Herbert Grossman, Esq., Chairman
Atomic Safety and Licensing Board
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Supervisor of the Town
of Ontario
107 Ridge Road West
Ontario, New York 14519

Jay Dunkleberger
New York State Energy Office
Agency Building 2
Empire State Plaza
Albany, New York 12223

Stanley B. Klimberg, Esquire
General Counsel
New York State Energy Office
Agency Building 2
Empire State Plaza
Albany, New York 12223

Mr. John E. Maier
Vice President
Electric and Steam Production
Rochester Gas and Electric Corporation
89 East Avenue
Rochester, New York 14649

ATTENDANCE LIST
MAY 12, 1983 MEETING

<u>Name</u>	<u>Affiliation</u>
George Dick	NRC
H. F. Conrad	NRC
Robert Mecredy	RG&E
J. C. Hutton	RG&E
Albert E. Curtis III	RG&E
B. D. Liaw	NRC/MTEB
C. Y. Cheng	NRC/MTEB
Louis Frank	NRC/MTEB
Jai Rajan	NRC/MEB

Ginna Station
Steam Generator Sleaving
NRC Meeting
May 12, 1983

Agenda

- A. Introduction Bob Mecredy.
- B. Eddy Current Results Al Curtis
- o Spring 1983
 - o summary
- C. Ginna Sleaving Background Al Curtis
- o Fall 1980
 - o Spring 1981
 - o Spring 1983
- D. Tubesheet Sleeves Al Curtis
- o sleeve design
 - o inspectability
- E. Brazed Sleeves Jim Hutton
- o process overview
 - o tube lockup
 - o braze procedure changes
 - o ultrasonic examination
- F. Analysis/Test Program Jim Hutton
- o analyses
 - o tests
- G. Conclusion Bob Mecredy

Ginna Station
 Steam Generator Sleaving
 NRC Meeting
May 12, 1983

B Steam Generator
 Eddy Current Data Review

	not sizeable	0-25%	26-50%	51-75%	76-100%	TOTAL
March 1979	0	0	0	2	0	2
December 1979	0	0	6	5	0	11
April 1980*	18	1	2	7	2	31
November 1980	2	0	0	1	0	3
April 1981	0	5	4	5	0	14
February 1982	1	0	1	6	5	13
October 1982	28	4	5	7	16	59 (31**)
April 1983	38	3	20	7	15	78
	87	13	38	40	38	211

* Crevice flushing implemented

** Number of tubes repaired (plugged)

Ginna Station
Steam Generator Slewing
NRC Meeting
May 12, 1983

B-Steam Generator
EDDY CURRENT DATA REVIEW

- A. Tubes above plugging criteria > 40% 23 tubes
 16 ~~old~~ new
 7 ~~new~~ old
- B. Tubes below plugging criteria < 40% 55 tubes
 35 new
 20 old
- C. Out of 78 tubes - 51 were new defects
 - 27 were there in the fall.
 - of the 27, 24 had changed since
 the fall.


"A" S/G Hot Leg

RG&E Steam Generator Spring 83 IGA

91 89 87 85 83 81 79 77 75 73 71 69 67 65 63 61 59 57 55 53 51 49 47 45 43 41 39 37 35 33 31 29 27 25 23 21 19 17 15 13 11 9 7 5 3 1

COLUMNS

92 90 88 86 84 82 80 78 76 74 72 70 68 66 64 62 60 58 56 54 52 50 48 46 44 42 40 38 36 34 32 30 28 26 24 22 20 18 16 14 12 10 8 6 4 2



44
42
40
38
36
34
32
30
28
26
24
22
20
18
16
14
12
10
8
6
4
2

ROWS

MANWAY

NOZZLE

AEC³
5/2/83


B SIG

RG&E Steam Generator Spring 83 IGA

91 89 87 85 83 81 79 77 75 73 71 69 67 65 63 61 59 57 55 53 51 49 47 45 43 41 39 37 35 33 31 29 27 25 23 21 19 17 15 13 11 9 7 5 3 1

COLUMNS

92 90 88 86 84 82 80 78 76 74 72 70 68 66 64 62 60 58 56 54 52 50 48 46 44 42 40 38 36 34 32 30 28 26 24 22 20 18 16 14 12 10 8 6 4 2



ROWS

MANWAY

NOZZLE →

AEC³
5/2/83

Ginna Station
 Steam Generator Slewing
 NRC Meeting
May 12, 1983

Spring 1983 Summary

<u>Category</u>	<u>Qty</u>	<u>U/T Exam</u>		<u>Pressure Test</u>	
		<u>Tested</u>	<u>Accepted</u>	<u>Tested</u>	<u>Accepted</u>
Fall 1980	5	5	2	3	0*
Spring 1981	16	15	13	3	0*
Spring 1983					
o tubesheet	29(4+25)	N/A	N/A	N/A	N/A
o 36"	19	19	15	4	4
o 36" PTD	22	17	17	5	5
o 28" PTD	9	4	4	5	5
o pulled	1	N/A	N/A	N/A	N/A
o plugged	2	N/A	N/A	N/A	N/A
o repairs	4(3+1)	N/A	N/A	N/A	N/A

Ginna Station
Steam Generator Sleaving
NRC Meeting
May 12, 1983

Analysis/Testing

A. Testing

- o locked tube braze
- o tube material tensile
- o bulged tube tensile
- o cold lockup
- o bulged brazed qualification

B. Analysis

- o main steam line break
- o operating transient loads
- o tube code stress calculations
- o sleeve code stress calculations