

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | F | L | S | L | S | I | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | \_\_\_\_\_ | 3  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

CONT 01 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 3 | 5 | 7 | 0 | 9 | 2 | 1 | 7 | 9 | 3 | 1 | 0 | 0 | 5 | 7 | 19 | 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
02 | During an evaluation of steam generator (S/G) level sensing instrumenta-  
03 | tion, conducted as a part of compliance with NRC I & E Bulletin 79-21,  
04 | it was noted that the design specifications of the S/G had been used  
05 | by the NSSS vendor to establish the instrument span for measuring S/G  
06 | level when the as-built dimensions should have been used. This resulted  
07 | in a non-conservative error of approximately 2% (or 4 inches) in the S/G  
08 | low-level trip set point.

09 | SYSTEM CODE | 1 | A | 11 | CAUSE CODE | B | 12 | CAUSE SUBCODE | A | 13 | COMPONENT CODE | Z | Z | Z | Z | Z | 14 | COMP. SUBCODE | Z | 15 | VALVE SUBCODE | Z | 16 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35  
17 | LER/RO REPORT NUMBER | \_\_\_\_\_ | EVENT YEAR | 7 | 9 | SEQUENTIAL REPORT NO. | 0 | 3 | 0 | OCCURRENCE CODE | 0 | 1 | REPORT TYPE | T | REVISION NO. | 0 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35  
ACTION TAKEN | E | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | ATTACHMENT SUBMITTED | Y | 23 | NRC-4 FORM SUB. | N | 24 | PRIME COMP. SUPPLIER | N | 25 | COMPONENT MANUFACTURER | C | 4 | 9 | 0 | 26 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
10 | Use of design specifications instead of as-built dimensions to establish  
11 | the S/G level sensing instrument span resulted in a 2% non-conservative  
12 | error in the S/G low level trip set point. After confirmation of the  
13 | plant staff's evaluation by the NSSS vendor, the reactor protective system  
14 | S/G low level trip setpoint was raised to 39%.

15 | FACILITY STATUS | E | 23 | % POWER | 1 | 0 | 0 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | A | 31 | DISCOVERY DESCRIPTION | Plant Staff Evaluation | 32 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

16 | ACTIVITY CONTENT RELEASED | Z | 33 | Z | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

17 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | NA | 39 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

18 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

19 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

20 | PUBLICITY ISSUED | N | 44 | DESCRIPTION | NA | 45 | NRC USE ONLY | \_\_\_\_\_ | 68 69 70  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

NAME OF PREPARER M. A. Schoppman PHONE: 552-3802

7910190346



ADDITIONAL EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

During an evaluation of steam generator level sensing instrumentation conducted as part of compliance with NRC I & E Bulletin 79-21, it was noted that the design specifications of the steam generator had been used by the NSSS vendor to establish the instrument span for measuring steam generator level. In actuality, the as-built dimensions should have been employed for this determination.

The FSAR analysis assumes a reactor trip during a loss of feedwater accident to occur when steam generator water level drops 50 inches below the normal water level. As a result of using the design (instead of as-built) steam generator dimensions, the low level trip setpoint of 37% is in error (non-conservative) by approximately 2% (4 inches) in comparison with the FSAR criteria. The FSAR analysis does, however, also assume an instrument error of 10 inches in analyzing the loss of feedwater accident.

Confirmation was received from the NSSS vendor that past operation with the setpoint error did not have an effect on the safety analysis and did not affect the health and safety of the public. This was the first occurrence of this type.

ADDITIONAL CAUSE DESCRIPTION AND CORRECTIVE ACTION

Use of wrong dimensions in establishing the steam generator level sensing instrument span resulted in a 2% error in the steam generator low level trip setpoint.

Immediate corrective action was to instruct the control center operators that, in the event of a low steam generator level condition, the reactor was to be manually tripped upon reaching 39% level. After receipt of NSSS confirmation of the plant staff's evaluation of the proper instrument span, the Reactor Protective System steam generator low level trip setpoint was raised to 39%.