

Note: The enclosure was inadvertently detached prior to mailing. It is attached hereto.

UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555



MAY 6 1995

Docket No. 50-397

Mr. G. C. Sorenson, Manager
Regulatory Programs
Washington Public Power Supply System
P. O. Box 968
3000 George Washington Way
Richland, Washington 99352

Dear Mr. Sorenson:

SUBJECT: GENERIC LETTER 83-28; REQUEST FOR ADDITIONAL INFORMATION

The staff is continuing its review and evaluation of the WNP-2 responses to Generic Letter 83-28 - Generic Implications of the Salem ATWS Event. Based on our review as of this date we have identified the need for additional information for the WNP-2 facility as listed in the enclosure. It is requested that you provide the information identified in the enclosure within 45 days of receipt of this letter.

The reporting and/or recordkeeping requirements of this letter affect fewer than ten respondents; therefore, OMB clearance is not required under P.L. 96-511.

Sincerely,


A. Schwencer, Chief
Licensing Branch No. 2
Division of Licensing

Enclosure:
Request for Additional Information

cc w/enclosure:
see next page

Distribution:

- Docket File
- NRC PDR
- Local PDR
- PRC System
- NSIC
- LB#2 Reading
- EHylton
- JBradfute
- Paton, OELD
- ACRS (16)
- JPartlow
- BGrimes
- EJordan



8505280474 850506
PDR ADOCK 05000397
P PDR
///

Note: The enclosure was inadvertently detached prior to mailing. It is attached hereto.

UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

MAY 6 1985

Docket No. 50-397

Mr. G. C. Sorenson, Manager
Regulatory Programs
Washington Public Power Supply System
P. O. Box 968
3000 George Washington Way
Richland, Washington 99352

Dear Mr. Sorenson:

SUBJECT: GENERIC LETTER 83-28, REQUEST FOR ADDITIONAL INFORMATION

The staff is continuing its review and evaluation of the WNP-2 responses to Generic Letter 83-28 - Generic Implications of the Salem ATWS Event. Based on our review as of this date we have identified the need for additional information for the WNP-2 facility as listed in the enclosure. It is requested that you provide the information identified in the enclosure within 45 days of receipt of this letter.

The reporting and/or recordkeeping requirements of this letter affect fewer than ten respondents; therefore, OMB clearance is not required under P.L. 96-511.

Sincerely,



A. Schwencer, Chief
Licensing Branch No. 2
Division of Licensing

Enclosure:
Request for Additional Information

cc w/enclosure:
see next page

WNP-2

Mr. G. C. Sorensen, Manager
Regulatory Programs
Washington Public Power Supply System
P. O. Box 968
3000 George Washington Way
Richland, Washington 99352

cc: Nicholas Reynolds, Esquire
Bishop, Cook, Liberman, Purcell & Reynolds
1200 Seventeenth Street, N. W.
Washington, D. C. 20036

Mr. G. E. Doupe, Esquire
Washington Public Power Supply System
P. O. Box 968
3000 George Washington Way
Richland, Washington 99532

Nicholas Lewis, Chairman
Energy Facility Site Evaluation Council
Mail Stop PY-11
Olympia, Washington 98504

P. L. Powell, Licensing Manager
Washington Public Power Supply System
P. O. Box 968
Richland, Washington 99352

Mr. W. G. Conn, SR. N/M Group Supervisor
Burns and Roe, Incorporated
601 Williams Boulevard
Richland, Washington 99352

R. B. Glasscock, Director
Licensing and Assurance
Washington Public Power Supply System
P. O. Box 968, MD 650
Richland, Washington 99352

M. J. D. Martin
WNP-2 Plant Manager
Washington Public Power Supply System
P. O. Box 968
Richland, Washington 99352



ENCLOSURE

REQUEST FOR ADDITIONAL INFORMATION
RELATING TO GENERIC LETTER 83-28
WASHINGTON NUCLEAR PROJECT NO. 2
DOCKET NO.: 50-397

1. Positions 3.1.2 and 3.2.2 of GL 83-28 both state that licensees should submit the results of their checks of vendor and engineering recommendations to ensure that any appropriate test guidance is included in the test and maintenance procedures or the Technical Specifications, where required. Your response to these requests, dated November 18, 1983, indicates that no check of vendor and engineering recommendations has been performed. While the practices described in your response contribute to a sound test program, it is not apparent how one can justify excluding control and prompt incorporation of service advice received from vendors. Since your program indicates no such control or prompt incorporation is provided, please perform the checks requested by Positions 3.1.2. and 3.2.2 and submit the results within the time period specified in the cover letter. The subject of your incorporation of vendor information in the future will be addressed by our review of Position 2.2.2.

30989 301