

RESULTS OF THE INSPECTION OF WNP-2 CYCLE I DISCHARGED FUEL

2.03

August 22, 1986

By: D.P. Chan M.C. Humphreys R.J. Talbert W.C. Wolkenhauer

1 d

p

2

.

.

· · · · · · • • • . .. •

· •

a and and a start of the start **`***

.

-

Results of the Examination

The assemblies appeared to have good structural integrity. The upper tie plates were level, rod springs had ample compression space, tie rod nuts were snug, there was not apparent rod bow and all rods were properly seated in the lower tie plate. The spacers were perpendicular to the rods and properly located.

Small scratches attributed to channeling and dechanneling were observed on some peripheral fuel pins and on spacer surfaces. Several locking tab washers were bent. In general, the mechanical integrity of the fuel appears to be good.

On the seven medium enriched bundles, nodular corrosion was observed on some of the spacer grids. The nodules can be characterized as ranging from discrete nodules to relatively complete coverage. On these same bundles, the fuel pins exhibit large areas completely covered with a white-appearing layer. At the extremes of the covered regions, a region covered in varying degrees with white particles can be observed. This spotted region can be found as a transition zone both above and below the completely covered region. Typically, the extreme ends of the fuel pins are free of any apparent deposit.

The apparent thickness of the deposition layer seems to correlate with the specific power being generated by the fuel. The apparent peak deposition on the fuel appears to be approximately one third up the fuel.

A key question is the composition of the observed deposition on the fuel. General Electric has characterized it as crud. They believe that if it were brushed off, some nodular corrosion would be observed. Another reviewer has characterized the deposit itself as nodular corrosion. It appears to Supply System engineers that at least some of the deposition is nodular corrosion rather than crud.

The one assembly of natural enrichment appear to be relatively free of any corrosion or crud.

Summary

The inspected fuel appears to be free of significant mechanical damage. Mechanical phenomena appear to be limited to minor scratches and distortion of the tie rod locking tab washers. The rod locking tab washers were probably distorted during channeling.

Nodular corrosion to a significant degree exists on some of the spacer grids; some nodular corrosion also exists on some of the fuel pins. The specific degree of nodular corrosion on the fuel cannot be further characterized except to say that it is apparent the integrity of the fuel is not presently at risk. •

۳ . . k

•

•

٩,

Introduction

In accordance with the WNP-2 FSAR, Section 4.2.4.3, a visual inspection of discharged fuel assemblies from WNP-2, Cycle 1, was performed.

Selection of Assemblies

Eight assemblies were selected for inspection representing greater than 5 percent of the discharged fuel (see Figure 1 attached). The selected assemblies included seven medium enriched assemblies and one natural assembly. They were selected to be representative of the total discharged fuel batch. Four assemblies, LJT 270, LJT 187, LJT 255, and LJT 216 were located in symmetric locations in the core and, in addition, are the high burnup assemblies discharged at the end of Cycle 1. They are all medium enriched assemblies. Three assemblies, LJT 295, LJT 248, and LJT 218, when combined with LJT 216 mentioned above, constitute a radial line from the high burnup location towards the core center. These three assemblies are also medium enriched. LJT 144 is a natural enriched bundle located on the core periphery along the same radial line defined by LJT 295, LJT 248, etc. Given the excellent core power symmetry that WNP-2 observed during Cycle 1, the selected pattern of assemblies to be inspected represents the spatial and exposure effects of the total discharge batch from Cycle 1.

Inspection Technique

The poolside visual examination was performed by means of an underwater camera system with the results of the fuel inspection being recorded on video tape. In general, two sides of each fuel assembly selected for inspection were viewed. The sides viewed were orientated based on the location indicator on the assembly bale handle. The inspection procedure involved moving the fuel assembly in a vertical direction past the fixed camera. This was accomplished by placing the fuel assembly in the fuel preparation machine and utilizing the fuel preparation machine as an elevator. In a typical inspection, a view was first taken of the upper bale and then one side viewed top to bottom. The camera was then moved to a location 90 degrees to the initial location and a second side viewed bottom to top as the fuel preparation machine was driven down.

Inspection Criteria

Visual inspection of the selected assemblies was performed to determine the extent of the following phenomena:

- Proper rod seating in the lower tie plate.
- Rod bow and spacing.
- Spacer location and perpendicularity.
- Relative rod growth.
- Condition of tie rod hex nuts and other structural components.
- Nodular corrosion and crud formation.
- Rod fretting.

•

4). 5

• • •

.

_		
(60	201220 1211180 630220 121120 121100 261123 020124	-
58	515 784 452 718 806 550 441 751 768 501 675 682 804 540 202	
56 —		
54	533624 398152 821 636 170186 687561 5441526 4438206471671 762627	/ ~
- 52 		
50 ——	Q27135631480 4071598 4971203 521 113 742 26 161 394 3841556 13716262871522 4031542 719 572	08168
48 ——	ERIERI 641 1816 605 705 238 461 285 414 260 413 390 225 759 276 430 30 10 200 743 646 474 44	119 109
46	A 158 530 661 655 746 315 429 310 750 302 422 122 145 386 380 704 305 537 585 499 160 421 508 471	656 775 28
44	0781587 741 1713 6041725 200 496 313483 3551723 2551690 26 1243 409 268 798 300 601 232 823 187 517 120	555149479312
(42-	013 160 711 1769 543 259 478 209 732 2018081 796 1298 257 120 234 425 201 703 031 601 188 580 202 580	464 766 693
40	6681472 6811411 73714792971538 56548 221755 364514 338 356 689 343 500 332 685 541 536 189 310 665	625 583 734 6
38	100 649 483 710 193 510 381 201 201 424 283 529 289 35 8367 349 643 393 600 311 168 802	535 621 457 1
36 —	116:1562 7971406 3791579 2751410 362694 236612 3251761 2641 2687 27127617641232177912924651186 506124	7541593 5471
34	1016 558 5771439723382 578 223721359554293412307 347279195 817 3141456 3271726 210 486 171 489	397800568
32	1131185 559 519 150 156 170 380 377 24 3.28 254 304 373 301 246 334 169 1239 26(319 235 201 130 175 192	658 818 662 8
30—	028 391 301 100 100 100 100 100 100 100 100 10	418654 451
(28	E33441 749435 709kgt 426 326 449 278 475 290 682 344 125 1378 318 527 244 453 256 648 361 597 165 1659	738751 585
26	1413/181 519 551 177 478 2021 22 2028 26 29 803 367 652 371 372 440 247 448 391 676 202 635 346 663 300	788 748 541 9
24	1331532 7761446 546122 767 292 698 33 500 261 509228 365257 2291632 3591686 995 574 2531673 376 150	19691634 591
22	102 468 531 773 594 716 303 476 276 642 259 564 221 444 375 291 445 251 707 357 680 288 637 1348 515 180	1570567811
20	0911404 4201657 481 200 500 500 500 500 230 630 630 630 630 630 650 630 650 650 650 650 650 650 650 650 650 65	528614399
18	600 666 66 66 67 17 02 147 3 100 706 FT 1539 352 590 351 488 37 0317 665 1318 415 1339 549 227 789 206 417 182	545 731 650 K
16 ——	BEITIO LICE ILLE 18 21 18 21 18 21 18 21 18 21 18 12 12 12 12 12 12 12 12 12 12 12 12 12	128459 201
14 ——	141 603 8-2 638 61 115 215 692 232 708 2 21495 196 209 431 20 130 385 695 194 586 516 813 62	1736 2421
12	231450 4301430 4321450 432141 619 233 815 393 166 183 201552 1621396 201485 7821477 7471615	198.12.2
(10	108143717921758534140214821493 392159415941591163 492181 40515715631501714178752314	
- 08 		
06	1231084722569163014911712 (841674 80259250515847531623774401 790132 1848	
04	432 795 729 765 729 765 467 454 679 416 427 697 618 724 780 739 697	
02	Dialicas (car) [13] [033 [102 [29 [01 [13 0]]00] [19] [08 [145 [08]]	
	FIGURE 1 - CORE MAP	JJ JJ JJ 5/ 5

, `

dre i

Legend

= Fuel Bundle Inspected



-a

.

. • , •

n - 1 - 1

. .