

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8711250267 DOC. DATE: 87/11/20 NOTARIZED: NO DOCKET #
 FACIL: 50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397
 AUTH. NAME AUTHOR AFFILIATION
 DAVISON, W. S. Washington Public Power Supply System
 POWERS, C. M. Washington Public Power Supply System
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 87-091-01: on 840823, RHR isolation & reactor low water level trip occurred while placing sys in shutdown cooling mode. Shutdown cooling suction isolated & full insp of sys conducted to determine leakage. W/871120 ltr.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD5 LA	1 1	PD5 PD	1 1
	SAMWORTH, R	1 1		
INTERNAL:	ACRS MICHELSON	1 1	ACRS MOELLER	2 2
	AEOD/DOA	1 1	AEOD/DSP/NAS	1 1
	AEOD/DSP/ROAB	2 2	AEOD/DSP/TPAB	1 1
	ARM/DCTS/DAB	1 1	DEDRO	1 1
	NRR/DEST/ADS	1 0	NRR/DEST/CEB	1 1
	NRR/DEST/ELB	1 1	NRR/DEST/ICSB	1 1
	NRR/DEST/MEB	1 1	NRR/DEST/MTB	1 1
	NRR/DEST/PSB	1 1	NRR/DEST/RSB	1 1
	NRR/DEST/SGB	1 1	NRR/DLPQ/HFB	1 1
	NRR/DLPQ/QAB	1 1	NRR/DOEA/EAB	1 1
	NRR/DREP/RAB	1 1	NRR/DREP/RPB	2 2
	NRR/DRIS/SIB	1 1	NRR/PMAS/ILRB	1 1
	REG FILE 02	1 1	RES DEPY GI	1 1
	RES TELFORD, J	1 1	RES/DE/EIB	1 1
	RGN5 FILE 01	1 1		
EXTERNAL:	EG&G GROH, M	5 5	H ST LOBBY WARD	1 1
	LPDR	1 1	NRC PDR	1 1
	NSIC HARRIS, J	1 1	NSIC MAYS, G	1 1

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Washington Nuclear Plant - Unit 2										DOCKET NUMBER (2) 0 5 0 0 0 3 9 7 1				PAGE (3) 1 OF 0 2		
TITLE (4) RHR Isolation and Reactor Low Water Level Trip																
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)						
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES				DOCKET NUMBER(S)			
0 8	2 3	8 4	8 4	0 9	1 0	1 1	1 2	0 8	7					0 5 0 0 0		
OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)														
POWER LEVEL (10)		20.402(b)				20.405(c)				50.73(a)(2)(iv)				73.71(b)		
0 1 0 1 0		20.405(a)(1)(i)				50.36(c)(1)				50.73(a)(2)(v)				73.71(c)		
		20.405(a)(1)(ii)				50.36(c)(2)				50.73(a)(2)(vii)				OTHER (Specify in Abstract below and in Text, NRC Form 366A)		
		20.405(a)(1)(iii)				50.73(a)(2)(i)				50.73(a)(2)(viii)(A)						
		20.405(a)(1)(iv)				50.73(a)(2)(ii)				50.73(a)(2)(viii)(B)						
		20.405(a)(1)(v)				50.73(a)(2)(iii)				50.73(a)(2)(x)						
LICENSEE CONTACT FOR THIS LER (12)																
NAME W.S. Davison, Compliance Engineer										TELEPHONE NUMBER AREA CODE 5 0 9 3 7 7 1 - 2 5 0 1						
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13) Ext. 2726																
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS						
B	B O			N												
SUPPLEMENTAL REPORT EXPECTED (14)												EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR
YES (If yes, complete EXPECTED SUBMISSION DATE)												NO				

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

With the reactor shutdown, an RHR isolation and a reactor low water level trip (+13") occurred while placing the RHR system in the shutdown cooling mode.

8711250267 871120
PDR ADOCK 05000397
S PDR

IE22 1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/88

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Washington Nuclear Plant - Unit 2	0 5 0 0 0 3 9 7	8 4	0 9 1	0 1	0 2	OF	0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Plant Conditions

- a) Power Level - 0%
b) Plant Mode - 3

Event

With the reactor shutdown and at 60 psig, RHR Loop B was being warmed up for shutdown cooling (SDC) operation when RHR-V-8 shut automatically. The cause of this isolation was apparently high SDC suction flow. However no annunciation was provided for by design, and the isolation went unnoticed for approximately 15 minutes. During this time, the RHR Loop B partially drained (flowpath was to radwaste through the warmup line via RHR-V-40). When RHR-V-8 was reopened, a low reactor water level RPS actuation occurred.

When RHR-V-8 was reopened, reactor water began to fill the partially drained RHR loop. RHR-V-8 was immediately shut by the control room operator when reactor water level started to decrease at a rapid rate. The lowest reactor water level recorded was +10" during this event.

Immediate Corrective Action

After the reactor water level dropped to +10" and the shutdown cooling suction was isolated, a full inspection of the system was conducted to determine system leakage; none was found. After determining the cause of the level decrease the reactor level was increased to approximately +50" and the shutdown cooling flowpath was reestablished.

Further Evaluation and Corrective Action

Subsequent hardware modifications have resulted in improving the reliability of the low pressure alarm instrumentation associated with the partial draining of RHR following an isolation. The annunciator response procedures have been revised to include an inadvertant isolation as a potential cause for the low pressure condition. No further action is considered necessary.

Safety Significance

This event did not compromise the health and safety of the public. All systems functioned as per design and an analysis of a similar postulated event (which bounds the event described here) indicates that level would not have decreased below 417". This is approximately 40" above low reactor water level 1(-129)". This analysis was originated as a result of our Operating Experience Review Program.

WASHINGTON PUBLIC POWER SUPPLY SYSTEM

P.O. Box 968 • 3000 George Washington Way • Richland, Washington 99352

Docket No. 50-397

November 20, 1987


Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Subject: NUCLEAR PLANT NO. 2
LICENSEE EVENT REPORT NO. 84-091-01

Dear Sir:

Transmitted herewith is Licensee Event Report No. 84-091-01 for the WNP-2 Plant. This report is submitted in response to the report requirements of 10CFR50.73 and discusses the items of reportability, corrective action taken, and action taken to preclude recurrence.

Very truly yours,



C.M. Powers (H/D 927M)
WNP-2 Plant Manager

CMP:db

Enclosure:
Licensee Event Report No. 84-091-01

cc: Mr. John B. Martin, NRC - Region V
Mr. C. J. Bosted, NRC Site (M/D 901A)
INPO Records Center - Atlanta, GA
Ms. Dottie Sherman, ANI
Mr. D. L. Williams, BPA (M/D 399)

LE22
11

